

TELEPHONE 3811

1217 13TH STREET

BRANDON, MAN., December 19 1941

Rev. Chapin,  
Indian Residential School,  
Brandon, Man.

IN ACCOUNT WITH

**H. D. SPRATLING**  
CONTRACTOR AND BUILDER  
CARPENTER, CEMENT WORK, ETC.

GLASS  
CABINETS  
SPECIAL MILLWORK

Building up concrete wall, splicing  
joist, repairing floor;  
Building chimney top

\$200.00

Excavating Coal Bin,  
Placing 2 yds. Concrete

27.50

\$227.50

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY




Indian Residential School

REV. R. T. CHAPIN, B.A.  
PRINCIPAL

PHONE 2838

Brandon, Man., December 23, 1941.

*Handwritten signature/initials*



The Secretary,  
Dept. of Mines & Resources,  
Indian Affairs Branch,  
Ottawa, Ont.

Dear Sir:

Regarding the account and vouchers enclosed - we received permission for the \$200.00, \$175.00 for repairs on barn and \$25.00 chimney on Principal's residence, through Inspector Hamilton's letter of September 8th.

Regarding the \$27.50 - we had no permission for this expenditure but just at the time the contractor came out to do the other work, the Farm Manager was clearing out the coal bin of his house for the winter's supply of coal and the back wall, which was a wooden construction, caved in. This was endangering the outer foundation of the building, so upon consultation with the contractor we put in a cement wall at the back of the coal bin, which also acted as an abutment to hold the earth from giving way underneath the foundation of the building at that point. We hope it will be in line for you to include this amount in the total bill.

Yours very truly,

*R.T. Chapin*

RTC/TS

*Approved by Sir.  
227.50  
10-691*

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

*VERY POOR COPY*

Shop Phone 3270  
Res. Phones 3819-2601



# McDOWELL & DOKE

## TINSMITHS



AUTO AND TRACTOR RADIATORS REPAIRED. RECORDED AND CLEANED  
IRON FIREMAN STOKERS. WILLIAMS OIL-O-MATIC OIL BURNERS

115 9th St. Brandon, Man.,

Dec 31 1941

Sold to

Industrial School  
Brandon Man

TERMS CASH—8% charged on overdue accounts.

DATE	ARTICLES	FOLIO	CREDIT AMOUNT	DEBIT AMOUNT	TOTAL
Oct-18	work & material repairing roof.			50.00	\$50.00

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY



Indian Residential School

133-0-5

REV. R. T. CHAPIN, B.A.  
PRINCIPAL

PHONE 2838

Brandon, Man., January 3, 1942.

*Handwritten initials and scribbles*

The Secretary,  
Dept. of Mines & Resources,  
Indian Affairs Branch,  
Ottawa, Ont.

Dear Sir:

We herewith forward voucher number 30 in  
favor of McDowell & Deke, which work was  
done under authority of letter from  
Inspector Hamilton dated September 8th.

Yours truly,

*R. T. Chapin*

RTC/TS

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

Indian Residential School

REV. R. T. CHAPIN, B.A.  
PRINCIPAL

133-0-5

PHONE 2838

Brandon, Man., January 3, 1942.

*Scholar*



The Secretary,  
Dept. of Mines & Resources,  
Indian Affairs Branch,  
Ottawa, Ont.

Dear Sir:

May we have permission to purchase the following articles from Yates & Neale:

- 1 - 2 1/2 inch gate valve
- 6 - steam radiator valves 3/4 inch
- 1 - steam radiator valve 1/2 inch
- 6 - basin taps 1/2 inch (hot)
- 2 - lengths of black pipe 2 inch
- 2 - lengths of black pipe 1 1/4 inch
- 2 - lengths of black pipe 3/4 inch
- 2 - unions 2 inch
- 2 - unions 1 1/4 inch
- 6 - unions 3/4 inch
- 1 set of pipe threading dies 2 inch
- 1 pipe cutter 2 inch.

These items are needed immediately for winter use. The valve on one of the furnaces has played out and needs replacing. Some of the valves on the radiators cannot be turned off or on and need replacing so that the radiators

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

Page 2.

may be used. Some of the boys' and girls' washroom sinks' taps are leaking continuously and beyond repair. On the return system from the radiators back to the steam boilers in five places the pipes have rusted through and are leaking badly. We attempted to put plugs in but the pipes are so badly rusted the plugs will not hold. We just tied them up temporarily as best we could. If we have the above fittings and set of two inch pipe dies (we have the smaller sizes) we can do this repair work ourselves.

Hoping this will receive your favorable consideration.

Yours truly,

*R.T. Chapin*

RTC/TS

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

Ottawa,  
January 12, 1942.

END.

Dear Sir:

I am in receipt of a request from the Principal of the Brandon Residential School for the under-mentioned supplies which are required to repair the heating system at the school:

- 1 - 2½" gate valve
- 6 - steam radiator valves ¾"
- 1 - steam radiator valve ½"
- 6 - basin taps ½" (hot)
- 2 - lengths black pipe 2"
- 2 - " " " 1½"
- 2 - " " " ¾"
- 2 - unions 2"
- 2 - unions 1½"
- 6 - unions ¾"
- 1 - set pipe threading dies 2"
- 1 - pipe cutter 2"

The Principal states that if he receives the above the work will be done by the school staff without cost to the Department. I should appreciate it if you would arrange for the immediate purchase and delivery of the above articles from a firm on the approved list.

Yours truly,

Mr. A.G. Hamilton,  
Inspector of Indian Agencies,  
Winnipeg, Man.

R.A. Hoey,  
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

133-0-5

DEPARTMENT OF MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH

Letter No. 209-11 A.U.

Office of the Inspector Indian Agency,

Winnipeg, Man., January 30, 1942.

Sir,

I enclose herewith Vouchers Nos. 331,

amounting to \$ 74.46 in favour

of The J. H. Ashdown Hardware Co. Limited, WINNIPEG, Manitoba,

for supplies to repair heating system at Brandon Residential School.

This expenditure was authorized by Departmental

Letter No. 133-0-5 dated January 12, 1942.



Your obedient servant,

A. G. Hamilton, ~~Inspector of Indian Agencies~~  
Inspector of Indian Agencies  
for Manitoba.

The Secretary,  
Indian Affairs Branch,  
Department of Mines and Resources,  
Ottawa

Form No. I.A. 518  
Requ. 7658

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

Ottawa,  
February 3, 1942.

Memorandum:

ACTING DEPARTMENTAL PURCHASING AGENT

I attach account amounting to \$74.46 covering purchase of supplies required to repair the heating system at the Brandon Indian Residential School. These were emergency repairs and authority was given for local purchase. The labour was supplied free by the school staff. It would be appreciated if you would issue purchase order so that the account may be paid. The coding is as follows: 576-76-10-691.



R.A. Hoey,  
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

Ottawa,  
February 3, 1942.

Memorandum:

ACTING DEPARTMENTAL PURCHASING AGENT

I attach account amounting to \$74.46 covering purchase of supplies required to repair the heating system at the Brandon Indian Residential School. These were emergency repairs and authority was given for local purchase. The labour was supplied free by the school staff. It would be appreciated if you would issue purchase order so that the account may be paid. The coding is as follows: 576-76-10-691.

R.A. Hoey,  
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

DEPARTMENT OF MINES AND RESOURCES

Order N<sup>o</sup> 1110

RECEIPT FORM

This order number to appear on all packages and invoices

15-2 man

File No. ....

J. H. Ashdown Hardware Co., Ltd.,

Ottawa, February 4, 1942.

19

Winnipeg, Man.

Supplies mentioned hereunder have been received and found satisfactory with exception of those listed under "Remarks".

Invoice received -

QUANTITY	DESCRIPTION	UNIT	TOTAL
	Emergency purchase - Brandon Indian Residential School		
	Steam fitting supplies to repair the heating system at the Brandon Indian Residential School		74.40
	As per invoice of Jan. 27th, 1942. " " voucher No. 331		
	Prices F.O.B.	as per your	of

Shipping Instructions

already delivered.

Vote

Primary

Date to be delivered:

Already delivered.

Encumbrance No.

1412

Freight or Express charges paid

Remarks: (Report shortages, if any)

Branch

Date

TO BE RETURNED TO HEAD OF BRANCH

Signature of Receiving Officer

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY POOR COPY



Interest at 7 per cent charged on all Overdue Accounts  
 No Claim for Shortage will be allowed unless made  
 within 5 Days after receipt of Goods.

GOODS TRANSIT AT RISK OF  
 PURCHASER



THE

RETURNED GOODS

No Goods may be returned without our permission.  
 Goods returned by permission that have been furnished  
 correctly on customer's order may be credited Less 10%.  
 ALL GOODS F.O.B. WAREHOUSE

# J. H. ASHDOWN HARDWARE CO., LIMITED

SOLD TO

DOMINION GOVT.,  
 DEPT OF INDIAN AFFAIRS,  
 538 DOMINION PUBLIC BLDG.,  
 WINNIPEG, MAN.

Order No.

Invoice No.

Terms

Shipped

3923-L 48092  
 Date

JAN 27 42/MC

KINDLY GIVE DATE AND INVOICE NO.  
 IF WRITING ABOUT GOODS HEREON.

WINNIPEG, CANADA

QUANTITY	DESCRIPTION	PRICE	GROSS AMT. LIST	2% GOODS	NET GOODS
	<b>209-11-AU</b>				
2	LENGTHS BLACK PIPE 1/2" 42'-0"	8 55		3 55	
2	" " " 1 1/2" 41'-8"	16 50		6 87	
2	" " " 2" 42'-0"	26 64		11 19	
				<u>21 65</u>	
1	ONLY GATE VALVE FITTING #131-2 1/2"	10 15		10 15	
6	ONLY STEAM RAD VALVES 1213 1/2"	1 55		9 30	
1	ONLY " " " " 1/2"	1 35		1 35	
6	ONLY BASIN TAPS #804-1/2" HOT	1 45		8 70	
2	ONLY UNIONS #26 BLACK 2"	60		1 20	
6	ONLY " " " " 1/2"	22		1 32	
2	ONLY " " " " 1 1/2"	37		74	
1	ONLY SET TOLEDO PIPE STOCKS & DIES TOLEDO #1	14 00		14 00	
1	ONLY SET TRIMO PIPE CUTTERS #2	6 05		6 05	
				<u>74 46</u>	
	<b>PRICIPAL INDIAN RESID SCHOOL BRANDON, MAN.</b>				

150M-9-41

CONTINUOUS INTERFOLD - MFG. BY WESTERN SALES BOOK CO. LTD. WINNIPEG & VANCOUVER

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)


PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
 POOR  
 COPY

Girls Dormitory



3rd Floor Hallway  
Indian Residential School  
Brandon, Man


Scale - 1 inch = 8 ft.

Boys Dormitory

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES ARCHIVES PUBLIQUES  
CANADA

VERY  
POOR  
COPY



10'

20'  
(2'3" deep)

Scale - 1 inch = 2ft.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES ARCHIVES PUBLIQUES  
CANADA

VERY  
POOR  
COPY

Indian Residential School


133-0-5

REV. R. T. CHAPIN, B.A.  
PRINCIPAL

PHONE 2838

Brandon, Man., February 9, 1942.

*[Handwritten signature]*



The Secretary,  
Dept. of Mines & Resources,  
Indian Affairs Branch,  
Ottawa, Ont.

Dear Sir:

We are handicapped to a considerable extent in our School work by the lack of facilities for storing clothing, dry goods, and children's overcoats. It would help in the orderliness of the work to have further cupboard room. I am enclosing a drawing of the third floor hall, and of a cupboard I would like to build in this hall as indicated. In this we could keep the girls' better coats and skirts that they wear in the winter, and by having the cupboard go to the ceiling, have shelf room for considerable other storage. I made out a bill of material, and find it would cost me \$49.70 for material at the local lumber yard. May we have authority to purchase this material? We will do the work ourselves, which in itself will be good training for some of the boys. Trusting this will meet with your approval.

Yours truly,

*[Handwritten signature: R.T. Chapin]*

*[Handwritten notes: 500 p.w., 607, 29/2/42]*

RTC/TS

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY POOR COPY

Ottawa,  
February 13, 1942.

Reverend Sir:

I am in receipt of your letter of the 9th instant requesting authority to expend \$49.70 for material to erect new cupboards at the Brandon School.

In the current year's appropriation an amount of \$500.00 was provided for repairs, improvements and purchase of new equipment at this school. We have already authorized expenditures exceeding that amount and under these circumstances favourable consideration cannot be given to the request contained in your letter of the 9th instant. You might renew your request after the first of April.

Yours truly,

R.A. Hoey,  
Supt. of Welfare & Training.

Rev. R.T. Chapin,  
Principal,  
Indian Residential School,  
Brandon, Man.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

# Indian Residential School

REV. R. T. CHAPIN, B.A.  
PRINCIPAL

133-0-5

PHONE 2838

Brandon, Man., April 22, 1942.



The Secretary,  
Dept. of Mines & Resources,  
Indian Affairs Branch,  
Ottawa, Ont.

Dear Sir:

In furtherance of your letter of February 13th, requesting authority to expend \$49.70 for materials to erect new cupboard, as per plans submitted to you, I am now, in the new fiscal year, asking for this authority. Trusting this will meet with your favorable consideration.

Yours truly,

*R. T. Chapin*

RTC/TS

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

Ottawa,  
April 28, 1942.

EX D  
A

Reverend Sir:

With reference to your letter of the 22nd instant, the Department approves an expenditure of \$49.70 to purchase material required for a new supboard at the Brandon Indian Residential School. It is noted that the work will be done by the school management without cost to the Department.

Yours truly,

R.A. Hoey,  
Supt. of Welfare & Training.

Rev. R.T. Chapin,  
Principal,  
Indian Residential School,  
Brandon, Man.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

Indian Residential School

REV. R. T. CHAPIN, B.A.  
PRINCIPAL

133-0-5

PHONE 2838

Brandon, Man., May 4, 1942.

*Supplies*



The Secretary,  
Dept. of Mines & Resources,  
Indian Affairs Branch,  
Ottawa, Ont.

Dear Sir:

The Boiler Inspector ordered the smoke pipes on our furnaces renewed. We were able to patch them to his satisfaction for the winter, but they must be renewed before another season. I had McDowell & Doke, Brandon, looking over the work, and they gave us an estimate of between \$95.00 and 100.00, to replace the above ~~pipes~~. They state they have the material on hand at present to do the work, and urge that we have it done immediately as they are having such extreme difficulty in getting further material. May we have authority to have this work done and have it done immediately.

Yours very truly,

*R. T. Chapin*

RTC/TS

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

PHONE 3333

BRANDON, MAN. April 1942.

MR. Indian Residential School,

# WADE & SONS LIMITED

## BUILDERS' SUPPLIES AND MILLWORK

OFFICE AND YARDS  
117 FOURTEENTH ST.

TERMS

EIGHT PER CENT. CHARGED ON OVERDUE ACCOUNTS

DATE	No. Pcs.	ARTICLES	FEET	PRICE	DEBIT AMOUNT	CREDIT AMOUNT	TOTAL
April 1	18	L.ft. 1 x 12 #1 Sp.	18		1.89		
	54	" " 1 x 12 #3 Bds.	54		2.86		
	6	- 2 x 4 - 10 Pine	40		5.80		
	6	- " - 12 Spruce	48		2.30		
	4	- 1 x 4 - 10 #1 Sp.	13				
	6	- 1 x 4 - 12 "	24				
		126 Lin. ft. 1 x 4 Sp.	42	79	6.72		19.57
	30	- 1 x 6 - 16 Sp. Flg.	240				
	15	- " - 12 " "	90	330	15.84		
	1	Fir Panel 1/4 x 4 x 6	24				
	1	" " 1/4 x 4 x 4	16	40	2.56		
	72	- 1 x 4 - 5 Cedar V. Joint	120				
	72	- " - 4 " "	96	216	13.18		
	9	- " - 10 Fir V. Jt.	30		2.04		33.62
	10	- 1 x 3 - 10 #1 Sp.	25				
	5	- " - 12 "	15				
	2	- 1 x 2 - 10 "	3				
	2	- 1 x 2 - 12 "	4	47			4.47
							\$57.66
							8.65
							49.01
		Less 15%					

Accounts due when rendered unless otherwise arranged

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY



133-0-5

# Indian Residential School

REV. R. T. CHAPIN, B.A.  
PRINCIPAL

PHONE 2838

Brandon, Man., May 5, 1942.

*Scholars*



The Secretary,  
Dept. of Mines & Resources,  
Indian Affairs Branch,  
Ottawa, Ont.

Dear Sir:

I am enclosing voucher number 8 in favor of Wade & Sons Limited, as authorized in your letter of April 28th.

Yours truly,

*R.T. Chapin*

RTC/TS

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

Ottawa,  
May 8, 1942.

Reverend Sir:

With reference to your letter of the 4th instant, the Department approves an expenditure not exceeding \$100.00 in replacing the pipes on the furnaces at the Brandon Indian Residential School.

Yours truly,

R.A. Hoey,  
Supt. of Welfare & Training.

Rev. R.T. Chapin,  
Principal,  
Indian Residential School,  
Brandon, Man.


Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY



**SYMBOLS**

- POLE, M.P.C.** 40 (size) / 2 (number)
- POLE, JOINT USE M.T.S.** Poles numbered from central point. North and east: odd, south and west: even
- CROSSARMS** double arms / single arm
- PRIMARY WIRES** single phase / 2 phase / 3 phase 3 wire / 3 phase 4 wire grounded neutral / 1 phase 2 wire grounded neutral
- SECONDARY WIRES** 1 wire / 2 wires / 3 wires / 4 wires / 3 phase / 3 phase & neutral
- WIRE SIZE and TYPE** shown on symbols for primary and secondary wires #2 A.C.S.R. / #6  
Common sizes: #8, 6, 4, 2 (D.B.W. Understood); #4 & #2 A.C.S.R.; #4 C.C.S.R.; #8 A.C.W.C.; #3/2 C.W.
- ANCHORS:** EXPANSION EXPANSION / SCREW SCREW / SLUG SLUG / SIDEWALK STRUT SIDEWALK STRUT / PUSH BRACE PUSH BRACE / HEAD OF SPAN GUY HEAD OF SPAN GUY
- GROUND** GROUND / **PRIMARY DEAD-END** PRIMARY DEAD-END / **SECONDARY CUT** SECONDARY CUT / **FUSED SECONDARY CUT** FUSED SECONDARY CUT
- TRANSFORMER** WYE WYE / DELTA DELTA / SIZE & PHASING SIZE & PHASING / LIGHTNING ARRESTER LIGHTNING ARRESTER
- STREET LIGHT** STREET LIGHT / **STREET LIGHT CLOCK** STREET LIGHT CLOCK / **RELAY** RELAY / **METERING ON POLE** METERING ON POLE
- SERVICES** not served  not served / 2 wire  2 wire / 3 wire  3 wire / 3 phase  3 phase  
**Type of Load** hot plate  hot plate / refrigerator  refrigerator / range  range / motor  motor / 3 H.P.  3 H.P. / water heater  water heater

Scale.....

Drawn by P.S. & T.L.W.  
 Traced by P.S.  
 Checked by T.L.W.  
 Approved by J.P.S.

**MANITOBA POWER COMMISSION  
 DISTRIBUTION SYMBOLS**



Date Feb. 17, 1942

FORM 84-200-6-28

CD401

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES ARCHIVES PUBLIQUES  
 CANADA  
 VERY POOR COPY



NOTE: Pole replacements and other changes in red.

Plan showing required changes  
at Indian Residential School

Brandon

June 5/42  
P.S.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY

**MANITOBA POWER COMMISSION**

DATE June 5 1942

ESTIMATED COST OF making alterations & repairs to distribution system in grounds of Indian Residential School

Location Brandon

Estimated by P.S.

Checked by A.M.

Approved by \_\_\_\_\_

CREDIT			CHARGE						
Quantity	Unit Price	Total Price	Quantity	Material	Cat. No.	Services .01	Meter .02	Unit Price	Total Price
			4	Poles 30 ft.				9 40	37 60
			2	" 35 ft.				14 25	28 50
5	5 00	25 00	4	" 25 ft.					
			4	Crossarms 4 Pin				80	3 20
			8	Crossarm Braces				26	2 03
			16	Pins Wood				05	80
				" Steel					
				" " Pole Top					
			16	Insulators	505			17	2 72
				Cooke Dead End K.V.					
				Secondary Rack Pt.					
				" " "					
				" Spool Fitting					
				" Cooke Dead End					
				Pole Top Extension Steel					
				Transf's KVA Volts					
				" " "					
				" Mounting Plates					
				" Device Arms					
				Drop Out Fuses					
				Lightning Arrestors					
				Ground Wire No. DBWP Strd.					
				" Rods					
				" Mould					
				" " Staples					
			2	Anchors screw type				2 25	4 50
			2	Anchor Shields				2 25	4 50
			4	Pole Plates				14	56
			8	Guy Clamps				32	2 56
			16 lbs.	" Wire, 9/32"				13	2 08
			2	" Strain Insulators	504			23	46
				Street Lt. Fixture					
				" " Lamps W					
				" " " W					
				" " Cable W No.					
			10	Lag Screws				05	50
			10	Carriage Bolts				05	50
				Machine Bolts 5/8" x					
				" " 3/4" x					
			5	" " 3/4" x 18"				24	1 20
			8	D.A. " 3/4" x 18"				30	2 40
			36	Washers 2 1/4" x 2 1/4"				04	1 44
				Copperweld Wire No.					
				Copper Tie Wire No. 8					
				" Connectors KS20					
				A.C.S.R. No.					
				Aluminum Tie Wire					
				" Tape					
				" Connector, 1 Bolt					
				Al/Copper " 1 Bolt					
				Sleeves					
				Solder Wire					
				" Paste					
				Friction Tape					
			10 lbs.	Wire No. 6 DBWP Copper				29	2 90
				" No. " "					
				Pulley Knobs					
				Meter Sockets					
				Meter-A. V. W.					
Total Material Credit		25 00	Total Material Cost						98 50
Contingency Labor			Labor .01					Cap. Labor	60 00
Expense			Sub-Total					" Expense	10 00
Comp.								" Comp.	3 00
Contingency Total								Cap. Miscellaneous	3 43
								Cap. Overhead	4 37
			TOTAL COST					2 % of 171.50	3 43
			# 179.30					2 1/2 % of 174.93	4 37
								Cap. Sub-Total	179 30

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES ARCHIVES PUBLIQUES  
 CANADA  
 VERY POOR COPY



MANITOBA POWER COMMISSION  
235 TENTH STREET  
BRANDON, MANITOBA

June 6th, 1942.

Rev. R. T. Chapin,  
Indian Residential School,  
Brandon, Man.

Dear Sir:

In accordance with our previous conversation, we have prepared a sketch and estimate of the work which should be done on the electrical distribution system of your School. We are enclosing herewith, also, a sheet of symbols which should enable you to interpret the sketch.

The work to be done, as we agreed, is listed as follows:

- (1) Pole 2 to be removed and replaced by a new 35 ft. pole about 50 ft. north of present location to skirt pre-posed Girls' Playground.
- (2) <sup>Pole 3</sup> Same as Item (1)
- (3) Guy and anchor removed and attached to opposite side of Pole 4.
- (4) Pole 6 moved 10 ft. north, approximately, to straighten line and clear evergreen tree.
- (5) Poles 7, 8, and 9 to be replaced by new 30 ft. poles in view of deterioration of present poles.

In addition to above, we have noted one or two other poles to be replaced near the barns; some tree trimming and wire tightening to be done; and a few other improvements to be made. The total cost of all this work is \$179.30.

We suggest that you communicate with your department and recommend that this work be done in the interests of safety.

Yours very truly,

MANITOBA POWER COMMISSION

P. Shane

Electrical Engineer

PS/MAM

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY  
POOR  
COPY