




TRANSMITTER
Used on Metal Cylinder
Outside Diameter.....
Gudgeon Diameter.....




GUDGEON FOR TRANSMITTER
Used on Metal Cylinder
Outside Diameter.....
Diameter Shaft.....
Length of Shaft.....
No. Bolt Holes.....




SPIDER
Used on Wood Cylinder
Outside Diameter.....
Diameter Shaft.....
Length of Shaft.....
Keyway.....




SHAFT
Length..... Diameter..... Size of Keyway.....




GEAR
No. Teeth.....
Face.....
Bore.....
Diameter.....
Size of Keyway.....



PULLEY
Face.....
Diameter.....
Bore.....
Size of Keyway.....




SPRING
Length.....
Outside Diameter.....
Number of Turns.....
Diameter of Wire.....



PIN
Length.....
Diameter.....
Cotter Pin Holes (Size) }



METHOD OF DIMENSIONING
Keyway.....



ROLL
Length of Large Portion.....
Length of Gudgeon.....
Diameter of Large Portion.....
Diameter of Gudgeon.....
Size of Keyway (if any).....

Note—Fill in spaces and also dimensions on sketches.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

OFFICE OF THE
GENERAL SUPERINTENDENT
OF INDIAN AGENCIES



CANADA
DEPARTMENT
OF
MINES AND RESOURCES

INDIAN AFFAIRS
BRANCH

108-1-5
File #304-11 A.U.

Regina, May 4th, 1943.



Indian Affairs Branch, Department of Mines & Resources, OTTAWA.

8200 for Reg
I have a letter from Mr. Kerley, the Indian Agent at Crooked Lake with respect to the washing machine at the Round Lake Residential School.

The machine now in use has a wooden cylinder and this is completely rotten in places, beyond repair. The main drive gear has ten cogs missing and the eccentric in connection with the drive pulley is badly worn.

From the above it looks as if a new machine is required but when I visited the Agency I suggested that perhaps a new cylinder could be installed. The machine now in use is 40" x 64" and its Serial No. 1215¹/₂ M 7241.

I am attaching Bulletin No. 7-B from The American Globe Washer Company and would ask that action be taken to accommodate the school either by replacement or securing the necessary repairs for the machine now in use.

John Rarchman

Enc.

for M. Christianson,
General Superintendent of Indian Agencies.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Ottawa,
May 10, 1943.

Dear Sir:

I have a requisition for repairs to the 40" x 64" washing machine, serial number 1215½ M 7241 at the Round Lake Indian Residential School, Whitewood, Sask. They report as follows:

"The machine now in use has a wooden cylinder and this is completely rotten in places, beyond repair. The main drive gear has ten cogs missing and the eccentric in connection with the drive pulley is badly worn."

Would you please let me know at your earliest convenience the approximate cost of repairing this machine and if the repair parts are available. Would you also give me the price of a new machine, stating whether or not it would be available.

Yours truly,

R.A. Hoey,
Supt. of Welfare & Training.

Mr. E.A. Guillaume,
c/o The Canadian Laundry Machinery Co. Ltd.,
Toronto 3, Ont.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)


PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Globe Washer — 30, 36, 40-Inch Diameters

Single End Drive
and Elevated Header

Belted Motor Drive

| |
|-----------------|
| Washer |
| Laundry—Wood |
| Style |
| Globe 30-inch |
| File AB 642-300 |
| Almco 11-38 |



30x48" GLOBE WASHER
ELEVATED HEADER
SINGLE END DRIVE

Machine shall be constructed with such characteristics and shall be equipped with such accessories as specified in our letter of proposal, to which this specification is attached, and as described below.

CYLINDER — Shall have heads, staves, and ribs of selected, long leaf yellow pine.

Staves and lifting ribs shall be rabbeted at heads. Staves shall be secured to the heads by wooden dowels.

Heads shall be gained to receive the three lifting ribs. The above shall be cut from stock as follows:

| | Diameter of Cylinder | | |
|------------------------|----------------------|--------|--------|
| | 30 | 36 | 40 |
| Heads | 2 | 3 | 3 |
| Staves | 1½ | 1½ | 1½ |
| Lifting Ribs | 3 by 5 | 3 by 7 | 3 by 7 |
| Door Closing Ribs..... | 3 by 3¼ | 3 by 4 | 3 by 4 |

Lifting ribs shall be secured to each cylinder head by a galvanized bolt through cylinder hoop, rib, and extending into recess in the head.

To assure tight fitting of the door, the door-closing rib at bottom of door opening shall be fitted with a stainless-steel angle; door-closing rib at top of door opening shall be fitted with a stainless-steel channel.

Door hinges shall be wide, well ribbed, made of brass, and shall rest on cylinder the full length of hinge. Hinge battens shall be of brass.

Door latches shall be of brass, heavy, with wide lips and provided with suitable finger grips.

Cylinder shall be banded with wide, heavy stainless-steel hoops fitted with turnbuckle. Where the door is 27 inches long or longer, a hoop shall be fitted between the heads and shall encircle the cylinder completely, except at the door opening.

Door openings on 30-inch diameter shall be 12 inches wide; on 36 and 40-inch, shall be 16 inches wide.

Meehanite Metal trunnions shall be attached securely to cylinder heads.

TUB — Shall have heads and staves of clear or better fir. Staves shall be tongued, grooved, and rabbeted to fit over heads to which they shall be secured by wooden dowels.

Heads and staves shall be cut from clear or better stock, sizes of which follow:

| | Diameter of Cylinder | | |
|--------------------------------|----------------------|----|----|
| | 30 | 36 | 40 |
| Heads | 2 | 2 | 2 |
| Staves 30 and 36 inches long | 1½ | 1½ | — |
| Staves over 36 inches long.... | 2 | 2 | 2 |

An upwardly sliding tub door, equipped with a supply door, shall operate in guides provided on adjustable, encircling hoops, fitted with take-up bolts.

A water-level gage glass shall be suitably fitted into left end of tub to indicate the height of the liquid in the cylinder.

A sheet-brass splash apron shall be provided at bottom of door opening to protect the staves.

FRAMES — Shall be cast iron of one-piece, heavy construction, rigidly bolted to tub heads, and shall support weight of the cylinder, tub, and driving mechanism. Also see Belted Motor Drive.

BEARINGS — Journals of cylinder trunnions shall operate in solid-bored cast-iron bearings supported by the frame and equipped with easily-accessible lubricators.

GEARS — Shall be machine-cut from solid blanks and covered with a narrow, paneled gear guard.

Cylinder-drive gears shall be furnished at right end of machine only; except on 40-inch diameter with elevated header, double gearing shall be furnished, when so ordered.

On 30-inch diameter, 30 and 36-inch lengths, main gear shall be of solid-hub type; on all other sizes main gear shall be of split-hub type. All main gears shall be keyed to trunnion.

WATER INLET — A 2-inch water inlet-connection shall be provided at rear of tub; lengths over 54 inches shall have two inlets connected by a manifold.

OUTLET VALVE — Shall be of the foot-operated, positive-closing, self-cleaning type, 4 inches in diameter on the 30, 6 inches on the 36 and 40-inch diameter machines.

GEAR LOCK — A gear-lock, for locking cylinder in stationary position while the washer is being loaded or unloaded, shall be provided.

INCHING DEVICE — On 36 and 40-inch diameters, gear lock shall be combined with a handwheel on worm-gear shaft for bringing the cylinder door into alignment with the tub door.

(OVER)

The American Laundry Machinery Co.

D-1A—2500—B-L P.
Supersedes D-1, D-2, D-3A, D-4, D-5, D-6A, D-6B

New York, Cincinnati, Chicago, San Francisco

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Globe Washer—30, 36, 40-Inch Diameters—Belt and Belted Motor Drives

AUTOMATIC REVERSE-HEADER MECHANISM—Shall consist of three pulleys and a worm-and-cam movement to assure that the number of cylinder revolutions between reversals shall be uniform with but slight difference in either direction of rotation. Pulleys shall be of such widths as to carry belt of the widths shown below:

| Diameter of Pulley — | Diameter of Cylinder | | |
|-------------------------|----------------------|-------------|-------------|
| | 30 | 36 | 40 |
| 30 and 36-inch lengths | 12" | 16" | — |
| Over 36-inch length.... | 14" | 16" | 16" |
| Belt Widths — | | | |
| 30 and 36-inch lengths | 1 1/4" & 1 1/2" | 1 3/4" & 2" | — |
| Over 36-inch length.... | 1 3/4" & 2" | 1 3/4" & 2" | — |
| 54 and 64-inch lengths | — | — | 2" & 2 1/2" |
| 72-inch length and over | — | — | 2 1/2" & 3" |

Belt-shifting mechanism shall be mounted on a heavy, cast-iron swiveling arm, adjustable to belt at various angles.

Header mechanism shall be supported by a bracket arm bolted to cast-iron frames of the washer. Header shall embody strength, simplicity, and reliability.

BELTED MOTOR DRIVE

Machine shall be belt driven type, with end header, to which motor and transmission equipment shall be attached.

FRAMES — Two heavy iron uprights bolted to frames at each end of machines shall provide bearings for an overhead drive shaft; motor and starting device shall be attached to these uprights. A through tie bolt shall act as a stiffener for the two uprights.

ELECTRICAL EQUIPMENT— Shall conform to applicable sections of standards of the National Electrical Manufacturers' Association. All wiring between electrical units mounted on the machine shall be furnished installed in accordance with the National Electrical Code.

MOTOR — The drive motor shall be ball-bearing, grease-lubricated type, of ample capacity to operate the washer under continuous operating conditions without the motor temperature rise exceeding the limits allowed by N.E.M.A.

CONTROLLER — A magnetic-type controller in a sheet-metal enclosure with a removable cover shall be furnished mounted on the machine, for control of the drive motor. Needed operating push buttons will be furnished.

Where needed, controller shall incorporate protective resistance and relays.

WIRING — In conduit, shall be furnished connecting motor, operating switch, and controller, with provision at controller for service connections. Service disconnect switch shall be furnished by customer.

SPECIAL ITEMS (Furnished When Ordered)

GALVANIZED TRIM — Hinges and latches shall be galvanized iron.

RIBS — METAL COVERED RIBS — Standard wood ribs shall be encased in sheet brass or sheet Monel, as ordered.

SHEET METAL RIBS — Substitutes for standard wood ribs shall be sheet brass or sheet Monel, as ordered, hollow, with perforations double embossed.

BRASS TUB DOOR — Shall be upwardly sliding and be equipped with supply door.

DIAL WATER-LEVEL GAGE — Shall be a hydrostatic-type indicator, located in a position convenient for observation. The gage shall be calibrated to indicate the height of water in the cylinder, in inches. The water-level gage glass shall be omitted.

OVERHEAD PIPING — Water inlet-connections, at the rear of the tub, shall be connected with galvanized piping, extending beyond the end and toward the front of the washer, branching into two separate inlets, one for hot and one for cold water. Inlet valves shall be mounted at the front of the machine, at a convenient height.

BACK PIPING — Water inlet-connections, at the rear of the tub, shall be connected with galvanized piping, extending beyond the end of the Washer, branching into two separate inlets, one for hot and one for cold water. Controls for the inlet valves shall be mounted at the front of the machine, at a convenient height.

AMERICAN QUICK-OPENING VALVES — Each water inlet shall be fitted with a quick-opening globe valve with renewable disks, so designed that only one complete turn of the valve handle is necessary to open the valve wide.

HUEBSCH TUWAY, CHASE FLOATLESS DIAL, OR CHASE FLOAT VALVES — Shall be fitted to the hot and cold water inlet-piping and shall automatically close when the predetermined quantity of water has entered the cylinder.

HUEBSCH WASHOMETER — Shall be connected so as to cause at a predetermined time, the outlet valve to open and a bell, contained within Washometer housing, to ring.

When Recording Device is furnished, shall consist of a stylus and tape to record washing cycle and operations of outlet valve.

STEAM VALVE AND PIPING — Brass piping, extending beyond the end of the machine, shall be connected to the spray-head type steam inlet-connection at the bottom of the tub. Machines over 54-inch length shall have two inlets. The piping shall be fitted with a globe valve, the control for which shall be mounted at the front of the machine, at a convenient height.


THERMOMETER — Shall be located in a position convenient for observation. The bulb shall extend into the waterspace between the bottom of the cylinder and the tub, and be connected to the thermometer by a tube.

Safety Devices

END HEADER WASHER — Shall consist of a hook for holding cylinder doors open, tub door interlock, and fully enclosed gear guard.

ELEVATED HEADER — Shall consist of a hook for holding cylinder door open, tub door interlock, covered drive shaft and fully enclosed gear guard.

BELTED MOTOR DRIVE — Shall consist of hooks for holding the cylinder door open, tub door interlock, covered drive shaft, fully enclosed gear guard and fully enclosed belt guards.



40x54" GLOBE WASHER, END HEADER, SINGLE END DRIVE, EQUIPPED WITH BELTED MOTOR DRIVE.

Accuracy of illustrations and description of equipment shown herein applies to product as manufactured at time of publication. Printed in U. S. A.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

DEPARTMENT OF MINES AND RESOURCES

This space for use of Head Office only

REQUISITION FOR SUPPLIES File No.

May 20 1943

108-1-5

Requisition No.

Order No.

To The Departmental Purchasing Agent, Ottawa,

PLEASE FURNISH THE FOLLOWING SUPPLIES FOR USE OF Round Lake Indian Residential

School

VOTE 76 Allotment 09-615

SHIP TO Rev. A.C. Huston, Principal, Round Lake Indian Residential School, Whitewood, Sask.

Purpose for which required Parts for 36" x 54" Globe Wood Washer

NOTE:—Requisition for non-consumable equipment, state if New Issue or Replacement.
" consumable equipment and supplies use columns 1 and 2.

| Quantity | | Quantity on hand (1) | Quantity used per month (2) | Unit Price | TOTAL |
|--|---------------------------------------|----------------------|-----------------------------|------------|-------|
| 1 | New wood cylinder, galvanized trimmed | | | | |
| 1 | Main gear | | | | |
| 1 | Drive pinion | | | | |
| 1 | Worm wheel | | | | |
| 1 | Cam on worm wheel | | | | |
| <p>Note: Mr. Christianson reports that the washing machine at the Round Lake School is in very bad condition and the repairs mentioned above are absolutely necessary. The Canadian Laundry Machinery Co. was written with a view to ascertaining if they had the parts required and for your information I enclose their reply.</p> | | | | | |
| <p><i>Cancelled</i></p> | | | | | |

I hereby certify that I have personal knowledge that all the above articles are required in the Department and Departmental purposes only. The expenditure required by this requisition is strictly unavoidable and the public interest will suffer if it is not made.

SIGNED—

APPROVED—

Hurstwood Hill

Form 37

(SEE OTHER SIDE)

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Ottawa,
May 21, 1943.

Mr. M. Christianson, Gen. Supt. of Indian Agencies,
Dominion Public Bldg., Scarth & Victoria, Regina,
Sask.

With reference to your letter of the 4th instant, regarding the washing machine at the Round Lake Residential School, I believe it will be possible to secure the parts that are required to repair this machine at an approximate cost of \$131.00. If we supply these parts to the school will it be possible for them to have someone install them? Otherwise it will involve heavy expense in shipping the machine to the factory.

Philip Phelan,
Chief, Training Division.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)


PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

OFFICE OF THE
GENERAL SUPERINTENDENT
OF AGENCIES



CANADA
DEPARTMENT
OF
MINES AND RESOURCES File #304-11 A.U.

INDIAN AFFAIRS
BRANCH



AIR MAIL

Regina, May 22, 1943.

Indian Affairs Branch, Department of Mines & Resources, OTTAWA.

I wish to bring to your attention that a letter was written from this office, our File No. 304-11 A.U. on the 4th instant in connection with the washing machine at the Round Lake Indian Residential School.

I am surprised that we have not heard from you by this time. I have a letter from Mr. Huston, the Principal, this morning, and by the tone of his letter he is about ready to throw up his hands and I do not blame him. You can imagine what it is to be short handed and have between children and staff somewhere in the neighborhood of 100 people, and all of the washing having to be done by hand. Also, Mr. Huston informs me last week the jacket heater at the school cracked. This heater heated the water for washing and bathing purposes, in fact it heated all of the hot water for the school. Mr. Huston drove about 200 miles to different towns trying to get the crack in the heater welded but was unsuccessful.

I can assure you the situation is bad when they have neither hot water at the school with the exception of what can be heated on the stove, nor a washing machine, causing everything to be done by hand, and as Mr. Huston will be coming to the city this coming week I telephoned some of the firms here. We can procure a heater and I would like to have authority for this.

I would also like to know what is going to be done about the washing machine. If you were to ask me I would get all of the children out of the school and then put dynamite under it because it has been nothing but a bill of expense from beginning to end. However, you are not asking my advice on the matter so I do not suppose it will be blown up.

M. Christianson,
General Superintendent of Indian Agencies.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

EXD.

AIR MAIL

Ottawa, May 24, 1943.


Mr. M. Christianson, General Supt. of Indian Agencies,
Dominion Public Building, R e g i n a, Sask.

Re: Washing machine,
Round Lake Residential School.

This will acknowledge receipt of your letter of May 22, in which you express surprise that you have not received information with respect to the purchase or repair of the marginally noted washing machine.

The records here indicate that this matter was first brought to the attention of the Department in a letter dated Regina, May 4 and signed by John Raichman. This letter reached the Records office on May 7 and the Training Division on May 8. On May 10 we communicated with Mr. E. A. Guillaume, of the Canadian Laundry Machinery Company, Limited, Toronto, in an attempt to discover if machines of this type were available or if repairs to the machine now in operation could be undertaken. In order to avoid delay, however, a requisition for a new machine was sent forward to the Purchasing Agent. The Chief of the Training Division informed you, in a letter of May 21, that parts for this machine could be secured at a cost of \$131.00. You will note, therefore, that despite the limited staff at our disposal here, this matter was handled promptly and certainly in a way that should not give rise to surprise on your part.

We are sorry to note that you have not indicated the size or the approximate cost of the new heater that may be required at this school. As your letter seems to indicate, however, that an emergency exists, you are authorized to secure a heater, if a heater of the type required is available.



Director.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

File #304-11 A.U.

Regina, May 27, 1943.

Dear Sirs:

I wish to inform you that we have an Indian Boarding School down at Round Lake which is 17 miles north of Whitewood. The power washing machine there is an antiquated one that had been furnished a few years ago by some firm in Montreal and is beyond repair. Therefore you can imagine what state the School is in where there are 100 people in residence.

We have a 7 h.p. gasoline engine which provides the power for the washing machine, and I would like to know what one of your washing machines that would be suitable would cost. Also, would the 7 h.p. engine be sufficient to run it in the event we purchased one of your machines.

This, of course, has to be submitted to our Branch at Ottawa first but I thought I had better try to get all of the information I possibly could.

You will get this letter in the morning and I wish you would write to me, giving any information you might have as I want to receive your reply by Saturday morning without fail. If you can do this it would be very much appreciated.

I might say that Mr. Brook was in her to see me two or three months ago.

Yours truly,

M. Christianson,
General Superintendent of Indian Agencies.

Messrs. Stanley Brock Limited,
Laundry Machinery,
WINNIPEG, Man.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

OFFICE OF THE
GENERAL SUPERINTENDENT
OF INDIAN AGENCIES



CANADA
DEPARTMENT
OF
MINES AND RESOURCES

INDIAN AFFAIRS
BRANCH

108-1-5

File #304-11 A.U.

AIR MAIL

Regina, May 29, 1943.



Indian Affairs Branch, Department of Mines & Resources, OTTAWA.

Regarding the washing machine at the Round Lake Indian Residential School, upon receipt of your letter No. 108-1-5 of the 21st instant, I immediately got in touch with the Principal, Mr. Huston. Mr. Huston then got in touch with Mr. Kerley and asked him to take Mr. Webb, of the firm of Webb and Wellbelove, Broadview, down to the school to ascertain if it would be possible to repair the machine or not, promising to pay Mr. Webb for his time.

Mr. Huston was in the office here the day before yesterday and advised me Mr. Webb had told him the matter of repairing the washing machine is absolutely hopeless and since Mr. Webb is a practical man and a good carpenter and mechanic I think we can pretty well take his advice.

After hearing the above I got in touch with Stanley Brock Limited, of Winnipeg, and I am herewith attaching copy of my letter to them and also their reply. You will note that the machine they have in mind can be purchased for \$525.00 and I would think that this is the only solution. Therefore, if possible, I would ask that an order be placed for the machine in question unless our Branch has something better to suggest.

I am also attaching pamphlet illustrating the Canadian Globe Wood Washer sent to me by Stanley Brock and Company of Winnipeg. Will you please return these documents without fail.

M. Christianson,
General Superintendent of Indian Agencies.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

DEPARTMENT OF MINES AND RESOURCES

This space for use of Head Office only

REQUISITION FOR SUPPLIES File No. 108-1-5

May 31 19 43

Requisition No. _____
 Order No. _____

To The Departmental Purchasing Agent, Ottawa,

PLEASE FURNISH THE FOLLOWING SUPPLIES FOR USE OF Round Lake Indian Residential School

VOTE 76 Allotment 12-415
 SHIP TO Rev. A.C. Huston, Principal, Round Lake Indian Residential School, Whitewood, Sask.

Purpose for which required _____

NOTE:—Requisition for non-consumable equipment, state if New Issue or Replacement.
 “ consumable equipment and supplies use columns 1 and 2.

| Quantity | | Quantity on hand (1) | Quantity used per month (2) | Unit Price | TOTAL |
|---|---|----------------------|-----------------------------|------------|-------|
| 1 | Reconditioned 36" x 54" belt driven power wooden washer, one compartment, end header, similar to attached cut | | | | |
| <p>Note: For your information I enclose copy of a letter received from Mr. Christianson, also quotation received from Stanley Brock Limited. You will note that Stanley Brock quote a price of \$525.00, f.o.b. Winnipeg, for this washer. It is evident from Mr. Christianson's letter that it is impossible to repair the present washer which has been in use for several years. This school has an authorized enrolment of 75 and, as they are without washing facilities at the present time owing to the total breakdown of the washer, it would be appreciated if arrangements could be made to secure the new washer immediately.</p> | | | | | |

I hereby certify that I have personal knowledge that all the above articles are required in the Department and Departmental purposes only. The expenditure required by this requisition is strictly unavoidable and the public interest will suffer if it is not made.

SIGNED—

APPROVED—

Form 37

(SEE OTHER SIDE)

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
 ARCHIVES PUBLIQUES
 CANADA

GOVERNMENT OF CANADA



CANADA

RADIOTELEGRAPH SERVICE

ADMINISTERED BY

DEPARTMENT OF NATIONAL DEFENCE—OTTAWA, CANADA

CLASSES OF SERVICE

DAY MESSAGES
DAY LETTERS
NIGHT MESSAGES
NIGHT LETTERS

TELEGRAPH, CABLE
AND RADIO
CONNECTIONS
TO ALL PARTS OF
THE WORLD

| NUMBER | SENT TO | SENT BY | REC'D BY | TIME SENT | TIME FILED | CHECK |
|--------------------------------|---------|---------|----------|-----------|------------|---------|
| | | | | | | 108-1-5 |
| Copy for Indian Affairs Branch | | | | | | |

SEND THE FOLLOWING MESSAGE SUBJECT TO THE TERMS ON THE BACK HEREOF :-

RADIO DAY LETTER

Canadian Laundry Machinery Company, Ltd.,
47 Sterling Road,
Toronto, Ont.

ADVISE TODAY YOUR PRICE F O B WINNIPEG MANITOBA ON ONE THIRTY SIX
INCH BY FIFTY FOUR INCH BELT DRIVEN GLOBE WOODEN WASHER ONE
COMPARTMENT END READER ALSO ALTERNATIVE PRICE ON THIRTY BY FORTY
EIGHT INCH SIZE

H. J. Davidson.
Mines and Resources Department,
Ottawa, Ont.

Phoned by WMV to PIM
1/6/43 - 3.45 p.m.

N.D.—G. F. 4c.
15M pads 100-7-40 (6016-7)
H.Q. 82-20-5.

GOVERNMENT OF CANADA



CANADA

RADIOTELEGRAPH SERVICE

ADMINISTERED BY

DEPARTMENT OF NATIONAL DEFENCE—OTTAWA, CANADA

CLASSES OF SERVICE

DAY MESSAGES
DAY LETTERS
NIGHT MESSAGES
NIGHT LETTERS

TELEGRAPH, CABLE
AND RADIO
CONNECTIONS
TO ALL PARTS OF
THE WORLD

| NUMBER | SENT TO | SENT BY | REC'D BY | TIME SENT | TIME FILED | CHECK |
|---------------------------------|---------|---------|----------|-----------|------------|---------|
| | | | | | | 108-1-5 |
| Copy for Indian Affairs Branch. | | | | | | |

SEND THE FOLLOWING MESSAGE SUBJECT TO THE TERMS ON THE BACK HEREOF :-

RADIO DAY LETTER

Stanley Brock Limited,
145 Market Ave.,
Winnipeg, Man.

REFERENCE YOUR QUOTATION TWENTY EIGHTH ULTIMO TO MR. CHRISTIANSON
ON RECONDITIONED GLOBE WOODEN WASHER PLEASE ADVISE PROMPTLY WHAT
TRADE IN ALLOWANCE IF ANY YOU WILL OFFER FOR THE WASHER AT PRESENT
IN USE AT ROUND LAKE INDIAN RESIDENTIAL SCHOOL WHITEWOOD SASKATCHEWAN

H. J. Davidson.
Mines and Resources Department,
Ottawa, Ont.

Phoned by WMV to ML,
1/6/43 - 4.45 p.m.

N.D.—G. F. 4c.
15M pads 100-7-40 (6016-7)
H.Q. 82-20-5.

EX'D.
A

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

DEPARTMENT OF MINES AND RESOURCES

Order N^o 18694

108-1-5

This order number to appear on all packages and invoices

RECEIPT FORM

File No. 40270-12-10-1

Stanley Brock, Ltd.,
100 Main St.,
Winnipeg, Man.

Ottawa, June 7, 1943. 19

Supplies mentioned hereunder have been received and found satisfactory with exception of those listed under "Remarks".

Rev. A. G. Ruston, Principal,
Round Lake Indian Residential School, Whitehead, Sask.,

| QUANTITY | DESCRIPTION | UNIT | TOTAL |
|---|---|------|---------|
| 1 only | Reconditioned 36" x 36" belt driven power wooden globe washer, one compartment, end header, new wooden cylinder, new outside case, all bearings thoroughly reballited. To carry same guarantee as New Globe washer. This guarantee should be forwarded to Mr. H. A. Hoop, Indian Affairs Branch, Ottawa. Price f.o.b. Winnipeg, - | | 3000.00 |
| 1 only | Used washer at present in use at Round Lake Indian Residential School - This washer to be properly crated by the school authorities and shipped freight collect to your Winnipeg address | | 50.00 |
| | | | 3075.00 |
| <p>This order cancels Purchase Order No. 18514. Br. 354.</p> <p><i>Blue slip sent to Mr. Christenson June 10/43</i></p> <p>Prices F.O.B. as above as per your quotations of 5-6-43 & 5-2-43</p> | | | |

Shipping Instructions *W.M.* Rev. A. G. Ruston, Principal, Round Lake Indian Residential School, Whitehead, Sask.

Vote Primary Date to be delivered:

Encumbrance No. 386 Immediately.

Freight or Express charges paid

Remarks: (Report shortages, if any)

Branch Date

TO BE RETURNED TO HEAD OF BRANCH

Signature of Rec.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Ottawa,
June 10, 1943.

EXL.

Mr. M. Christianson, Gen. Supt. of Indian Agencies,
Dominion Public Bldg., Searth & Victoria, Regina, Sask.

With reference to your letter of the 29th ultimo and previous correspondence, regarding the washing machine at the Round Lake Residential School, the Departmental Purchasing Agent placed an order on the 7th instant with Stanley Brock Limited, Winnipeg, for the washing machine which you recommended be purchased.

Philip Phelan,
Chief, Training Division.

me

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

P.O.
661-76-12-422
—

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

**PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA**

EXD.

Ottawa, June 15, 1943.

Memorandum:DEPARTMENTAL PURCHASING AGENT.

I attach account amounting to \$122.00, covering the cost of a jacket heater for the Round Lake Indian Residential School. The jacket heater at this school was purchased several years ago and recently its condition became such that it could not be further used. Mr. Christianson, General Superintendent of Indian Agencies, recommended that a new heater be supplied immediately, as it was necessary to provide hot water for washing and bathing purposes at the school. Under the circumstances he was authorized to make local purchase. It would be appreciated if you would issue purchase order so that the account may be paid. The coding is as follows:- 661 - 76 - 12-422.

R. A. Hoey,
Supt. of Welfare & Training.

Encl.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

DEPARTMENT OF MINES AND RESOURCES
INDIAN AFFAIRS BRANCH

FORM No. I.A. 506A
Req. 1358

TREASURY ONLY

CHEQUE No.....
DATE.....

Pay to **Crane Limited,**
Address **1408 Broad Street,**
Regina, Sask.

Crooked Lake Agency.

| 1943 | DATE | SERVICE | AMOUNT |
|------|------|--|--------|
| May | 29 | To one V 30 Tank heater complete for the Round Lake Indian Residential School, Whitewood, Sask., as per attached account. Vote #76, Allot. 12-415 | 122 00 |
| | | One hundred & twenty-two --XX/100 Dollars | 122 00 |

I HEREBY CERTIFY that this Voucher is correct, that the material has been supplied, the work performed and that the charges are fair and just, also that the expenditure has been incurred legitimately and that each item of the same is a fair and just charge against the Government of Canada. This expenditure was authorized by Departmental Letter, File No. **108-1-5** dated **May 24th, 1943**

VOUCHER No. **76**

DATE **June 10th, 1943.** *W. J. D. Keule* Agent

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

DEPARTMENT OF MINES AND RESOURCES
INDIAN AFFAIRS BRANCH

FORM No. I.A. 506A
Req. 1358

TREASURY ONLY

CHEQUE No.....
DATE.....

Pay to **Crane Limited,**
Address **1408 Broad Street,**
Regina, Sask.

Crooked Lake Agency.

| 1943 DATE | SERVICE | AMOUNT |
|-----------|--|--------|
| May 29 | To one V 30 Tank heater complete for the Round Lake Indian Residential School, Whitewood, Sask., as per attached account. Vote #76, Allot. 12-415 | 122 00 |
| | One hundred & twenty-two --XX/100 Dollars | 122 00 |

TRIPPLICATE FOR FILE
22.6.43
Voucher in duplicate detached
for Accountant to pay.

I HEREBY CERTIFY that this Voucher is correct, that the material has been supplied, the work performed and that the charges are fair and just, also that the expenditure has been incurred legitimately and that each item of the same is a fair and just charge against the Government of Canada. This expenditure was authorized by Departmental Letter, File No. **108-1-5** dated **May 24th, 1943**

VOUCHER No. **76**

DATE

W. J. Kenley
June 10th, 1943.

Agent

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

DEPARTMENT OF MINES AND RESOURCES

Order N^o 18847

RECEIPT FORM

This order number to appear on all packages and invoices

File No. 15-29.

Place Order, Ottawa, June 10, 1942.

W. J. ...
W. J. ...
 Invoices already received.

Supplies mentioned hereunder have been received and found satisfactory with exception of those listed under "Remarks".

| QUANTITY | DESCRIPTION | UNIT | TOTAL |
|----------|---|--------|--------|
| 1 only | Purchased by Mr. Christianson to replace worn out jacket heater at Round Lake Indian Residential School 730 Tank Heater complete | 122.00 | 122.00 |

Regina, Sask.
 Prices F.O.B. as per your of

Shipping Instructions *Goods already received.*

Vote 75 Primary 12-432 Date to be delivered:

Encumbrance No. 488

Freight or Express charges paid

Remarks: (Report shortages, if any)

Branch TO BE RETURNED TO HEAD OF BRANCH

Date

Signature of Receiver

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
 ARCHIVES PUBLIQUES
 CANADA

Ottawa, June 15, 1943.

Memorandum:DEPARTMENTAL PURCHASING AGENT.EX'D
A

I attach account amounting to \$122.00, covering the cost of a jacket heater for the Round Lake Indian Residential School. The jacket heater at this school was purchased several years ago and recently its condition became such that it could not be further used. Mr. Christianson, General Superintendent of Indian Agencies, recommended that a new heater be supplied immediately, as it was necessary to provide hot water for washing and bathing purposes at the school. Under the circumstances he was authorized to make local purchase. It would be appreciated if you would issue purchase order so that the account may be paid. The coding is as follows:- 661 - 76 - 12-422.

R. A. Hoey,
Supt. of Welfare & Training.

RAH
Encl.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

GENERAL SUPERINTENDENT
OF INDIAN AGENCIES



CANADA
DEPARTMENT
OF
MINES AND RESOURCES

INDIAN AFFAIRS
BRANCH

W. A. ...
...

108-1-5

Regina, Sask. June 18, 1943.



EX'D.
A

Indian Affairs Branch, Department of Mines & Resources, OTTAWA.

I wish to inform you that I was down at the Round Lake School this week and I had a look at the boiler that has to be repaired. I have already made arrangements with the Regina Plumbing & Heating Company to send a good experienced man down there on Monday morning to examine the heating plant.

I hope that we will be able to repair it, but I am just doubtful. One of the difficulties there is that they use terribly hard water and the pipes corrode in a short time, and in all probability there are sections of this boiler that are corroded so badly that no water is passing through them at all. However, I have told Mr. Robertson, the Manager of this firm, that we want this plant to be fixed if at all possible. We will know in a few days and I shall advise you immediately.

Swales
...
Feb 27

M. Christenson

M. Christenson,
General Superintendent of Indian Agencies.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA



108-1-5
File 304-11AU

Regina, Sask. June 28, 1943.



[Handwritten signature]
Indian Affairs Branch, Department of Mines & Resources,
OTTAWA, Ont.

Last winter I had a letter from the School Branch asking me to have the furnace at the Round Lake Indian Residential School repaired during the summer time.

Last week I visited this institution and I wrote you on the 18th instant. I will admit that I am not a furnace man; however, I was anxious to see it before we took any steps to have it repaired, and that is one reason that I called at the school. As I advised you in my letter of the 18th instant, I had arranged with the Regina Plumbing & Heating Limited to send an experienced man down there to have a look at the boiler, and I am herewith attaching his report. I had a talk with Mr. Robertson before sending the man down and told him how anxious you were to have this boiler repaired instead of replaced. I also had a talk with Mr. Robertson and the man that he sent down there. They came over to the office just as I was leaving for Kamsack last Tuesday. You will note from Mr. Robertson's letter, which is attached herewith, that he does not recommend spending any money on this boiler, because in all probability it would go out of commission during the coming winter and leave the school without any heat. I saw the boiler myself and everything they say about it is correct; in fact it is in terrible shape.

As soon as I get the bill from the Regina Plumbing and Heating Limited for sending a man down there it will also be forwarded, and the next thing is what is to be done to replace this furnace.

[Handwritten signature: M. Christianson]
M. Christianson,
General Superintendent of Indian Agencies.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Ottawa, July 5, 1943.

EX'D.
A

Mr. M. Christianson, General Supt. of Indian Agencies,
Dominion Public Building, Scarth & Victoria Streets,
R e g i n a, Sask.

The Department has received your letter
of the 28th ultimo, with reference to the furnace
at the Round Lake Indian Residential School.

Please let me have detailed information
regarding the type of boiler required, and an
endeavour will be made to secure same.

Philip Phelan,
Chief, Training Division.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Phone 23310

Regina Plumbing and Heating, Limited

HEATING AND PLUMBING CONTRACTORS

CLAIMS CAN ONLY BE CONSIDERED
WHEN MADE WITHIN FIFTEEN DAYS
FROM DATE OF INVOICE.

2416 Eleventh Avenue,

REGINA, Sask., June 1943

Sold to Department of Indian Affairs,

Federal Bldg., Regina.



Accounts due when rendered

E. & O. excepted

Interest at 8 per cent. per annum charged on all overdue accounts

| DATE | ARTICLES | LABOR | MATERIAL | TOTAL |
|---------|---|-------|----------|--------------|
| June 21 | To Steamfitters time inspecting Boiler at Round Lake School <i>12 1/2 hrs @ \$1.40</i> | 17 50 | | |
| | Railway Ticket | | 6 60 | |
| | | 17 50 | 6 60 | <u>24 10</u> |

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

ROUND LAKE INDIAN RESIDENTIAL SCHOOL

THE WOMEN'S MISSIONARY SOCIETY
United Church of Canada

REV. A. C. HUSTON,
Principal

WHITEWOOD,
Saskatchewan

July, 15/43.

Mr. M. Christianson,
Gen. Supt. of Indian Agencies,
Regina, Sask.



Dear Mr. Christianson;

The Newly reconditioned washer has arrived from The Stanley Brock Limited, Winnipeg. It now rests well covered from the weather just outside the school Residence. We thought we would wait a rainy day before we would call the men from the hay for such a task as removing the old washer and installing the new.

Mr. Kerley was here to-day with the Auditor and we under took to investigate the washer and to tell you truthfully it is not what one might expect for \$525.00. The mechanical part of course is newly painted and its difficult to determine its condition until it is in operation for awhile. The wooden sections are constructed mainly of fir lumber with the addition of four or five pieces of hardwood. Mrs. Webb of Broadview when called to give an estimate on costs about two months ago suggest Cyprus as the ideal lumber for the job but doubted if such could be procured under existing circumstance.

The workmanship with the lumber used had certainly not been the best. Indeed I would say it lacked what you would expect to find from the hand of an experienced and particular workman. The washer is smaller than our former one. Indeed I would say that one should be able to secure its like in the neighbourhood of two hundred and fifty dollars.

Now of course we have to place all this criticism over against the fact of war. We have to have a washer. The war is on. It is impossible to get a new one and what can we do about it. There seems to be no alternative. However I do feel that it would not hurt to bring all this to the notice of the company. They will soon be looking about for post-war business and I would say that unless they have a monopoly of the Washer business that they are putting themselves in the way of losing business. You could consult Mr. Kerley as to his opinion and I will let the washer stand until I hear from you.

Yours sincerely,

A handwritten signature in cursive script that reads "A. C. Huston".

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

OFFICE OF THE
GENERAL SUPERINTENDENT
AGENCIES



CANADA
DEPARTMENT
OF
MINES AND RESOURCES

108-1-5
File #304-11 A.U.

INDIAN AFFAIRS
BRANCH

Regina, July 19, 1943



Indian Affairs Branch, Department of Mines & Resources, OTTAWA.

I am herewith forwarding a letter received from
Mr. A.C. Huston, Principal of the Round Lake Indian Residential School,
Whitewood. I have not the time to make a copy.

This letter speaks for itself and you will note Mr. Huston
does not think very much of the new tumbler for the washing machine that
he has received from The Stanley Brock Limited Company.

M. Christianson,
General Superintendent of Indian Agencies.

Encl.

Indian Affairs. (RG 10, Volume 6333, file 661-5, part 5)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA