

DEPARTMENT OF MINES AND RESOURCES

Order N<sup>o</sup> 27268

RECEIPT FORM

This order number to appear on all packages and invoices

File No. 15-3 Ont.

Walter S. Channer,  
104 Dundas St.,  
London, Ont.

Ottawa, October 20, 1944.

Supplies mentioned hereunder have been received and found satisfactory with exception of those listed under "Remarks".

Invoices already received.

QUANTITY	DESCRIPTION	UNIT	TOTAL
	Wall paper purchased for the Mount Elgin Indian Residential School and Principal's Residence as per invoice dated Oct. 11th 1944. Voucher No. 287		87.00
WMV/HC	Prices F.O.B.	as per your	of

Shipping Instructions Already received

Vote 76 Primary 10-691 Date to be delivered:

Encumbrance No. 1032

Freight or Express charges paid

Remarks: (Report shortages, if any)

Branch TO BE RETURNED TO HEAD OF BRANCH

Date

Signature of Receiving Officer

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

7-0-5

Ottawa,  
October 19, 1944.

Memorandum:

DEPARTMENTAL PURCHASING AGENT

I attach account amounting to \$87.60, covering purchase of wall paper required for papering the Principal's quarters at the Mount Elgin Residential School. It would be appreciated if you would issue purchase order so that the account may be paid. The coding is as follows: 468-76-10-691.

R.A. Hoey,  
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

THE MOUNT ELGIN INDIAN RESIDENTIAL SCHOOL

MUNCEY, ONTARIO

DEPARTMENT OF MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH

THE UNITED CHURCH OF CANADA  
REV. S. H. SOPER, M.A., PRINCIPAL

Nov. 6th 1944.

12524

Mr. G. W. Down,  
Indian Agent,  
Muncey.

Dear Mr. Down;


A Bush Fire Destroyed the house over the water tank on the Moses Seneca property Nov. 1st. at 6.30.P.M.

I am reporting this to you for advice and recommendation at your convenience.

At present prices I believe it will take \$20 .00 for material and \$5.00 for labour to make a suitable replacement . The concrete tank is flush with the ground and in consequence dirt is blowing in and is carried down into the water supply pipes.

I am enclosing bill from Caradoc Farmers for five bags cement to complete the pavement near the back entrance steps.

I remain yours sincerely.

S. H. Soper.  




Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA


OFFICE OF THE  
INDIAN AGENT



CANADA


DEPARTMENT  
OF  
MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH

7-0-5  
PLEASE QUOTE  
FILE 125-4



Muncey, Ontario,  
November 8th, 1944.

I submit herewith, for your consideration, a report as received from the Rev. Mr. Soper which is self-explanatory. I have made enquiries and learned that a small bush-fire, more or less a grass-fire, about a  $\frac{1}{2}$ -mile from the Institute destroyed a small frame shack covering the springs and water supply tank. For sanitary purposes this building should be replaced. Mr. Soper, in his letter, has submitted an estimate as to the cost. I would recommend approval.

  
Geo. W. Down,  
INDIAN AGENT.

Indian Affairs Branch,  
Dep't of Mines & Resources,  
Ottawa.

GWD/BC

Encl

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

7-0-5

*Handwritten scribbles and initials, possibly "R.A. Hoey".*

Ottawa,  
November 10, 1944.

Mr. G.W. Down, Indian Agent, Muncey, Ont.

With reference to your letter of the 8th instant, the Department approves an expenditure of \$25 for material and labour in repairing the building over the water tank on part of the property leased by the Mount Elgin Indian Residential School.

*Handwritten scribbles and initials, possibly "R.A. Hoey".*

R.A. Hoey,  
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

7-0-5

Copy sent to Mr. Down

Ottawa,  
November 10, 1944.

EX'D.  
A

Dear Mr. Soper:

With reference to that portion of your letter of the 9th instant which refers to the new pump for the laundry, Mr. Phelan understood that you were going to submit specifications and approximate cost. No such information has yet reached us. However, as it is evident from your letter that this pump is required immediately, this letter will authorize you to make immediate purchase. The account should then be forwarded for payment through the Agent's office. A copy of this letter is being forwarded to Mr. Down.

Yours truly,

R.A. Hoey,  
Supt. of Welfare & Training.

Rev. S.H. Soper,  
Principal,  
Mount Elgin Indian Residential School,  
Muncey, Ont.

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

Phone 61 R 3

Int. at 6% added

# The Caradoc Farmers' Co-operative Co. Ltd.

DEALERS IN

Flour, Feed, Grains, Seeds, Potatoes, Cement, Cattle, Horses  
and other goods. Custom Chopping and Rolling  
Also Lime and Fencing

Mt. Brydges, Ont.,

*Chart 6*  
*Mt. Elgin Indian Agency*

KEEP THIS COPY AS YOUR ONLY  
ITEMIZED ACCOUNT

Account  
Forwarded

*5 sacks cement*

*335*

*Charge to Dept of Indian Affairs*  
*Chey*

15

DOMINION STATIONERS, TORONTO

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

**PUBLIC ARCHIVES**  
**ARCHIVES PUBLIQUES**  
**CANADA**





ONTARIO

DEPARTMENT OF LABOUR

EAST BLOCK, PARLIAMENT BUILDINGS  
TORONTO 5

TELEPHONE ADELAIDE 1211

November 15, 1944.

Department of Indian Affairs,  
Mount Elgin Indian Residential School,  
Munsey, Ontario.

Attention: Mr. S.H. Soper,  
Superintendent.

Gentlemen:

On October 26th our Inspector Mr. A.E. Turner made the following annual inspections of pressure equipment located in the Mount Elgin Indian Residential School.

Kewanee Heating boiler #1, O.A.#12840

Condition satisfactory and certificate will be issued in due course.

Vertical boiler #2, O.A.#12841

- X A drain valve or cock must be connected in the plugged opening provided for that purpose and operated frequently.
- X A check valve must be fitted in the cold water supply line to this boiler.
- X The welded bracket in the rear of the boiler supporting the chimney was found to be in danger of collapse and had been partly destroyed by the products of combustion. This bracket must be rebuilt and will require the employment of qualified welders. At the time of making repairs kindly notify our Inspector Mr. A.E. Turner, Box 336, Windsor, Ontario, in order that an internal inspection can be made. The gases that can escape from this breaching are considered to be dangerous and the repairs should be made without delay.

H.R.T. boiler #3 O.A.12842.

- X A cold water supply line was found to be directly connected to the boiler. This line must be fitted with a check valve close to the boiler.
- X The front arch over the fire door was found to be burned out, leading to serious deterioration of the cast iron front from over heating. The arch must be rebuilt and extended to protect the rivet heads in the front head seam.
- There was evidence of a low water condition at some time in the past which may have caused slight seepage at the circumferential seam over the bridge wall. This condition is not considered to be serious at this time.
- X Three tubes appeared to have been renewed recently. There was slight seepage at these tube ends on the rear head in the combustion chamber. These tube ends must

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



ONTARIO

DEPARTMENT OF LABOUR

EAST BLOCK, PARLIAMENT BUILDINGS  
TORONTO 5

TELEPHONE ADELAIDE 1211

Dept. of Indian Affairs,  
Mount Elgin Indian Residential School,  
Munsey, Ontario.

November 15, 1944.

H.R.T. boiler #3 O.A.12842- Cont'd.

be properly flared or beaded at this time.

Kindly advise this office when repairs to this boiler have been made in order that we may issue and forward the necessary certificate.

Hydro-pneumatic Tank O.A.12843

1. The check valve between the safety valve and the tank must be removed.
2. The tank must be raised several inches to allow ventilation and inspection of the lower head.

Kindly advise this office when the above items have been attended to in order that we may issue and forward the necessary certificate.

Steam Chest #5 O.A.12844.

Condition satisfactory and certificate will be issued in due course.

Steam Chest #6 O.A.12845.

Condition satisfactory and certificate will be issued in due course.

The fees chargeable for inspections amount to \$9.00 for which we are enclosing invoice.

Yours very truly,

*J.N. Briggs*  
J.N. BRIGGS,  
DIRECTOR.

JNB:AC.  
ENC.

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

THE MOUNT ELGIN INDIAN RESIDENTIAL SCHOOL

MUNCEY, ONTARIO

DEPARTMENT OF MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH

THE UNITED CHURCH OF CANADA  
REV. S. H. SOPER, M.A., PRINCIPAL

Nov 15th 1944.

Mr G W Down.  
Indian Agent.  
Muncey.

Dear Mr Down;

I am enclosing herewith the report of the Boiler Inspector  
Mr. A.E.Turner.

This report bears out your own considered opinion , in which I heartily  
concur, that matters of real importance here have been tinkered with  
too long and it is high time that some real renovations be made before  
everything is in a state of total collapse.

May I trouble you to have the enclosed report sent to the  
Department in order that authority for repairs be made in due course.

Yours very sincerely.

S. H. Soper  


Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

OFFICE OF THE  
INDIAN AGENT



CANADA  
DEPARTMENT  
OF  
MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH

7-0-5  
PLEASE QUOTE  
FILE 125-4

Muncey, Ontario,  
November 18th, 1944.

I attach herewith for your consideration a complete report on a boiler inspection at the Mount Elgin Residential School, recently authorized under file 7-0-5 September 29th, 1944.

It would appear quite evident from the report that the unit needs repair. The greatest difficulty would be in securing an experienced boiler man to do the work. Time also is a factor at this season of the year. Personally I am crowded to capacity with more work than I can comfortably handle. However, if you will please advise what action you want taken I will discuss the matter with Mr. Soper, and with his usual cooperative spirit we may be able to arrive at some satisfactory solution.

*Geo W. Down*  
Geo W. Down

Indian Agent.

Indian Affairs Branch,  
Dep't of Mines & Resources,  
Ottawa.



encl.

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

7-0-5

Ottawa,  
November 23, 1944.

Mr. G.W. Down, Indian Agent, Muncey, Ont.

I am in receipt of your letter of the 18th instant, enclosing report on the boiler inspection at the Mount Elgin Residential School. In view of the Boiler Inspector's report, the following repairs are approved:

Vertical boiler #2, O.A.#12841

A drain valve or cock must be connected in the plugged opening provided for that purpose and operated frequently.

A check valve must be fitted in the cold water supply line to this boiler.

The welded bracket in the rear of the boiler supporting the chimney was found to be in danger of collapse and had been partly destroyed by the products of combustion. This bracket must be rebuilt and will require the employment of qualified welders.

H.R.T. boiler #3 O.A.12842

A cold water supply line was found to be directly connected to the boiler. This line must be fitted with a check valve close to the boiler.

The front arch over the firedoor was found to be burned out, leading to serious deterioration of the cast iron front from overheating. The arch must be rebuilt and extended to protect the rivet heads in the front head seam.

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

Three tubes appeared to have been renewed recently. There was slight seepage at these tube ends on the rear head in the combustion chamber. These tube ends must be properly flared or beaded at this time.

Hydro-pneumatic Tank O.A. 12843

1. The check valve between the safety valve and the tank must be removed.
2. The tank must be raised several inches to allow ventilation and inspection of the lower head.

R.A. Hoey,  
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

Phone B10

MT. BRYDGES, Ont.,

Nov. 16/44

194

Dept. Mines and Resources, Indian Affairs

Invoice #10,940  
In triplicate

Caradoc Agency, Muncney, Ont.

Mat deld- Nov. 6  
their truck per  
S. Dodds

In Account with

# LONGFIELD BROTHERS LIMITED

DEALERS IN

*Lumber, Coal, Builders' Supplies, Posts, Lath, Shingles, Wall Board,  
Building Paper*

CUSTOM SAWING AND PLANING

All accounts due when rendered.

Interest Charged on Overdue Accounts.

For: MT. EGIN INSTITUTE

155 ln1.ft. 1 x 10, Select #3 Pine, rgh 129' BM	\$83	10	70
5 pcs - 2 x 12 - 12' Nwy Pine, rgh 120' BM	\$81	9	72
2 pcs. -2 x 10 - 16' Nwy Pine, rgh 53-1/3' BM	\$75	4	00
Ripping and dressing ) 1/2 hour machine work)			75
		\$	25 17

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



GOVERNMENT OF THE



PROVINCE OF ONTARIO

ONTARIO  
**TO BOILER INSPECTION BRANCH DEPARTMENT OF LABOUR DR**

MAKE CHEQUES PAYABLE TO PROVINCIAL TREASURER OF ONTARIO AND FORWARD  
 TO CHIEF BOILER INSPECTOR, EAST BLOCK, PARLIAMENT BUILDINGS, TORONTO

MESSRS.

Dept. of Indian Affairs,  
 Mount Elgin Indian Residential School,  
 Munsey, Ontario.

DATE

November 15, 1944.

DATE		SERVICE			AMOUNT	
1944.		MOUNT ELGIN INDIAN RESIDENTIAL SCHOOL, MUNSEY.				
Oct.	26					
		Kewanee Heating boiler #1	O.A. 12840	2	50	
		Vertical boiler #2	12841	1	50	
		H.R.T. boiler #3	12842	1	50	
		Hydre-pneumatic Tank #4	12843	1	50	
		Steam Chester #5	12844	1	00	
		Steam Chester #6	12845	1	00	\$ 9 00
		Inspector A. E. Turner				

**IMPORTANT**KINDLY RETURN COPY OF INVOICE  
WITH YOUR REMITTANCE

INVOICE NO. 08775

10M-JUNE 48(A2814)

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

**PUBLIC ARCHIVES**  
**ARCHIVES PUBLIQUES**  
 CANADA



7-0-5

THE MOUNT ELGIN INDIAN RESIDENTIAL SCHOOL

MUNCEY, ONTARIO

DEPARTMENT OF MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH

THE UNITED CHURCH OF CANADA  
REV. S. H. SOPER, M.A., PRINCIPAL

*[Handwritten signature]*



November 21st 1944.

Mr R.A. Hoey.  
Department of Indian Affairs.  
Ottawa.

Dear Mr Hoey;

I am sorry to worry you over what seems a small matter but a very important one to us.

We have not been able to obtain the items on this order sheet and this is the third time this order has been sent in. Granger Taylor assures us that we have had the very last allotment possible in fact they gave us all of some lines that they obtained from the mill.

*W*

We simply cannot buy at retail prices. Is there any way that you could send this order to some place where it could be given priority rating. If these children were at home their parents would shop round till they got things. We cannot do that.

Then again we have an appropriation for electrical repairs but simply cannot get wire and fittings. Here again it seems that we must get some kind of priority before we can get materials. Is there any way that this can be done?

Anything that you can do to help us in this vital matter will be greatly appreciated.

Yours very sincerely.

S. H. Soper  
*[Handwritten signature]*

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

THE MOUNT ELGIN INDIAN RESIDENTIAL SCHOOL

Muncey, Ont., Oct 23 1944

To Granger Taylor

Dep.

PLEASE SUPPLY THE FOLLOWING GOODS AND CHARGE TO OUR ACCOUNT:

2	doz	boys helmets
1	"	wrens winter caps
1	"	smocks size 30
2	doz	overalls, size 30
2	"	" " 28"
4		overalls size 34
4		" " 36
2	doz	mackinaw Sox, large
3	"	" " medium
1	"	" " small
3	"	boys mitts, small

The Mount Elgin Indian Residential School  
Per .....


Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



*See  
attached with  
plans*

*7-0-5  
File*



Muncey, Ontario,  
July 25th, 1944.

Re Survey:  
Mt. Elgin Residential School

Reporting on my recent survey of barns and outbuildings at the Mt. Elgin Residential School, as requested in your letter of July 3rd, I know of no better way than to take you on an imaginary tour. To enable you to readily visualize positions and approximate distances from the main School buildings, I have prepared a rough plan which is herewith attached. To further assist I have numbered the buildings in order of our travel.

Starting from a point south is Building No. 1. This is a large barn, 100' by 50', with annex attached 27' by 18'. This building is constructed of slop cement stabling wall with hip roof, upper structure all steel storage barn with cement silo attached. It is in first class condition throughout and fully equipped to house a large number of any type of farm animal.

Travelling north a distance of approximately 200', we enter Building No. 2. This is a T-shaped barn measuring 100' by 40' and 70' by 30'. It has the same construction as No. 1 with two silos attached. It is in first class condition and especially equipped with steel stanchions and steel stalls to house approximately 100 head of cattle. It is, without doubt, on of the most up-to-date barns in Western Ontario.

Travelling north a distance of approximately 150' we enter Building No. 3. This is an L-shaped building 30' by 50' and 30' by 60'. The 30' by 50' is in a dilapidated, unsafe condition and should be demolished. The 30' by 60' is an implement shed in a good state of repair.

Travelling north a distance of approximately 100' we enter Building No. 4. This is a brick building 25' by 16'. The order here is confusion but at some time it has been used as a general repair for farm machinery. It is in need of major repairs.


Turning west and travelling a distance of approximately 75', we enter Building No. 5, 60' by 20'. This is an all steel, dirt floor implement shed in A 1 condition throughout.

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

Approximate measurements

Survey of Farm Buildings  
Mt Elgin Residential School 18'



Geo W. Down  
INDIAN AGENT

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

Turning south we travel a distance of approximately 100' and enter Building No. 6, 40' by 66'. This building has a brick foundation stabling with an all steel upper structure hay barn. It is equipped exclusively for horses having fourteen individual stalls and one box-stall. It is in first class condition.

Travelling south and passing the main School buildings, a distance of approximately 500 ft., we enter Building No. 7. This is a two-story brick building, 24' by 24'. It is used as a general store house and the raising of early chickens. Some work on the outside brick is necessary to put this building in good repair.

Turning west we travel a distance of approximately 250' and enter Building No. 8. This is a one-story, 20' by 50', frame henhouse in good condition.

The water system, throughout, is supplied from springs located on Indian property and is, I think, under long term lease. It is piped and pumped into pressure tanks and as far as is known, it has never failed.

Root storage facilities consist of two rooms, 14' by 24' each, both dry and suitable for any type of storage; also, one room, 15' by 40'. The smell here is very bad and the place is musty and wet. However, its location lends itself readily to drainage and I think that is all it needs to correct the condition.

This completes our tour and general survey of the farm buildings; and I would say <sup>they</sup> constitute one of the finest and most up-to-date set of farm buildings in Western Ontario. Under proper management and with the leased lands attached they could be made to serve the full requirements of the Mt. Elgin Residential School, not only in the matter of providing food for the pupils and staff but one of the most up-to-date instructional centres for all Indians in Ontario, west of Toronto. There would be, of course, changes and perhaps a few problems before realization of a plan could materialize, but nothing of a nature that co-operation could not overcome.

In submitting this report please keep in mind that it is merely a report on the barns and outbuildings in an endeavour to enable you to decide as to the advisability of renting or utilizing them in our general Welfare program as suggested in your letter of July 3rd.

  
Geo. W. Down,  
INDIAN AGENT.

Indian Affairs Branch,  
Dep't of Mines & Resources,  
Ottawa.

GWD/bc

Epls

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

7-0-5

Ottawa,  
November 28, 1944.

EX'D.  
A

Dear Mr. Soper:

Mr. Hoey has referred to me your letter of the 21st instant, with reference to securing certain items of clothing for the boys at the Mount Elgin School. I regret very much that it is impossible for us to assist you in this particular regard. As you know, clothing for pupils attending the school is provided by the school management. I realize that if we purchased the clothing you would be prepared to refund the cost. However, we have never taken such action and it is quite possible that if we made an exception in one case we would receive many similar requests.

Yours truly,

Philip Phelan,  
Chief, Training Division.

Rev. S.H. Soper,  
Principal,  
Mount Elgin Indian Residential School,  
Muncey, Ont.

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

DEPARTMENT OF MINES AND RESOURCES

INDIAN AFFAIRS BRANCH

TREASURY ONLY

CHEQUE No. ....

DATE .....

Pay to..... Principal of the Mt. Elgin School,

Address..... Muncey,

..... Ontario.

EXD

1944	DATE	SERVICE	AMOUNT
	Dec. 7	To allowance toward salary of the Night Watchman at the Mt. Elgin Residential School for the month of November, 1944.  (Duties commenced November 25th, 1944.)	10.00
		Apr. 30. 50.00	
		11-12-44	

I HEREBY CERTIFY that this Voucher is correct, that the material has been supplied, the work performed and that the charges are fair and just, also that the expenditure has been incurred legitimately and that each item of the same is a fair and just charge against the Government of Canada. This expenditure was authorized by Departmental Letter, File No. 7-0-5 dated NOV. 12/43

FORM No. I.A. 506

Req. 1265

*[Signature]*

Agent

VOUCHER No. 372

DATE December 7th, 1944.

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

**Longfield Brothers**  
 W.H. LONGFIELD, MANAGER  
 LUMBER PHONE B10 COAL LIMITED

HOUSE FURNISHING  
 BUILT IN FURNITURE

Mt. Bridges, Ont.  
 CANADA

December 6, 1944.

Dept. Mines & Resources,  
 Indian Affairs, Muncey Agency,  
 W. H. Down, Agent, Muncey, Ont.

Invoice No. - 11,248  
 in triplicate

Taken by: G. Long

All accounts due when rendered.

Interest Charged on Overdue Accounts.

FOR: Mt. Elgin Institute

20 pcs. 1 x 12 - 12'	#3 Com Pine, rgh	240'	\$78	18	70
10 pcs. 1 x 6 - 12'	" " " "	60'	\$70	4	20
42 ft. ln. 1 x 2	" " " "	"	"		50
20 pcs. 2 x 4 - 8'	Norway Pine	107'	\$73	7	80
6 sheets 4' x 8'	Ironwood Wallboard	192'	\$35	6	70
				<hr/>	
				\$	37 90
				<hr/>	

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
 ARCHIVES PUBLIQUES  
 CANADA



OFF. THE  
INE. GENT


*Schroeder*



CANADA  
DEPARTMENT  
OF  
MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH

7-0-5

PLEASE QUOTE  
FILE 125-4



Muncey, Ontario,  
December 20th, 1944.

The Rev. Mr. Soper, of the Mt. Elgin Residential School, has again been billed by Walter D. Channer, of London, for an old account authorized by the Rev. Mr. Strapp. In this connection I would refer you to Voucher No. 239, dated September 16th, 1944. Attached to this voucher was a notation explaining the amount namely, \$ 16.18.

Mr. Channer reports that he has not yet received this amount, and as I had not been advised to the contrary I presumed the account had been paid. It would be appreciated if you would advise as to what action was taken in this matter.

*Geo. W. Down*

Geo. W. Down,  
INDIAN AGENT.

Indian Affairs Branch,  
Dep't of Mines & Resources,  
Ottawa.

GWD/BC

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

DEPARTMENT OF MINES AND RESOURCES

FORM No. I.A. 506A

INDIAN AFFAIRS BRANCH

TREASURY ONLY

CHEQUE No.....

DATE.....

Pay to..... **Geo. H. Channer,**

Address..... **104 Dundas Street,**

**London, Ont.**

DATE	SERVICE	AMOUNT
1944 Dec. 27	To Cost of wall paper supplied to The Mount Elgin Indian Residential School, as per account dated June 15, 1944. -	\$16.18

28.42.44

I HEREBY CERTIFY that this Voucher is correct, that the material has been supplied, the work performed and that the charges are fair and just, also that the expenditure has been incurred legitimately and that each item of the same is a fair and just charge against the Government of Canada. This expenditure was authorized by Departmental Letter, File No..... dated.....

VOUCHER No.....

DATE.....

Agent

Indian Affairs. (RG 10, Volume 6207, file 468-5, part 9)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA

