

133-0-5
Indian Residential School

PHONE 2838
[Handwritten scribble]



REV. R. T. CHAPIN. B.A.
PRINCIPAL

Brandon, Man., June 9, 1942.



The Secretary,
Dept. of Mines & Resources,
Indian Affairs Branch,
Ottawa, Ont.

Dear Sir:

I am enclosing correspondence which I have just received from the Manitoba Power Commission, in reference to our distribution system within the School property.

A short time ago the electrical engineer and head linesman were here because of a blow-out through lightning. They pointed out to me that in one place particularly, the line was in a very dangerous condition, and so we went over the whole distribution system. At one point between poles 1 and 2, wires are so low that you can almost reach them with an upstretched hand. The insulation on the wires is becoming so old and worn that in some places it is breaking away, leaving the wires in a very dangerous position. By putting a higher pole in at number 2, and moving it to a little higher ground to the north, this danger can be eliminated. I asked them of the possibility of running the wires at the edge of the girls' playground, instead of across it, with the pole in the centre of the playground. This they measured out and considered very feasible indeed advisable, replacing pole number 3 with a higher pole to the north. Near pole number 6 a large shade tree on the edge of the lawn is growing into the wires, and to eliminate danger from

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

Page 2.

the high voltage wires, this would either have to be cut out or pole number 6 moved farther north. They recommended this latter, as it would also straighten the line. Poles 7, 8 and 9 are deteriorating beneath the ground and becoming somewhat shaky. Likewise two poles near the barns need replacing. The good part of pole number 3 could be used for one of these. So a total of six new poles is required. They are making us allowance for the old poles, as the top parts of them could be utilized in some of their other work. As they pointed out, where we have so many children, it is in the interests of safety to keep the line in good condition, and I would recommend that the improvements be carried on, and ask for authority for them to proceed with the work.

Yours very truly,

R. T. Chapin

RTG/TS

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

Ottawa,
June 13, 1942.

EXD

Reverend Sir:

I have your letter of the 9th instant, with reference to the work which should be done on the electrical distribution system at the Brandon Indian Residential School. It is noted that the Manitoba Power Commission has estimated that the necessary work can be done at a total cost of \$179.30. Funds are available for this purpose and you may arrange to have the necessary repairs made as soon as possible.

Yours truly,

R.A. Hoey,
Supt. of Welfare & Training.



Rev. R.T. Chapin,
Principal,
Indian Residential School,
Brandon, Man.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

Shop Phone 3270
Res. Phones 3819-2601

McDOWELL & DOKE

TINSMITHS



AUTO AND TRACTOR RADIATORS REPAIRED, RECORDED AND CLEANED
IRON FIREMAN STOKERS. WILLIAMS OIL-O-MATIC OIL BURNERS

115 9th St. Brandon, Man., *June 9* 194

Sold to *Industrial School*

Brandon, Man.

TERMS CASH—8% charged on overdue accounts.

DATE	ARTICLES	FOLIO	CREDIT AMOUNT	DEBIT AMOUNT	TO
<i>May 27</i>	<i>Making & erecting smoke pipe on 2 large tractors</i>			<i>100.-</i>	
				<i>7/0</i>	

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

*VERY
POOR
COPY*

133-0-5
Indian Residential School

PHONE 2838



REV. R. T. CHAPIN, B.A.
PRINCIPAL

Brandon, Man., June 10, 1942.



The Secretary,
Dept. of Mines & Resources,
Indian Affairs Branch,
Ottawa, Ont.

Dear Sir:

Enclosed is voucher number 11 in favor of McDowell & Deke for replacing pipes on furnaces under authority of your letter of May 8th, 1942, file 133-0-5.

Yours truly,

R. T. Chapin

RTC/TS

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

332 LEGISLATIVE BUILDING

WINNIPEG, MAN., August 15, 1942.

Dept. of Indian Affairs,

Dominion Government,

Winnipeg, Manitoba.

IN ACCOUNT
WITH

BUREAU OF LABOR

Indian School--Brandon

Sept. 10, 1941	To Boiler Inspection Report #355	3.00
Sept. 10, 1941	To Boiler Inspection Report #356	3.00
Sept. 10, 1941	To Boiler Inspection Report #357	3.00
Aug. 8, 1942	To Boiler Inspection Report #75	3.00
Aug. 8, 1942	To Boiler Inspection Report #76	3.00
Aug. 8, 1942	To Boiler Inspection Report #77	3.00
		<hr/>
		\$18.00

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

Report of Boiler Inspection

Provincial Number of Boiler
 Date Inspected Aug 20/42 Report Number 114
 Location of Boiler Indian School Brandon
 Owner or Agent Dept of Indian Affairs
 Address Winnipeg
 Type of Boiler Vert Horse Power 7
 Name of Manufacturer Vert Year Built
 Manufacturer's Number no record Owner's Number
 Length 6 Diameter 2 1/2
 Hydrostatic Pressure Applied 40 Pressure Allowed
 Name and Cert. No. of Engineers in Charge

Safety Valves Water Column

Blow down Gauges

Re inspection of report No 77
Hydrostatic pressure applied and tank head found to be deteriorated, and head will need to be renewed, otherwise the boiler is in good condition

Certificate will be issued on completion of work and payment of fee.

Amount of fee \$ no charge

PLEASE MAKE ALL MONEY ORDERS AND CHEQUES PAYABLE TO
 DEPARTMENT OF LABOUR, LEGISLATIVE BUILDINGS, WINNIPEG.
 (ONLY CHEQUES MARKED BY BANK ACCEPTED.)

Inspector Woodie



Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VE
PO
GO

Report of Boiler Inspection

Provincial Number of Boiler.....
 Date Inspected Aug 8/42 Report Number 77
 Location of Boiler Indian School Brandon
 Owner or Agent Dept of Indian Affairs
 Address Winnipeg
 Type of Boiler Port Horse Power 7
 Name of Manufacturer No record Year Built

Manufacturer's Number

Length 6 Diameter 28
 Hydrostatic Pressure Applied Internal Pressure Allowed 30
 Name and Cert. No. of Engineers in Charge.....

Safety Valves Good Water Column Nil
 Blow down 11 Gauges 0/1

Good Condition

Certificate will be issued on completion of work and payment of fee.

Amount of fee \$ 3.00

PLEASE MAKE ALL MONEY ORDERS AND CHEQUES PAYABLE TO DEPARTMENT OF LABOUR, LEGISLATIVE BUILDINGS, WINNIPEG. (ONLY CHEQUES MARKED BY BANK ACCEPTED.)

Inspector E. Moodie



Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VEI
P00
CO

Report of Boiler Inspection

Provincial Number of Boiler.....
 Date Inspected Aug 8/42 Report Number 75
 Location of Boiler Indian School Brandon
 Owner or Agent Dept. of Indian Affairs
 Address Winnipeg
 Type of Boiler Firebox Horse Power 30
 Name of Manufacturer R. Bell Year Built.....
 Manufacturer's Number..... Owner's Number 1
 Length 9 Diameter 5 1/2
 Hydrostatic Pressure Applied Internal Pressure Allowed 30
 Name and Cert. No. of Engineers in Charge.....

Safety Valves Good Water Column Good

Blow down " Gauges "

1 nipple from boiler to return line to be renewed
1 Check valve on boiler feed line to be renewed
otherwise in Good Condition

Certificate will be issued on completion of work and payment of fee.

Amount of fee \$ 3.00

PLEASE MAKE ALL MONEY ORDERS AND CHEQUES PAYABLE TO DEPARTMENT OF LABOUR, LEGISLATIVE BUILDINGS, WINNIPEG. (ONLY CHEQUES MARKED BY BANK ACCEPTED.)

Inspector E. Moodie



Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VA
PO
CC

Report of Boiler Inspection

Provincial Number of Boiler.....
 Date Inspected Aug 8/42 Report Number 76
 Location of Boiler Indian School
 Owner or Agent Dept of Indian Affairs
 Address Winnipeg
 Type of Boiler Fuelbox Horse Power 30
 Name of Manufacturer B. Bell Year Built.....
 Manufacturer's Number..... Owner's Number 2
 Length 9 Diameter 5 1/4
 Hydrostatic Pressure Applied Internal Pressure Allowed 30
 Name and Cert. No. of Engineers in Charge.....

Safety Valves Good Water Column Good
 Blow down..... Gauges.....

- 1) Rubble from boiler to return line to be renewed
- 2) Boiler to be thoroughly washed out otherwise in Good Condition

Certificate will be issued on completion of work and payment of fee.

Amount of fee \$ 3.11

PLEASE MAKE ALL MONEY ORDERS AND CHEQUES PAYABLE TO DEPARTMENT OF LABOUR, LEGISLATIVE BUILDINGS, WINNIPEG. (ONLY CHEQUES MARKED BY BANK ACCEPTED.)

Inspector Moodie



Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES


ARCHIVES PUBLIQUES

CANADA

VE
PO
CO

133-0-5
Indian Residential School

PHONE 2838



REV. R. T. CHAPIN. B.A.
PRINCIPAL

[Handwritten signature]

Brandon, Man., August 26, 1942.



The Secretary,
Dept. of Mines & Resources,
Indian Affairs Branch,
Ottawa, Ont.

Dear Sir:

I am enclosing the reports of the Boiler Inspector. As you can see there is considerable work involved. The Inspector had Mr. Yates of Yates & Neale, plumbers, and also a Boiler Maker out here, to look over the work with him. Their conclusion was that either a new boiler would need to be installed, or the head of the present one replaced. They thought it might be possible to secure a used boiler in good condition that would not cost any more then putting a head in the present boiler. Mr Yates and Mr. Moodie were going to see if they could locate one and let me know. I will report further to you as soon as I get definite word. In the meantime may we have permission to have the other work done by Yates & Neale?

Yours truly,

[Handwritten signature: R.T. Chapin]

RTC/TS

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

Ottawa, August 29, 1942.

Re: Boiler repairs,
Brandon Indian Residential School

Dear Mr. Chapin:

I have for acknowledgment your letter of the 26th instant and also reports on the condition of the boiler at the Brandon school, attached thereto.

It is my hope that we may be able to avoid the necessity of installing a new boiler at this time. We have recently been informed by the Purchasing Division that it is becoming increasingly difficult to secure such supplies. If a used boiler in fairly good condition could be secured, such a boiler, no doubt, would meet your needs for the war period at least. In the meantime you are authorized to have the other repairs undertaken by Yates & Neale.

Yours truly,

R. A. Hoey,
Supt. of Welfare & Training.

Reverend R. T. Chapin, B.A.,
Principal,
Indian Residential School,
Brandon, Manitoba.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

332 LEGISLATIVE BUILDING

WINNIPEG, MAN., August 12, 1942.

Dept. of Indian Affairs,

Dominion Government,

Winnipeg, Manitoba.

IN ACCOUNT
WITH

BUREAU OF LABOR

Indian School--Brandon

Sept. 10, 1941	To Boiler Inspection Report #355	\$3.00
Sept. 10, 1941	To Boiler Inspection Report #356	3.00
Sept. 10, 1941	To Boiler Inspection Report #357	3.00
Aug. 8, 1942	To Boiler Inspection Report #75	3.00
Aug. 8, 1942	To Boiler Inspection Report #76	3.00
Aug. 8, 1942	To Boiler Inspection Report #77	3.00
		<hr/>
		\$18.00
		<hr/>

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

PHONE 3399

231 TENTH STREET

NIGHT PHONE 3530 AND 3571

BRANDON, MAN., Aug 19 42

MR. Indian Industrial School.

Brandon.

Oil Burners
Water Softeners, Filters
Pipe Cutting, Boilers.

IN ACCOUNT WITH **JAYES, NEALE & CO.**
PLUMBERS and HEATING ENGINEERS
HIGH GRADE PLUMBING, HOT WATER, ATMOSPHERIC VAPOR
AND STEAM HEATING

Bath Room Accessories
Septic Tanks, Hydraulic
Rams, Stokers.

DATE	PARTICULARS	FOLIO	TIME AND MATERIAL	CR.	TOTAL
Aug 19	Fwd		50 10		
	2 - 1" Plugs		20		
	1 - Gauge Glass		20		
	2 - " " Washers		10		
	3# - Trade Packing		1 50		
	3 - 2 1/2 x 5/8 Bolts		24		
	1/2 Ball Candle Wicking.		15		
	1 - 1 1/2 Gasket		10		
	1 - 1/2" #7 Globe Valve		3 65		
	1 - 1/2" S/C Valve		3 35		
	3 - 1/2" Nipps Gal		45		
	1 - 1/2" Gasket		05		
	1 - Grate for Cottage Boiler		3 75		
					63 84

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

PHONE 3399

231 TENTH STREET

NIGHT PHONE 3530 AND 3571

BRANDON, MAN., Aug 19 42

MR. Indian Industrial School,

Brandon.

Oil Burners
Water Softeners, Filters
Pipe Cutting, Boilers.

IN ACCOUNT WITH **JATES, NEALE & CO.**
PLUMBERS and HEATING ENGINEERS
HIGH GRADE PLUMBING, HOT WATER, ATMOSPHERIC VAPOR
AND STEAM HEATING

Bath Room Accessories
Septic Tanks, Hydraulic
Rams, Stokers.

DATE	PARTICULARS	FOLIO	TIME AND MATERIAL	CR.	TOTAL
Aug 10	1 - 6x4 Hand Hole Gaskets		45		
	5 - 2x3 " " "		1 75		
	4#- Trade Packing		2 00		
	To Cleaning Urinal Wastes, drill & tap out for Strainer & repair				
	Gauge Cox Mounting M&H 6hrs	2.10	12 60		
	1 - Gauge Glass		20		
	1 - 1/8 Pet Cox		35		
	1 - C.P. Strainer & 6 Brass Bolts		75		
18	To Cleaning Boiler & Heaters M&H 6	2.10	12 60		
19	" " " and				
	renew Returns. M&H 8hrs	2.10	16 80		
	2 - 2 1/2 Ells		1 40		
	2 - 2 1/2 Nipps		90		
	1 - 3" Plug		30		
	Fwd.		50 10		

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES ARCHIVES PUBLIQUES
CANADA

VERY POOR COPY

133-0-5
Indian Residential School


PHONE 2838



REV. R. T. CHAPIN. B.A.
PRINCIPAL

Brandon, Man., September 11/42...

The Secretary
Dept. of Mines and Resources,
Indian Affairs Branch,
Ottawa, Ont.



Dear Sir:--

I am enclosing Voucher #16 as per authority of your letter August 29 133 - 0 - 5. Part of one item is not for boiler repairs, Namely that referring to cleaning urinal wastes. For some-time we had been having difficulty with one drain and were unable to get it clear, so when the plumbers were here we had them put it in order. I trust this will be satisfactory.

Yates, Neale & Co. were able to secure and put in a ^{shape} used boiler of about the same dimensions as that which we had. They are installing this and will forward the account when completed.

Yours truly,

R. T. Chapin

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

PHONE 3399

231 TENTH STREET

NIGHT PHONE 3530 AND 3571

BRANDON, MAN., Aug 19 42

MR. Indian Industrial School.

Brandon.

Oil Burners
Water Softeners, Filters
Pipe Cutting, Boilers.

IN ACCOUNT WITH **JATES, NEALE & CO.**
PLUMBERS and HEATING ENGINEERS
HIGH GRADE PLUMBING, HOT WATER, ATMOSPHERIC VAPOR
AND STEAM HEATING

Bath Room Accessories
Septic Tanks, Hydraulic
Rams, Stokers.

DATE	PARTICULARS	FOLIO	TIME AND MATERIAL	CR.	TOTAL
Aug 19	Pwd		50 10		
	2 - 1" Plugs		20		
	1 - Gauge Glass		20		
	2 - " " Washers		10		
	3# - Trade Packing		1 50		
	3 - 2 1/2 x 5/8 Bolts		24		
	1/2 Ball Candle Wicking.		15		
	1 - 1 1/2 Gasket		10		
	1 - 1/2" #7 Globe Valve		3 65		
	1 - 1/2" S/C Valve		3 35		
	3 - 1/2" Nipples Gal		45		
	1 - 1/2" Gasket		05		
	1 - Grate for Cottage Boiler		3 75		
					63 84

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

PHONE 3399

231 TENTH STREET

133-0-5

NIGHT PHONE 3530 AND 3571

BRANDON, MAN.,

Aug

19 42

MR. Indian Industrial School.

Brandon.

Oil Burners
Water Softeners, Filters
Pipe Cutting, Boilers.

IN ACCOUNT WITH **JATES, NEALE & CO.**
PLUMBERS and HEATING ENGINEERS
HIGH GRADE PLUMBING, HOT WATER, ATMOSPHERIC VAPOR
AND STEAM HEATING

Bath Room Accessories
Septic Tanks, Hydraulic
Rams, Stokers.

DATE	PARTICULARS	FOLIO	TIME AND MATERIAL	CR.	TOTAL
Aug 10	1 - 6x4 Hand Hole Gaskets		45		
	5 - 2x3 " " "		1 75		
	4/- Trade Packing		2 00		
	To Cleaning Urinal Wastes, drill & tap out for Strainer & repair Gauge Cox Mounting MAH 6hrs	2.10	12 60		
	1 - Gauge Glass		20		
	1 - 1/8 Pet Cox		35		
	1 - C.P. Strainer & 6 Brass Bolts		75		
18	To Cleaning Boiler & Heaters MAH 6	2.10	12 60		
19	" " " and renew Returns. MAH 8hrs	2.10	16 80		
	2 - 2 1/2 Elbs		1 40		
	2 - 2 1/2 Nipps		90		
	1 - 3" Plug		30		
	Fwd.		50 10		

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY POOR COPY

133-0-5

Indian Residential School

PHONE 2838

School



REV. R. T. CHAPIN, B.A.
PRINCIPAL

Brandon, Man., September 24, 1942



The Secretary,
Dept. of Mines & Resources,
Indian Affairs Branch,
Ottawa, Ont.

Dear Sir:--

I am enclosing Voucher #18 covering
Yates, Neale & Co., for the used boiler which they
put in shape and installed. This has been tested
out and is giving satisfactory service.

Yours truly,

R. T. Chapin

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

*VERY
POOR
COPY*

Ottawa, September 29, 1942.

Memorandum:DEPARTMENTAL PURCHASING AGENT.

I am enclosing account covering used boiler installed at the Brandon Indian Residential School. The repairs required to the old boiler at the school would have amounted to more than the cost of the used boiler. It would be appreciated, therefore, if you would issue purchase order for \$178.06, so that the account may be paid. The coding is as follows:-

576 - 76-12-422 - Nat. Alloc. Sym. 17-20

R. A. Hoey,
Supt. of Welfare and Training.

M.H.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

FOR INFORMATION OF MR. HOEY

ADDRESS REPLY TO
PURCHASING DIVISION

Records File



CANADA
DEPARTMENT
OF
MINES AND RESOURCES
GENERAL ADMINISTRATIVE OFFICES

133/0/5

PLEASE REPLY TO
Man.



OTTAWA

October 1, 1942.

Dear Sirs,-

In reference to your account of the 8th ultimo, for supplying and installing boiler and accessories at the Brandon Indian Residential School, you will please advise as to the exact size and capacity of the Vertical steam boiler supplied. This information is requested for our assistance in arranging for payment of your account.

Yours very truly,

[Signature]

Departmental Purchasing Agent.

Messrs. Yates, Neale & Co.,
231 Tenth Street,
Brandon, Man.

WDMV/HC

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

*VERY
POOR
COPY*

PHONE 3399

231 TENTH STREET

NIGHT PHONE 3530 AND 3571

BRANDON, MAN., Sept 19 42

-MR. Indian Industrial School.

Brandon.

Oil Burners
Water Softeners, Filters
Pipe Cutting, Boilers.

IN ACCOUNT WITH **JAYES, NEALE & CO.**
PLUMBERS and HEATING ENGINEERS
HIGH GRADE PLUMBING, HOT WATER, ATMOSPHERIC VAPOR
AND STEAM HEATING

Bath Room Accessories
Septic Tanks, Hydraulic
Rams, Stokers.

DATE	PARTICULARS	FOLIO	TIME AND MATERIAL	CR.	TOTAL
Sep 7	To installing Vert Boiler M&H 8hrs	2.10	16 80		
8	" " " " 6 "	"	12 60		
	2 - 1½ Nipples	15	30		
	1 - 1½ Ell		25		
	1 - 1½ Gasket		10		
	2'- ¾" Pipe B	12	24		
	2 - ¾" Ells "	15	30		
	1 - ¾" Nipple"		10		
	2'-6" - ¾" Pipe Gal	15	37		
	3 - ¾" Ells "	20	60		
	4 - ¾" Nipples "	10	40		
	1 - 1x½ Bush B		10		
	1 - ¾" T Gal		25		
	1 - ¾" Union "		45		
	1 - ¾" Gauge Glass		20		
	1 - Vert Steam Boiler		145 00		
	Boiler Inspection Certificate #130				
					178 06

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

DEPARTMENT OF MINES AND RESOURCES

Order No 14839

RECEIPT FORM

This order number to appear on all packages and invoices

File No. 15-3 Man.

Yates, Neale and Company,

Ottawa, October 8, 1942. 19

251 - 10th St., Brandon, Man.

Supplies mentioned hereunder have been received and found satisfactory with exception of those listed under "Remarks".

invoice received -

QUANTITY	DESCRIPTION	UNIT	TOTAL
	Emergency purchase - supplying and installing in the Brandon Indian Residential School -		
1 only	Vertical steam boiler, diameter 30" height 6' H.P. 10 Tubes 44 - 2" Heating surface 100 sq.ft. Weight - 1400 lbs.		\$145.00
	Boiler inspection certificate #130	No charge	
	Steamfitting accessories		3.66
	Installation charges		23.40
			<u>\$172.06</u>
	As per invoice of Sept., 1942. " " voucher No. 18		

Noted
[Signature]

Prices F.O.B. as per your of

Shipping Instructions *mm* already received

Vote 76 Primary ~~10-691~~ 10-691 Date to be delivered:

Encumbrance No. 838 already received -

Freight or Express charges paid

Remarks: (Report shortages, if any)

Branch TO BE RETURNED TO HEAD OF BRANCH Date Signature of Receiving Officer

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY POOR COPY

Ottawa, September 29, 1942.

Memorandum:

DEPARTMENTAL PURCHASING AGENT.

I am enclosing account covering used boiler installed at the Brandon Indian Residential School. The repairs required to the old boiler at the school would have amounted to more than the cost of the used boiler. It would be appreciated, therefore, if you would issue purchase order for \$178.06, so that the account may be paid. The coding is as follows:-

576 - 76-12-422 - Nat. Alloc. Sym. 17-20

R. A. Hoey,
Supt. of Welfare and Training.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 7)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY