

# DEPARTMENT OF MINES AND RESOURCES

## PURCHASE ORDER

NO. 16979

THIS ORDER NO. TO APPEAR ON  
ALL PACKAGES AND INVOICES.

WIN/OMD

OTTAWA Feb. 20/46

FILE NO. 15-3 Ont.

TO **McClary's Plumbers and Steamfitters,**  
**604 Bay Street,**  
**Sault Ste. Marie, Ont.**

PLEASE FURNISH THE FOLLOWING MATERIALS AND CHARGE TO THE DEPARTMENT OF MINES AND RESOURCES.

SHIP TO

F.O.B.

QUOTATION OF

RENDER A SEPARATE INVOICE FOR EACH ORDER AND SEND

COPIES AFTER SHIPMENT

TO

*W.B. 7*

QUANTITY	DESCRIPTION	UNIT	TOTAL
	Material and labour supplied Shingauk Indian Residential School, Sault Ste. Marie, Ont., in connection with the installation of a larger reducing valve on cold water inlet -		\$125.01
	As per Invoice of February, 1947. " Voucher No. 181, dated Feb. 11, 1947.		

*Passed  
26/2/47*



VOTE	PRIMARY	OBJECT	ENCUMB. NO.	DELIVERY REQUIRED BY
75	10	001		already received.

CERTIFIED IN ACCORDANCE WITH SECTION 29  
OF THE CONSOLIDATED REVENUE AND AUDIT  
ACT 1931.

FOR COMPTROLLER OF THE TREASURY.

PURCHASING AGENT

R 2622

TO BE RETURNED TO HEAD OF BRANCH

SEE REVERSE SIDE

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



**McClary's**

PHONE 1978

**Plumbers and Steamfitters**

ACCOUNT NO.

LETTER	FOLIO

664 BAY STREET

SAULT STE. MARIE, ONT.

194

7

SOLD TO

*Indian Agent*  
*Post Office Bldg. Soo Ont.*

Accounts due when rendered

Interest charged on all overdue accounts

Contracts Taken on Large or Small Jobs

DATE	ARTICLES	FOLIO	CREDIT AMOUNT	DEBIT AMOUNT	TOTAL
<i>Jan 31/</i>	<i>Work at Thompson's Home</i>	<i>At Home</i>		<i>7.00</i>	
	<i>6 Hrs. Labor</i>			<i>4.50</i>	
	<i>2-2" Gate Valves</i>			<i>1.40</i>	
	<i>2-2" Gal- Elbows</i>			<i>1.25</i>	
	<i>1-2" " Union</i>			<i>.30</i>	
	<i>1-2" x 3" Tee</i>			<i>1.25</i>	
	<i>6-2" Hot " "</i>			<i>10.00</i>	
	<i>1-2" Reducing Valve</i>			<i>12.79</i>	

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

**PUBLIC ARCHIVES**  
**ARCHIVES PUBLIQUES**  
**CANADA**



**Form No. I.A. 506A**  
R. 2753

CHEQUE No. ....

DATE .....

1947	DATE	SERVICE	AMOUNT
Jan.	31	To Material and labour supplied the Shingwauk Indian Residential School for the purpose of installation of a larger reducing valve on the cold water inlet, as per statement attached —	\$128.91
			\$128.91

469  
26/3/47  
Voucher in duplicate detached for Accountant to use

EX'D.

Department of Mines  
FEB 14 1947

I HEREBY CERTIFY that this Voucher is correct, that the material has been supplied, the work performed and that the charges are fair and just, also that the expenditure has been incurred legitimately and that each item of the same is a fair and just charge against the Government of Canada. This expenditure was authorized by Departmental Letter, File No. 13-0-5(WT1) dated Oct. 23, 1946.

VOUCHER No. 181

DATE Feb. 11, 1947. Agent

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



13-0-5

DEPARTMENT OF MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH

Form No. I.A. 506A  
R. 2753

TREASURY ONLY

CHEQUE No. ....

DATE .....


Pay to..... Robinson Electric,

Address..... 135 Pine Street,

Sault Ste. Marie, Ontario.

1947 DATE	SERVICE	AMOUNT
Jan. 31	To Charges for urgent repairs made to Vacuum pump at the Shingwauk Indian Residential School, as per statement attached --	\$2.80
Feb. 28	To Charges for repairs made to Vacuum Pump in connection with heating system at the Shingwauk Indian Residential School, as per statement attached --	\$4.55
		\$7.35

469  
17/13/47  
Duplicate for file  
Voucher in duplicate detached  
for Accountant to pay.



I HEREBY CERTIFY that this Voucher is correct, that the material has been supplied, the work performed and that the charges are fair and just, also that the expenditure has been incurred legitimately and that each item of the same is a fair and just charge against the Government of Canada. This expenditure was authorized by Departmental Letter, File No. .... dated .....

VOUCHER No. 327

DATE March 13, 1947.

Agent

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



★ BRANCH STORE 8 WELLINGTON E.

# GREENWOOD ELECTRIC & HARDWARE ★ *Two Stores*

HOUSEHOLD HARDWARE, PAINT AND VARNISH ★ ELECTRICAL CONTRACTING, SUPPLIES AND APPLIANCES

MAIN STORE  
708 QUEEN STREET E.  
SAULT STE. MARIE, ONT.

April 5th, 1947

Shingwauk Home  
City.

Dear Sir:

We herewith submit our tender for supplying  
ind installing 12 only Wheeler Fluorescent  
48" 2 tube Fixtures for the sum of Three Hundred  
and twenty-four dollars. (\$324.00)

Thanking you, we remain,

Yours truly,

GREENWOOD ELECTRIC AND HDWE.

per. *T. C. Greenwood*

*This is a reduction  
in price from last  
year which was \$4.20*

*See P.O. 8629  
Feb 24 46  
J.P.*

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



OFFICE OF THE  
AGENT  
Sault Ste. Marie Ont.

CANADA  
DEPARTMENT  
OF  
MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH

13-0-5  
PLEASE QUOTE  
FILE 2-39-3-2

*Mr. R.P.G. Laurence*  
April 10th. 1947.

INDIAN AFFAIRS BRANCH DEPARTMENT OF MINES AND RESOURCES.

In accordance with instructions contained in Departmental letter file 13-0-5 (WT.1) dated January 14th. 1947, I am enclosing a new quotation for the installation of 12 fluorescent lighting fixtures, at the Shingwauk Indian Residential School, Sault Ste. Marie Ontario.

*R.P.G. Laurence*

R.P.G. Laurence  
Indian Agent  
Sault Ste. Marie Ontario.




Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA




13-0-5 (WT 1)

  
Ottawa, April 15th, 1947.

Mr. R.P.G. Laurence, Indian Agent,  
Sault Ste. Marie, Ontario.

We have your letter of the 10th instant with reference to installing additional fluorescent lighting fixtures at the Shingwauk Residential School.

Mr. Doucet intends to visit this school when he is in your section of the country next week and will discuss this matter further with you at that time.

  
Philip Phelan,  
Chief, Training Division.

PP/MGD

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



Mr. Hoey

RT

13-0-5

I.A.1380-4

Re your memoranda of August 13, and December 7, 1946, and for your information. Recommendations concurred in. Will you kindly advise us of your wishes in due course.  
15/4/47 J.M.W. J.M.W.

April 10, 1947.

MEMORANDUM:

Re: Shingauk Home.  
Sault Ste. Marie, Ontario.

An inspection of the mechanical services at the above was carried out by an officer from this Service on February 24th to 26th inclusive, and the results are summarized as follows:-

The boiler plant and piping distribution system is of relatively good design and with several exceptions was installed according to the original plans. Most of the equipment appeared to be in good condition, but several items are in need of repair and some additional equipment is necessary if the plant is to function with normal efficiency.

Complaints received indicated a lack of heat in the Class Rooms, Auditorium and Sewing Room. Complaints were also received concerning the lack of domestic hot water.


Much of the heating difficulty can be overcome by re-locating the thermostat which controls the entire building, along with several additional radiators located where required.

The original design of the domestic hot water heating equipment was not followed out in its entirety, and while the storage tank is large enough, the heater capacity is definitely inadequate. An undersized coal fired domestic hot water heater is now in use and this unit is too small as well as being in poor condition. The present low pressure heating boilers have ample capacity to heat the building as well as to heat the domestic hot water, if one stoker was installed.

The domestic hot and cold water piping is all undersized, and most of it is buried under the basement slab in cinder fill which has been the cause of failures due to rapid corrosion. (Incidentally, the main building return from the heating system is also buried under the slab.) All domestic hot and cold risers are undersized and none of this piping is insulated.

While no immediate emergency exists, this buried piping should be replaced and the building return housed in a trench, to prevent further interruptions to these services. A careful analysis of the requirements indicate that the following exceptions are necessary to bring this plant up to a reasonably efficient standard.

J.M. Wardle, Esq.,  
Director,  
Surveys and Engineering Branch,  
Department of Mines and Resources,  
OTTAWA, Ontario.



(over)

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



1. Install one stoker to serve one of the present low pressure heating boilers.
2. Provide an indirect steam fed heater of sufficient capacity to adequately handle the domestic hot water requirements.
3. Replace all domestic hot and cold water mains and most of the risers, and properly insulate same.
4. Replace that portion of main building return now buried under basement slab and house new line in concrete trench.
5. Move building thermostat to more favourable location.
6. Add several new radiators in rooms which are now under heated.
7. Provide new Jacket heater for summer service only and arrange piping to this end.
8. Arrange with manufacturer to service existing vacuum pump and controls.

It is estimated that the above operations will cost in the neighborhood of \$5000.00

This Service now has data from which plans and specifications could be prepared, but we are in no position at present to advise when such work could be undertaken.

The matter of ice formation on the roof was discussed with the Principal. It was pointed out that no satisfactory method of preventing such conditions could be suggested, and the school authorities should arrange with the Indian Agent to have men remove accumulations of snow before ice had a chance to form. The Principal accepted the idea that it was part of the normal maintenance which should be carried out under his direction.

*J. A. Mills*

Chief Engineer.

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



13-0-5 (WT 1)

*EXD.*

Ottawa, April 17th, 1947.

Memorandum:

DIRECTOR OF SURVEYS & ENGINEERING BRANCH

Re: Shingwauk Home, Sault Ste. Marie, Ontario.

We have your memorandum of April 10th with reference to certain improvements that might be made at the above mentioned school.

It is noted that your Branch is not in a position to advise when the work could be undertaken.

If possible, you could let us know if you consider the work so urgent that we should endeavour to obtain the balance of the amount required in the supplementary estimates, or if the amounts should be included in the main estimates for the fiscal year 1948-49.

*PP*  
*MGD*

*W. H. H. H.*  
Director.

PP/MGD

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



Shingwauk I.R.S.  
Sault Ste.Marie, Ont.


April 24.1947

Mr R.P.G.Laurence,  
Indian Agent.  
Sault Ste.Marie.

Dear Sir:

When Mr.Hargeaves,the engineer sent by the Department to report on Heating System,was here last month,He told me that he should request The Dunham Vacuum Heating System to send a mechanic to overhaul the Dunham vacuum pump in use here which is not doing its job. Mr Hargeaves wanted this work done before the furnaces are shut down. So far no word has been received and the pump is getting worse. This is urgent as there is no one locally who can service these vacuum pumps. Soon the pump may give out entirely.

Yours very truly,



Principal.

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA




13-0-5

OFFICE OF THE  
INDIAN AGENT  
S.S. Marie Ont.

  
CANADA  
DEPARTMENT  
OF  
MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH


PLEASE QUOTE  
FILE 2-39-3-2

  
April 24th. 1947.

INDIAN AFFAIRS BRANCH DEPARTMENT OF MINES AND RESOURCES.

Enclosed please find letter received from the Principal of the Shingwauk Indian Residential School, Sault Ste. Marie Ontario, regarding the Dunham vacuum pump at the school, which is self explanatory.

Kindly advise me regarding this matter as soon as possible.



R.P.G. Laurence  
Indian Agent  
Sault Ste. Marie Ontario.



Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



13-0-5 (WT)

~~EX-13~~

Ottawa, April 26th, 1947.

Memorandum:

DIRECTOR OF SURVEYS AND ENGINEERING BRANCH

Re: Shingwauk Home, Sault Ste. Marie, Ontario.

Further to our memorandum of April 17th, we have now received a copy of a letter from the Principal of this school, which reads as follows:

"When Mr. Hargeaves, the engineer sent by the Department to report on Heating System was here last month, he told me that he should request the Dunham Vacuum Heating System to send a mechanic to overhaul the Dunham vacuum pump in use here which is not doing its job. Mr. Hargeaves wanted this work done before the furnaces are shut down. So far no word has been received and the pump is getting worse. This is urgent as there is no one locally who can service these vacuum pumps. Soon the pump may give out entirely."

Could you please advise what action you intend to take in this regard.

*[Handwritten initials]*

BFN/MGD

c/c to Indian Agent Laurence.

*[Handwritten signature]*  
Director.

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



FL

13-0-5

I.A.1380-4

Mr. Hoey

For your information, please.  
Mr. Mills' opinion concurred  
in. Will you kindly advise if you  
wish this work to be done during the  
current fiscal year.

April 22nd, 1947.

26/4/47

Memorandum

J.M.W.

Re: Shingwauk Home-Sault Ste. Marie, Ont.

In connection with Mr. Hoey's memorandum of April  
17th, 1947, and your notations of the 19th instant thereon,  
you are advised as follows:

While it can be fairly stated that no immediate  
emergency exists at the above, it is also true that the dom-  
estic hot and cold water piping now buried under the basement  
slab, is in a state of progressive deterioration, and the need  
for continual repairs can be expected. The same situation on  
other residential schools has resulted in disorganization of  
the school routine. Should an emergency arise, the repairs  
would involve cutting the concrete slab and patching worn  
piping, which in the past has been carried out by the School  
staff, resulting in considerable neglect to boiler room duties.

If requested by Indian Affairs to prepare plans and  
specifications for the necessary revisions as outlined in our  
memorandum of April 10th, 1947, we consider they could be  
issued for tendering about May 30th next, which would enable  
the work to be carried out before the beginning of the fall  
term.

It is felt that this work should be carried out  
during the current fiscal year if funds can be made available.



*J. A. Mills*  
Chief Engineer.

J.M. Wardle, Esq.,  
Director,  
Surveys and Engineering Branch,  
Department of Mines and Resources,  
O t t a w a, Ont.



Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



*END.*

Ottawa, April 28th, 1947.

Memorandum:

DIRECTOR OF SURVEYS & ENGINEERING BRANCH

Re: Shingwauk Home, Sault Ste. Marie, Ont.

We have your memorandum of April 22nd in further reference to your memorandum of April 17th.

We did not include in the current year's appropriation an amount sufficient to carry out all the repairs mentioned in your memorandum of 10th. Under the circumstances, it will be necessary to defer the proposed work at the Shingwauk Home.

*PP*  
*MGD*

*[Signature]*  
Director

PP/MGD

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



FAL

13-0-5

I.A.1380-4

Mr. Hoey

For your information and  
attention, please.

3/5/47

J.M.W./J.M.W.

P.

May 1st, 1947.



MEMORANDUM

Re: Shingwauk Home,  
Sault Ste. Marie, Ont.

In connection with Mr. Hoey's memorandum of April 26th, 1947, and your notation of the 29th instant thereon, regarding the above, you are advised as follows:-

When the mechanical services were inspected (February 24th-26th) the condition of the vacuum pump was noted. It was felt at that time following a close check, that the pump would function reasonably well enough for the balance of the heating season. Included in our memorandum of April 10th, 1947, is a clause recommending that the pump be serviced by the manufacturer at the same time as the proposed revisions to the mechanical services are carried out.

This pump has not had shop service since it was installed, and as already stated, no immediate concern was felt when our inspection was made. This is a condition that applies to most of the residential schools and there is no doubt that some elements such as packing, joints, etc., are in need of attention. Since the Principal's letter indicates some concern, we feel that Indian Affairs should authorize the manufacturer to examine the pump and make what replacements are necessary as soon as possible. This would avoid the risk of a breakdown.

The pump was manufactured by the C.A. Dunham Co. Ltd. It was supplied by their local agent, who is located at 45 Rideau Street, Ottawa. Under the circumstances this firm might be contacted with the view of carrying out the work.

*J. T. Miller*

Chief Engineer.

J.M. Wardle, Esq.,  
Director,  
Surveys and Engineering Branch,  
Department of Mines and Resources,  
O t t a w a, Ont.



Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



13-0-5 (WT 1)

EXD.

Ottawa, May 10th, 1947.

Dear Sirs:-

In the Shingwauk Residential School at Sault Ste. Marie, Ontario, there is a vacuum pump which was supplied by your firm. One of our engineers has recently visited the school and states that this pump has not had shop service since it was installed and that there is no doubt that some elements, such as packing, joints, etc., are in need of attention.

Would it be possible for your firm to have some qualified man examine the pump and make the replacements necessary as soon as possible, or could you suggest the name of some firm in Sault Ste. Marie, Ontario, whom we could engage to do the necessary work.

Yours sincerely,



Bernard F. Neary  
Supt. of Welfare & Training.

C.A. Dunham, Co., Ltd.,  
45 Rideau Street,  
O t t a w a.

PP/MGD

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA




13-0-5

 **C. A. DUNHAM CO., LIMITED**  
1523 DAVENPORT RD. TORONTO, ONT. PHONE LOMBARD 1186

M A N U F A C T U R E R S     O F     H E A T I N G     E Q U I P M E N T

REPLY TO  
BRANCH SALES OFFICE No. 6  
404 PLAZA BLDG.  
OTTAWA, ONT.  
GEO. A. GRAY, MANAGER  
TELEPHONE 3-4391



Ottawa, Ontario.  
May 12, 1947.




Department of Mines and Resources,  
Welfare and Training Branch,  
Indian Affairs Branch,  
OTTAWA, Ont.

Re: 13-0-5 (WT-1)  
Shingwauk Residential School?Soo  
Attention Mr. B. F. Neary

Dear Sir:

This will acknowledge your letter of May 10 in connection with the above subject and would suggest you contact Mr. J. McLeod 125 Alexander St. Sault Ste. Marie as he has installed a number of Dunham Vacuum Pumps and is quite familiar with them, and feel that he could make any adjustments and repairs necessary.

Yours very truly,  
OTTAWA SALES OFFICE.

By   
GEO. A. GRAY

GAG:IK

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

**PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA**



*EXTD.*

Ottawa, May 14th, 1947.

Mr. R.P.G. Laurence, Indian Agent,  
Sault Ste. Marie, Ontario.

With reference to your letter of the 24th ultimo enclosing letter from the Principal of the Shingwauk Residential School, we understand that the vacuum pump requires overhauling.

The official of the Surveys and Engineering Branch who visited the school in February states that there is no doubt that some elements such as packing, joints, etc., are in need of attention.

*PP*

This pump was manufactured by the C.A. Dunham Co., Limited, and I am advised by them that we should employ Mr. J. McLeod, 125 Alexander St., Sault Ste. Marie to examine this pump. The Dunham firm states that he is quite familiar with their equipment and they believe he can make any adjustments and repairs necessary. You may make immediate arrangements to have him service this pump.

*[Signature]*  
Bernard F. Neary,  
Supt. of Welfare & Training.

PP/MGD

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



Shingwauk I.R.S.  
Sault Ste.Marie, Ont.

May 9.1947

Mr.R.P.G.Laurence,  
Indian Agent,  
Sault Ste.Marie, Ont.

Dear Sir:

Enclosed is account for Repairs to roof of School.  
During the winter storms a good number of shingles were blown  
off the school roof and others were loosened. Mr.Sundin has  
done work for us before which has proved satisfactory. I  
was fortunate in being able to get the work done as soon as  
the weather would allow and believe everything is now in good  
shape.

Yours very truly,

*Arthur W. Minshun*  
Principal.

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



INDIAN AFFAIRS BRANCH

TREASURY ONLY

CHEQUE No.....

DATE.....

Pay to.....A. Sundin.....

Address..... Queen Street E.,  
Sault Ste. Marie, Ont.

1947	DATE	SERVICE	AMOUNT
May	8	To Charge of repairing the roof of the Shingwauk Indian Residential School, as per statement attached --	\$79.50
<div style="border: 1px solid black; padding: 5px; width: fit-content;"> <p>AUDITED FOR PAYMENT MAY 20 1947 Treasury Office I. A. BRANCH</p> </div> <div style="text-align: center; margin-top: 20px;"> <p>469 79-15-167 TRIPPLICATE FOR FILE Voucher to duplicate detached for Amountant to bank</p> </div> <div style="text-align: right; margin-top: 20px;"> <p>Department of Mines &amp; Technical Surveys Indian Affairs Branch MAY 16 1947</p> </div>			
			\$79.50

I HEREBY CERTIFY that this Voucher is correct, that the material has been supplied, the work performed and that the charges are fair and just, also that the expenditure has been incurred legitimately and that each item of the same is a fair and just charge against the Government of Canada. This expenditure was authorized by Departmental

Letter, File No. .... dated .....

**FORM No. I.A. 506**

**Req. 2568**

VOUCHER No. 572

DATE..... May 13, 1947.

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



OF THE  
INDIAN AGENT

S.S. Marie Ont.



CANADA  
DEPARTMENT  
OF  
MINES AND RESOURCES  
INDIAN AFFAIRS BRANCH

13-0-5  
PLEASE QUOTE  
FILE 2-39-3-2

May 22nd. 1947.

INDIAN AFFAIRS BRANCH DEPARTMENT OF MINES AND RESOURCES.

I wish to acknowledge your letter file 13-0-5 (WT 1) dated May 14th. 1947, concerning the vacuum pump, manufactured by the C.A. Dunham Company Ltd., which is located in the Shingwauk Indian Residential School, Sault Ste. Marie Ontario.

As per instructions, the Principal of the above mentioned school, contacted Mr. J. McLeod, 125 Alexander Street, Sault Ste. Marie, and after examining the pump he stated that as he had never serviced that particular type of equipment, he advised Reverend Minchin to have a company representative do the work. Mr. McLeod stated that the only work he has done for the C.A. Dunham Company, was installation of new equipment.

As Reverend Minchin has advised this office that the fires will not be kept burning in the school furnaces much longer, kindly advise this office what steps should be taken to have the pump serviced, at your earliest convenience.



R.P.G. Laurence  
Indian Agent  
Sault Ste. Marie Ontario.

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



*EXD.*

Ottawa, May 28th, 1947.

Dear Sirs:-


On receipt of your letter of May 12th we instructed our Agent at Sault Ste. Marie to get in touch with Mr. J. McLeod. We have just received the following reply,-

" As per your instructions, the Principal of the above mentioned school contacted Mr. J. McLeod, 125 Alexander Street, Sault Ste. Marie, and after examining the pump he stated that as he had never serviced that particular type of equipment, he advised Reverend Minchin to have a company representative do the work. Mr. McLeod stated that the only work he has done for the C.A. Dunham Company, was installation of new equipment.

" As Reverend Minchin has advised this office that the fires will not be kept burning in the school furnaces much longer, kindly advise this office what steps should be taken to have the pump serviced, at your earliest convenience."

In view of the above, I would appreciate it if you would give the matter further consideration and let me know how we could have this pump serviced.

Yours sincerely,

  
Bernard F. Neary  
Supt. of Welfare & Training.

Messrs. C.A. Dunham Co.,  
404 Plaza Bldg.,  
O t t a w a.

PP/MGD

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



2-627

13-0-5 98 BANK ST

# THE SPORT SHOP

FRANK I. RITCHIE  
SPORTING GOODS & CLEVELAND BICYCLES

OTTAWA, ONT.,

MAY 27 1947  
194

Department of Mines & Resources

Room 503 Booth Bldg.,

order May 12, 1947.

Our order # 3-5-47

DATE	INVOICE	DEBITS	CREDITS	BALANCE
May 15	A 9275			
14	Playground Balls			
	@ \$ 1.80 Each	\$ 25 20		
2	Basket Balls			
	@ \$14.40 Each	28 80		
	C.P.X. Ppd. Voucher			
	ATT'D....	1 05		
		-----		\$ 55 05
				-----

AUDITED  
FOR PAYMENT  
To: Rev. A. E. Minchin, Principal,  
Shinwauk Indian Res. School,  
Sault Ste. Marie, Ont.....  
MAY 28 1947

Treasury Office  
I. A. BRANCH

NOTE: This order completed.

DUPLICATE FOR FILE  
Voucher in duplicate detached  
for Accountant to keep

"Ottawa's Most Popular Sports Centre"

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



13-0-5 (W T)

*EXD.*

Ottawa, June 5, 1947.

Mr. R.P.G. Laurence,  
Indian Agent, Sault Ste. Marie, Ontario.

Shingwauk Home - Vacuum pump

Immediately upon receipt of your letter 2-39-3-2 we contacted the local representative of the Dunham Company. He wrote at once to his head office concerning the sending of a representative to Sault Ste. Marie to carry out the necessary repairs. Unfortunately, due to pressure of work, this is impossible at the present time.

We have today been informed that the Company is fairly certain of the parts which will need replacement or repair. The representative has supplied me with the attached diagram. The sections of the pump outlined in red are to be removed and shipped to:

C. A. Dunham Company,  
1523 Davenport Road,  
Toronto, Ontario.

They should be labelled as being from the above school. It is suggested that you have Mr. McLeod remove these parts.

As soon as the replacements and repairs can be effected, the Company will send a representative to Sault Ste. Marie to assist in installing the parts and to check the other parts and test the whole apparatus.

Encl.

*B*  
Bernard F. Neary,  
Supt. of Welfare & Training.

BFN/EM

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



## DEPARTMENT OF MINES AND RESOURCES

OR/00

## PURCHASE ORDER 13-0-5

NO. 16821

THIS ORDER NO. TO APPEAR ON  
ALL PACKAGES AND INVOICES

OTTAWA

Feb. 15, 1947

FILE NO. 70236-15-6

TO Cochrane-Dunlop Hardware Ltd.,  
Sault Ste Marie, Ont.

PLEASE FURNISH THE FOLLOWING MATERIALS AND CHARGE TO THE DEPARTMENT OF MINES AND RESOURCES.

SHIP TO Rev. A. E. Minchin, Principal, Shingwauk Indian Residential School,  
Sault Ste Marie, Ont.

F.O.B. Sault Ste Marie, Ont.

QUOTATION OF

Feb. 11, 1947

RENDER A SEPARATE INVOICE FOR EACH ORDER AND SEND 4 COPIES AFTER SHIPMENT

TO

The Consignee

QUANTITY	DESCRIPTION	UNIT	TOTAL
15 gals	Grey Truscon concrete floor dressing -	4.70	70.50
10 "	White Martin-Senour flat Nu-tone paint -	3.95	39.50
5 "	Green " Gloss paint -	4.35	21.75
2 "	Grey " "	4.35	8.70
			\$140.45
			sales tax exempt

VOTE	PRIMARY	OBJECT	ENCUMB. NO.
76	10	691	

DELIVERY REQUIRED BY

as soon as possible

CERTIFIED IN ACCORDANCE WITH SECTION 29  
OF THE CONSOLIDATED REVENUE AND AUDIT  
ACT 1931.

FOR COMPTROLLER OF THE TREASURY.

PURCHASING AGENT

R 2622

TO BE RETURNED TO HEAD OF BRANCH

SEE REVERSE SIDE

Indian Affairs. (RC 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



SAULT STE MARIE

NORTH BAY

SUDBURY

FORT WILLIAM

TORONTO

GERALDTON

COPPER CLIFF

HUDSON

## COCHRANE-DUNLOP HARDWARE LIMITED

WHOLESALE HARDWARE

Department of Mines & Resources,  
c/o Rev. A. E. Minchin,  
Queen Street East,  
CITY.

Sault Ste. Marie, Ontario,  
May 31, 1947.

ORDER No. 16321  
YOUR ORDER No.  
TERMS

INVOICE No.  
INVOICE DATE  
SHIPPED VIA  
F. O. B.

QUANTITY	DESCRIPTION	PRICE	GROSS	NET TOTAL
7	Cans Truscon Concrete Floor Dressing 17 1/2 gal.	gal. 4.70	82.25	
2	gals. Grey Coneritene Floor Dressing	gal. 4.70	9.40	
10	gal. White Neu Tone	gal. 3.95	39.50	
2	gal. Cream Neu-Hi Glos	gal. 4.35	21.75	
2	gal. Grey Gloss Paint	gal. 4.35	8.70	
			\$ 161.60	
			4.40	
			\$ 152.20	

*Corrected Invoice*  
*Arthur S. Minchin*  
*Presented - Sault Ste. Marie*

" SALES TAX RECEIPT "

COPLAND-CHATTERSON LIMITED, BRAMPTON, ONT. — 22445-15

Indian Affairs. (RC 1C, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA



13-0-5

TREASURY ONLY  
EXD

Cheque No. ....

DATE.....

Address 388 Queen Street E.,

Sault Ste. Marie, Ont.

DATE	SERVICE	AMOUNT
May 31 1947	To Paint supplied Shingwauk Indian Residential School, as per statement attached -- Purchase Order #16821; File No. 70236-15-6	\$152.20
	  	\$152.20

I HEREBY CERTIFY that this Voucher is correct, that the material has been supplied, the work performed and that the charges are fair and just, also that the expenditure has been incurred legitimately and that each item of the same is a fair and just charge against the Government of Canada. This expenditure was authorized by Departmental Letter, File No. 70236-15-6 dated Feb. 15, 1947

**FORM No. I.A. 506**

Reg. 2568

VOUCHER No. 676

*[Signature]* Agent

DATE June 13, 1947.

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

**PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA**



## DEPARTMENT OF MINES AND RESOURCES

INDIAN AFFAIRS BRANCH

TREASURY ONLY




CHEQUE No.....

DATE.....

Pay to Greenwood Electric & Hardware,

Address 708 Queen Street E.,

Sault Ste. Marie, Ontario.

1947	DATE	SERVICE	AMOUNT
May	31	To Repairs made to Electric stoves at the Shingwauk Indian Residential School, as per certified statement attached --	\$35.97
  			\$35.97

I HEREBY CERTIFY that this Voucher is correct, that the material has been supplied, the work performed and that the charges are fair and just, also that the expenditure has been incurred legitimately and that each item of the same is a fair and just charge against the Government of Canada. This expenditure was authorized by Departmental

Letter, File No. .... dated .....

**FORM No. I.A. 506**

**Req. 2568**

VOUCHER No. 838

DATE July 8, 1947.

Agent

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

**PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA**



13-0-5 (W T 1)

Ottawa, September 12, 1947.

G. A. Dunham Co., Ltd.,  
404 Plaza Building,  
Ottawa, Ontario.


Attention - Mr. G. A. Gray

With reference to our conversation a few days ago, this letter will authorize you to send a representative to Sault Ste. Marie, Ontario, to carry out necessary repairs to the heating system at the Shingwauk Indian Residential School.

This Department will be responsible for the expenses incurred in this regard.

We are writing to the school and as soon as the repairs reach Sault Ste. Marie we will be advised by wire. We will then immediately notify you.

Yours sincerely,

  
Philip Phelan,  
Chief, Training Division.

FP/EM

Indian Affairs. (RG 10, Volume 6213, file 469-5, part 8)

PUBLIC ARCHIVES  
ARCHIVES PUBLIQUES  
CANADA