

INSPECTOR OF INDIAN AGENCIES



CANADA
DEPARTMENT
OF
MINES AND RESOURCES

INDIAN AFFAIRS BRANCH

209-11 AU

133-0-5

W.H.

538 Dominion Public Bldg.
Winnipeg, Manitoba
December 3, 1946

Indian Affairs Branch
Department of Mines and Resources
Ottawa, Ontario

RE: Furnace for Brandon School -
Principal's home - File 133-0-(W.T.1)


I wrote Rev. Strapp concerning installing the furnace in his home and also asked that the account be certified by him and sent to this office. I quote his reply:

"Further to my letter of the 6th. Inst. I have received the accounts for the furnace and forwarded them to Ottawa, under voucher #22.

I am enclosing a copy of the account and of my covering letter to the Secretary.

I have received a communication from Dr. Dorey with a copy of a letter received from Mr. Neary. Mr. Neary is inclined to be rather critical of my action from an official point of view and I quite agree with him officially. However, personally I feel that I would have merited severe criticism had I not taken advantage of the opportunity to get a furnace when it was available as had we had to wait until another could have been ordered we could not have prevented damage to the water system. Another element that enters into the situation is the fact that I am entitled to a comfortable house to live in and had Ottawa taken as long to decide about the furnace as they have about our kitchen stove in the school kitchen, and the repairs to the hot water system and the boilers, I would be wondering where to find a place to live.

I hope that the matter will turn out to be not too serious and that the account will be paid."



A.G. Hamilton
A.G. Hamilton
Inspector of Indian Agencies
for Manitoba

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

INSPECTOR OF INDIAN AGENCIES



CANADA

DEPARTMENT
OF
MINES AND RESOURCES

133-0-5

INDIAN AFFAIRS BRANCH

209-11AU

538 Dominion Public Bldg
Winnipeg, Manitoba
December 3, 1946

Indian Affairs Branch
Department of Mines and Resources
Ottawa, Ontario

Re: Range for Brandon School.

I have just received the following letter from Rev. Strapp concerning this matter. You will note Rev. Strapp states a discount of 25% is being allowed on large models until the end of December.

On October 1, I recommended a new range be supplied.

"I had a traveller for Ashdowns in to see me yesterday and he asked me what was being done about the kitchen stove, at the same time he informed me that until the end of the year a discount of 25% was being allowed on the large model. This would bring the price down somewhere near that of the present stove in the kitchen."



A.G. Hamilton

A.G. Hamilton
Inspector of Indian Agencies
for Manitoba

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

REV. A. LLOYD SMITH, D.D.
CHAIRMAN

Board of Home Missions

The United Church of Canada

299 QUEEN ST. WEST
TORONTO 2 B. ONTARIO

133-0-5

REV. GEORGE DOREY, D.D.
SECRETARY

REV. MALCOLM C. MACDONALD, B.A.
ASSOCIATE SECRETARY

REV. JOHN R. LENG, B.A., B.D.
ASSISTANT SECRETARY

Handwritten initials

Attention: Colonel B.F. Neary

December 6th,
1 9 4 6.

Indian Affairs Branch,
Department of Mines and Resources,
O t t a w a, Ontario.

Dear Colonel Neary: Re: Brandon Residential School

I am advised by Mr. Strapp that the new stove for the kitchen is urgently needed, and I hope that you can get money to meet this need. In that connection, may I suggest that the Department consider the purchase of an Esso stove. It is more expensive to begin with than the ordinary type of stove, but it keeps the kitchen cool and conserves a great deal of fuel. It is sold by the J.H. Ashdown Company, who would give a discount of 25% if one were ordered before the end of the year.

Mr. Strapp asks me to urge that something be done, as they are in quite a fix in the kitchen.

Yours sincerely,

Handwritten signature: G. Dorey

GD.MLT



Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY POOR COPY

133-0-5 (W.T. 1)

AIRMAIL

Ottawa, 10 December 1946.


EBD.

Mr. A.G. Hamilton, Inspector of Indian Agencies,
WINNIPEG, Manitoba.

We have your letter of Dec. 3rd with reference to the range required at the Brandon Residential School. If you refer to your letter of Oct. 1 you will note that you stated that the purchase of a new range was not a necessity and consequently we advised you in official letter of Oct. 7th that funds would be provided in our appropriation for the fiscal year 1947-48.

In addition to your recent letter, we have also received a letter from the Secretary of the Board of Home Missions of the United Church of Canada urging the immediate purchase of a new kitchen range. In his letter it is suggested that we secure an Esso stove which is handled by the Ashdown Hardware Company.

Please let us have full particulars regarding the size of stove required. If possible let us have the catalogue number of the Esso stove which has been requested.

mm

Bernard F. Neary,
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

DEPARTMENT OF MINES AND RESOURCES

PURCHASE ORDER

NO. **15215**
THIS ORDER NO. TO APPEAR ON
ALL PACKAGES AND INVOICES.

OTTAWA **Dec. 9/46**

FILE NO. **15-2**

TO **McDowell & Deke,
115 Ninth St.,
Brandon, Man.**

PLEASE FURNISH THE FOLLOWING MATERIALS AND CHARGE TO THE DEPARTMENT OF MINES AND RESOURCES.

SHIP TO **Already received**

F.O.B.

QUOTATION OF

RENDER A SEPARATE INVOICE FOR EACH ORDER AND SEND COPIES AFTER SHIPMENT

TO **Already received**

QUANTITY	DESCRIPTION	UNIT	TOTAL
	To supplying and installing furnace in the Indian Residential School, Brandon, Man., Invoice dated Nov. 21/46 oucher No. 22.		\$526.10

WMV/HC

VOTE	PRIMARY	OBJECT	ENCUMB. NO.	DELIVERY REQUIRED BY
76	12	415		-----

CERTIFIED IN ACCORDANCE WITH SECTION 29
OF THE CONSOLIDATED REVENUE AND AUDIT
ACT 1931.

FOR COMPTROLLER OF THE TREASURY.

PURCHASING AGENT

R 2622

TO BE RETURNED TO HEAD OF BRANCH

SEE REVERSE SIDE

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

**VERY
POOR
COPY**

McDOWELL & DOKE

TINSMITHS

AUTO AND TRACTOR RADIATORS REPAIRED, RECORDED AND CLEANED
CONDITIONED AIR AND ANCHOR KOLSTOKER

SHOP PHONE 3270
RES. PHONES 3819-2601

115 9TH STREET

BRANDON, MAN.

21 November

1946

SOLD TO Indian Residential School

Brandon, Man

TERMS: CASH
8% CHARGED ON
OVERDUE ACCOUNTS.

DATE	ARTICLES	FOLIO	CREDIT AMOUNT	DEBIT AMOUNT	TOTAL
Nov 11	Furnace and Casing			\$ 450.00	
	9" Cold Air Box			6.50	
	8 Hot Air Collars			8.00	
	2 12" Pipes			2.50	
	2 8" Pipes			2.20	
	1 8" Elbow			1.00	
	1 12" Elbow			1.25	
	1 13" Elbow			1.40	
	3 9" Elbows			4.50	
	4 9" Pipes Galv 30"			6.00	
	1 Taper 12 to 15			1.75	
	1 Humidifier			15.00	
	Installation Charges			26.00	\$526.10

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

133-0-5 (W.T. 1)

Ottawa, 27 November 1946.

Memorandum:


DEPARTMENTAL PURCHASING AGENT

Attached is an account amounting to \$526.10 covering the cost of supplying and installing a new furnace in the Principal's Residence at the Brandon Indian Residential School.

Permission was not obtained for this expenditure because of the fact that the Principal considered it was an emergency and was needed in order to prevent freezing of the water system.

For a considerable space of time, the Principal had trouble with gas fumes coming up the air pipes from the furnace in the Principal's residence. When the outside casing was taken off, it was found that the fire box was split for about 18 inches along the front and that a piece of it had fallen out. The radiator on the back had been repaired but at last had burned right through with the result that the furnace was beyond repair. The Principal's residence at this school is a very old building and the old furnace had been in use for many years. The Principal was able to secure a furnace in stock from McDowell and Doke and he arranged for its immediate installation.

Under the circumstances, it is recommended that purchase order be issued so that the account may be paid. The Brandon School and Principal's Residence is Government property. The coding is as follows:- 576-76-09-622.



Bernard F. Neary,
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY



I.A.1480-4

December 16th, 1946.

MEMORANDUM:

Re: Brandon Indian Residential School

Further to our memorandum of November 23rd, 1946, you are advised that we are in receipt of additional correspondence from Mr. Gow, under date of December 10th, 1946, in which he informs us of a reluctance on the part of the School Principal to have that phase of the work, already approved by Indian Affairs, carried out this winter, as he feels that considerable disturbance would be created and that the interference to the normal school routine would be troublesome.

In this connection, the following excerpt is quoted from Mr. Gow's letter dated the 10th instant on the matter:

"In discussing the situation at the Brandon Indian School with the Principal, I found that he was fairly well satisfied with the present hot water situation at the School and would much prefer that no action be taken this winter with respect to this installation. It is his idea that, if work of major repairs is to be carried out next summer, that this repair work can be well delayed until that time. In view of the reluctance of these firms to proceed with this installation along the lines outlined, and the wishes of the Principal of the School, we will not take any further action with respect to the matter until we have had a further communication with you on the subject."

It is felt that a brief summary of the entire project should be brought to the attention of the Indian Affairs Branch before our commentary is added, and the following outlines in condensed form, the reasons for our previous recommendations.

From October 30th, 1945, to February 9th, 1946, complaints, reports, and suggestions were submitted by the School authorities and Mr. Gow's office, all relative to the continuing inefficiencies, failures and general unsatisfactory performance of the existing high pressure steam and domestic hot water services. These conditions were confirmed by an officer from this Service on an inspection made last June. The high lights which should be kept in mind are: (1) an inadequate supply of hot water due to several causes, mainly the wearing out of present equipment, (2) the inability of the high pressure boiler to provide steam at sufficient pressure and in sufficient quantity to serve the laundry machines, caused by its deterioration and excessive loads.

Our original recommendation, under date of July 29th, 1946, provided for a complete modernization of this plant, including a new high pressure boiler, sufficient in capacity to

J. M. Wardle, Esq.,
Director,
Surveys and Engineering Branch,
Department of Mines and Resources,
O T T A W A, Ontario.

(over)

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

handle laundry machinery and a rather large domestic hot water load. The auxiliary equipment necessary to complete this project was included along with an estimate. Indian Affairs not realizing the extent of the work involved, could not see their way clear to provide funds as estimated, and suggested that one phase of the work be carried out at this time, namely, (our recommendation), improvements to the domestic hot water service. We realize that by splitting the work up into two or more phases the cost would be increased because when the final phase is undertaken certain changes and adjustments would be necessary, disturbing to some extent, the new work. In view of the serious shortage of hot water, it was felt that, in spite of this probability, the first operation should be carried out.

In commenting on the Principal's reluctance to have part of the work done now, during the School season, we wish to say that we fully realize that the disturbance unavoidably created would tend to upset, in varying degrees, the normal school routine. We would certainly prefer having all the work carried out at one time, since a much more satisfactory solution would result.

However, due to the time required by Contractors to assemble data for their tenders, and their reluctance to take on new work at this time, any benefit that may have been derived from carrying out one phase of the work has been lost, and it would appear that nothing better could be achieved before the close of the present fiscal year, than the purchase of as much essential equipment as possible from funds now available.

If Indian Affairs concur, we will prepare a bill of materials for equipment to the approximate value of funds now transferred to this Service, for delivery to the School this fiscal year. This procedure, of course, would require a revised design and specifications embodying the completed work to be undertaken in the 1947-48 fiscal year.

J. A. Mills

Chief Engineer.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

133-0-5



CANADA
DEPARTMENT
OF
MINES AND RESOURCES

SURVEYS AND
ENGINEERING BRANCH

December 19th, 1946.

Mr. Hoey


Re: Brandon Indian Residential School.

Please refer to your memorandum of December 2nd and previous correspondence relative to the proposed repairs to the heating plant at the above school.

A further memorandum dated December 16th has been received from Mr. Mills, copy of which is attached. It will be noted that the school authorities are still opposed to having any work done until next summer and in addition, it is virtually impossible to get any contractor to undertake the work. In view of the circumstances, Mr. Mills' recommendation to spend the money which is available now on the procurement of equipment and to undertake the complete repairs, as originally proposed, early in the 1947-48 fiscal year, is concurred in.

If you are in agreement with this plan would you please advise as soon as possible in order that a revised design and specifications may be prepared as per the last paragraph of Mr. Mills' memorandum.

692-1500-^{Dec 24}arg
EA 2792



Director.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

WT1
Do you want to
write in this
Hamilton

133-0-5 (WT1).

Ottawa, December 27, 1946.

Memorandum:

DIRECTOR,
SURVEYS AND ENGINEERING BRANCH.

Re: Brandon Indian Residential School
Brandon, Manitoba.

We have your memorandum of December 19th and it is noted that it has been found impossible to get any contractor to undertake the work required at the present time.

Your suggestion that some of the material be purchased now and placed in storage at the school is approved. However, we would appreciate it if this matter could receive immediate attention so that any funds not expended can be returned to this Branch before the end of February.

[Handwritten initials]

Director.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

Handwritten scribbles and initials in the top left corner.

133-0-5 (WT1).

Ottawa, December 28, 1946.

Mr. A.G. Hamilton, Inspector of Agencies,
538 Dominion Public Building, Winnipeg, Man.,

The Surveys and Engineering Branch has been endeavouring to make improvements to the heating plant at the Brandon Residential School. However, they now report to us as follows:

"In discussing the situation at the Brandon Indian Residential School with the Principal, I found that he was fairly well satisfied with the present hot water situation at the School and would much prefer that no action be taken this winter with respect to this installation. It is his idea that, if work or major repairs is to be carried out next summer, that this repair work can be well delayed until that time. In view of the reluctance of these firms to proceed with this installation along the lines outlined, and the wishes of the Principal of the School, we will not take any further action with respect to the matter until we have had a further communication with you on the subject".

In view of the above, it has been decided to defer further action until next summer.

Handwritten signature of Bernard F. Neary
Bernard F. Neary,
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY POOR COPY

THE J.H. ASHDOWN HARDWARE CO. LIMITED



W. J. ILLSEY
MANAGER WINNIPEG RETAIL

WINNIPEG, CANADA

December 16, 1946.

Mr. A. G. Hamilton,
Department of Indian Affairs,
538 Dominion Public Building,
Winnipeg, Manitoba.

Dear Sir:

We have pleasure in quoting you on Esse Cooker equipment as follows:

Model 700XB	-	\$3,370.00
Model 700XB HC		\$4,650.00

These two Units will be found illustrated on page two of the attached booklet. The difference being merely that the Model 700XB - HC has a hot closet all the way across the back as shown in the small cut on page two, whereas the 700XB does not have the hot closet.

From the foregoing prices may be deducted your discount of 25% and, in addition, presumably if you are exempt from Sales Tax, same also might be deducted. The actual Sales Tax deduction would be \$163.39 on the 700XB - HC, and \$120.56 on the 700XB.

These excellent Cookers are very attractive in view of the fuel saving. The Model 700 Unit, whether with or without hot closet, is operated with two fires and the total fuel consumption for the whole unit is 16 Tons of Anthracite or equivalent per year. The Cooker burns continuously 24 hours a day. The reason for this economy is simply that the heat of the coal is stored up in the heavily insulated cooker and some of it, also, is stored up in the heavy steel heat accumulator so that all the fuel is used for cooking rather than a large percentage of it being wasted through the side of the usual coal range and serving chiefly to raise the temperature of the kitchen to an uncomfortable level.

In addition the cooking qualities in so far as the ovens are concerned are stated to produce a saving in meat shrinkage of at least 10%. The reason for this is that the heat is even all around the oven, same being produced by means of the caloriduct. In ordinary coal ranges the heat is largely concentrated on one side which means continuous turning and attention. In the Esse Cooker, the meat is placed in the oven and one turning, at the most, is usually sufficient, the meat cooking evenly all around and without the weight lost which is usual with coal ranges.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

THE J. H. ASHDOWN HARDWARE CO. LIMITED


- 2 -

In addition, the kitchen is maintained in a very clean appearing and cool condition. Under current conditions, with staff difficulties, this is often a great feature in retaining a satisfied staff.

We trust the foregoing will prove of interest and are ready to supply any other information you may require at any time.

Yours very truly,

THE J. H. ASHDOWN HARDWARE COMPANY LIMITED,



G. M. Fleming,
Manager, ESSE COOKER DEPARTMENT.

CMF/M
Enc.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

133-0-5



CANADA

INDIAN AFFAIRS BRANCH

INSPECTOR OF INDIAN AGENCIES

DEPARTMENT OF MINES AND RESOURCES

209-11AU

Hold

[Handwritten signatures]

538 Dominion Public Bldg.
Winnipeg, Manitoba
December 17, 1946

Indian Affairs Branch
Department of Mines and Resources
Ottawa, Ontario

RE: Range for Brandon School
File 133-0-5 (W.T.1) Dec.10/46

In my letter 209-11AU, dated October 1, 1946, I wrote as follows:


"In view of the history of the range and its present condition I recommend a new one be provided when available. This is not an emergency but a suitable range is necessary. There are over 200 to cook for and it is impossible to do so satisfactorily with the present equipment.

I trust a new range will be purchased as soon as one can be made available. "

The range now in use is a Gurney Oxford No.13C.L.. It has three ovens with a firebox at one end. A large range is required but in view of our experience with the one in use I am not prepared to recommend the purchase of another range of the same design and make. In any event I am advised there are no large ranges of this type available in Winnipeg, and it is doubtful if there will be until some time late in 1947.

Ashdowns have the Esse range available for immediate shipment from their store in Winnipeg, and until December 31, are giving a 25% discount. I am enclosing their quotation together with a book of designs. This is undoubtedly an excellent range. The price is high but there is no comparison between this and the old range now in use.

Again I recommend the purchase of a new range. The Esse is available for immediate shipment and if funds are available I recommend it be purchased at once.



A.G. Hamilton
A.G. Hamilton
Inspector of Indian Agencies
for Manitoba.

*Winnipeg
2-6942*

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY POOR COPY

133-0-5 (W.T. 1)

Ottawa, 30 December 1946.

Mr. A.G. Hamilton, Inspector of Indian Agencies,
538 Dominion Public Bldg., Winnipeg, Manitoba.

We have your letter of the 17th instant with reference to the range for the Brandon Residential School.

Careful consideration has been given to the request that we supply Esse Cooker Equipment. However, the price of this is out of line with similar equipment supplied to other residential schools and consequently we are not prepared to incur the expenditure that would be involved.

We can secure within six weeks or two months, a McClary "Chef Junior Range". This would be supplied with double deck high shelf. The dimensions are as follows:-

Cooking Surface - 115" x 35"
Pan Tops - 30" x 28"
Height to Top - 31½"
Smoke Collars - 10"
Ovens - W-26", D-27", H-15½"

The above range gave satisfactory service in many military camps during the war and has been supplied to other residential schools with an enrolment of approximately the same number as Brandon.

We feel it should be satisfactory for the Brandon School but before placing the order we thought it advisable to write to you. Please let me hear from you as soon as possible.

The catalogue which you forwarded is enclosed.

Bernard F. Neary,
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

M^cCLARY FOOD SERVICE EQUIPMENT


THE "CHEF JUNIOR" RANGE

These ranges have proven very satisfactory when adapted for use with automatic stokers.

When supplied for use with stoker units the firebox and ashpit are completely lined with firebrick; also, if required, the castings on the front of the firebox can be left off and the front enclosed with a blank plate. The opening for stoker connection is made through end or front of firebox as required.


Ranges for use with stokers can be supplied with firebox on either left or right hand side of range.

Owing to the extremely high temperatures which may be developed with some stokers, we are not able to guarantee range tops when used with these units. We are, however, able to supply a top of a special nichrome mixture which has a greater heat resistance than the standard tops. We, therefore, strongly recommend that all ranges for use with stokers be equipped with nichrome tops over the firebox.



No. 20 "Chef Junior" with Double Deck High Shelf

Measurements:	No. 20 "CHEF JUNIOR" RANGE	No. 30 "CHEF JUNIOR" RANGE
Cooking Surface	One fire, two ovens. 84" x 35"	One fire, three ovens. 115" x 35"
Pan Tops	30" x 28"	30" x 28"
Height to Top	31 1/2"	31 1/2"
Smoke Collars	8"	10"
Ovens	W-26", D-27", H-15 1/2"	W-26", D-27", H-15 1/2"
Firebox for Coal or Wood	18" x 12" x 10 1/2" deep	18" x 12" x 10 1/2" deep
SHIPPING WEIGHTS:		
Range	1880 lbs.	2400 lbs.
Double Deck High Shelf	130 lbs.	190 lbs.
High Closet	130 lbs.	190 lbs.
Waterfront	60 lbs.	60 lbs.



No. 30 "Chef Junior" with Double Deck High Shelf

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES


ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

M^oCLARY FOOD SERVICE EQUIPMENT

THE "NAVY" RANGE



No. L.H.224-1. "Navy"—With Left-Hand Firebox and High Closet.

This is a well-constructed heavy duty range designed for restaurant or hotel service. Built as a unit of one firebox and two ovens it can be used in conjunction with the "Army" Range to give larger combinations. Can be supplied with either left-hand (No. 224-1) or right-hand (No. 225-1) firebox.

SPECIFICATIONS

BODY—Constructed of 14 gauge steel.

FIREBOX—Lined with best quality firebrick 4" thick. Fitted with three heavy triangular grates. If required for burning wood a special grate will be supplied when specified.

COOKING TOP—Top over firebox is 1" thick and over ovens $\frac{3}{4}$ " thick; of best grade cast iron—polished surface. A one-piece steel grease trough is fitted along front of blank plates and is provided with a drain in right end which connects with a removable grease can.

OVEN—Bottom of 12 gauge steel; top and sides of 16 gauge steel; aluminum finish. Heavy duty, drop, platform type doors. Fitted with strong, rugged polished hinges, door frame and catch, of wrought iron. Double latch permits door to be left slightly open.

GUARD RAIL—Is standard equipment, nickel-plated finish and fits around grease trough.

SHELVES—Single or double deck high shelves or high closet; constructed of blue polished steel with polished steel trim.

WATER HEATING EQUIPMENT—Flat waterback, "L" waterback, straight waterfront or hot water coil.

Measurements:

- Cooking Surface—76" x 31"
- Height to Top—30"
- Smoke Collar—8"
- Size of Ovens—W—24", D—21", H—14"
- Firebox—16" x 10 $\frac{1}{2}$ " x 11" D.
- Length of Wood Firebox—25"

Shipping Weights:

- Range—1200 lbs.
- Single Deck High Shelf—105 lbs.
- Double Deck High Shelf—175 lbs.
- High Closet—175 lbs.
- Flat Water Back—30 lbs.
- "L" Water Back—40 lbs.
- Straight Water Front—40 lbs.
- Hot Water Coil—25 lbs.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES


ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

**THE "CHEF JUNIOR" RANGE
CENTRE FIREBOX TYPE**

Where a centre firebox type range of large capacity is required, we offer the Chef Junior No. 2110 C.F. consisting of two fireboxes and three ovens. Available with or without double deck high shelf or high closet. This range has the same outstanding features as other models of "Chef Junior" Ranges, and may also be installed in straight line battery formation or back to back duplex arrangement.



No. 2110 C.F. "Chef Junior" Range

Measurements:	No. 21 C.F. "CHEF JUNIOR" One fire, two ovens	No. 2110 C.F. "CHEF JUNIOR" Two fires, three ovens
Cooking Surface	78" x 35"	132" x 35"
Pan Tops	28" x 28"	1st and 2nd: 28" x 28" 3rd: 30" x 28"
Height to Top	31 1/2"	31 1/2"
Smoke Collars	9"	1st: 9" 2nd: 8"
Ovens	W—24", D—27", H—15 1/2"	1st and 2nd: W—24", D—27", H—15 1/2" 3rd: W—26", D—27", H—15 1/2"
Firebox for Coal or Wood	18 1/2" x 12 1/2" x 12 1/2" deep	Both: 18 1/2" x 12 1/2" x 12 1/2" deep
Shipping Weights:		
Range	1850 lbs.	3250 lbs.
Double Deck High Shelf	125 lbs.	185 lbs.
High Closet	125 lbs.	185 lbs.
Waterback	65 lbs.	—

**GENERAL STEEL WARES
LIMITED**

Montreal Toronto London Winnipeg Calgary Vancouver

3B

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

McCLARY FOOD SERVICE EQUIPMENT

THE "CHEF JUNIOR" RANGE CENTRE FIREBOX TYPE

For those who prefer a heavy duty coal and wood range with firebox in the centre we recommend the Chef Junior No. 21 C.F. The outstanding features found in all other styles of Chef Junior Ranges have been incorporated in this model. These ranges are constructed in such a manner that any number of units may be combined to make either straight line or back to back installation.



No. 21 C.F. "Chef Junior" Range

SPECIFICATIONS

BODY—Constructed of 14 gauge steel.

FIREBOX—Lined with best grade firebrick 4" thick. Coal grate is three triangular bar type easily removable. For wood, a flat grate can be supplied in place of the three bar type.

FLUE SYSTEM—Completely insulated throughout with firebrick to give added protection from corrosive gases. Efficient standard flue system with direct draft damper. Separate damper control for each oven. Draft control in ash pit door.

COOKING TOP—Three-ring cover over firebox and blank plates over the ovens. Top of best grade cast iron 1 $\frac{1}{4}$ " thick over firebox and $\frac{3}{4}$ " thick over oven. French type blank plates grooved around edge for draining grease into troughs which run along front. Troughs are standard equipment and have drains on ends. Grease flows into receptacles on sides of range.

IMPROVED FIRE DOOR—Fits into top which permits easy firing. Draft check door in fire door which can be opened to hold fire overnight.

OVEN—Extra large. Bottom made of 12 gauge steel. Top and sides of 14 gauge steel. Extra heavy, drop, platform type doors, insulated 1" thick. These doors have a very heavy cast door frame. Sliding in frame and supporting door when open, is a heavy brace hinged to a steel rod. Door is counterbalanced by heavy coil spring concealed in hinge box. Double latch permits door to be left slightly open.

CLEANOUTS — Provided below ovens.

SHELVES — Double deck high shelf or high closet constructed of blue polished steel with polished steel trim.

WATER HEATING EQUIPMENT — Special water-back can be supplied for centre fire ranges.



No. 21 C.F. "Chef Junior" Range with
Double Deck High Shelf

3A

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

133-0-5

INSPECTOR OF INDIAN AGENCIES



CANADA
DEPARTMENT
OF
MINES AND RESOURCES

INDIAN AFFAIRS BRANCH

209-11 A.U.

AIR MAIL

538 Dominion Public Bldg.,
Winnipeg, Manitoba,
January 9th, 1947.

*See Steel
465-1*

Indian Affairs Branch,
Department of Mines and Resources,
OTTAWA, Ontario.

Re: Range for Brandon Indian School,
Your file 133-0-5 (W.T.1), Dec.30/46.)

The No. 30 McClary Chef Junior has, as you will note by the catalogue enclosed, one firebox and three ovens. It is the same type as the Gurney Oxford range now in use, which has never given satisfactory service.

I have discussed the matter with Mr. Strapp and he thinks it unwise to purchase this same type again and I heartily agree. I would suggest for your consideration, and I hope approval, the purchase of McClary Chef Junior Range No.2110 C.F. with double deck high shelf. This range, as you will note, has two fire boxes and these are independent of each other. The cost of this range, f.o.b. Winnipeg, is perhaps \$85.00 more than the one suggested in your letter.

I recommend the immediate purchase of the Chef Junior No. 2110 C.F. with double deck high shelf and I would suggest that the company be requested to arrange for installing the range when it arrives at the Brandon School.



A.G. Hamilton
A.G. Hamilton,
Inspector of Indian Agencies
for Manitoba.

Encl.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

133-0-5 (W.T. 1)

Ottawa, 13 January 1947.

Mr. A.G. Hamilton, Inspector of Indian Agencies,
538 Dominion Public Bldg., WINNIPEG, Manitoba.

With reference to your letter of
the 9th instant, we are requesting the Purchasing
Branch to secure a McLary Chef Junior Range No.
2110 C.F. with double deck high shelf for the
Brandon Indian Residential School.

Philip Phelan,
Chief, Training Division.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

DEPARTMENT OF MINES AND RESOURCES

Requisition No.....

133-0-5

13 January

19 47.

Order No.....

To the Dept. Purchasing Agent, Ottawa,

PLEASE FURNISH THE FOLLOWING SUPPLIES FOR USE OF.....

VOTE 76 ALLOTMENT 12-415 ALLOCATION SYMBOLS.....

SHIP TO Rev. O.B. Strapp, Principal, Indian Residential School,
Brandon, Manitoba.

Purpose for which required Brandon Indian Residential School - No. 576

QUANTITY		UNIT PRICE	TOTAL
1	McLary Chef Junior Range No. 2110 C.F. with double deck high shelf. This range, as you will note, has two fire boxes and these are independent of each other.		

*P.O. 16377 d/20 Jan 47
 plus slip mailed to
 Inspector Hamilton
 5 Feb 47
 H.B.
 B.D.*

I hereby certify that I have personal knowledge that all the above articles are required in the Department and for Departmental purposes only. The expenditure required by this requisition is strictly unavoidable and the public interest will suffer if it is not made.

SIGNED— *[Signature]*

APPROVED— *[Signature]* Director

- NOTE:—
1. In ordering stationery and printed matter use separate sheets.
 2. Order numbered forms by number or send sample.
 3. Orders for unnumbered forms should be accompanied by samples.
 4. Orders for books should be accompanied by sample pages or folios.
 5. Orders for which purchase orders will issue should give as full details as possible for each item.
 6. All Requisitions should be submitted in duplicate. One copy will be returned as acknowledgment.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

*VERY
POOR
COPY*

133-0-5

DEPARTMENT OF INDIAN AGENCIES



CANADA
DEPARTMENT
OF
MINES AND RESOURCES

INDIAN AFFAIRS BRANCH

209-11 A.U.

[Handwritten scribble]


538 Dominion Public Bldg.,
Winnipeg, Manitoba,
January 16th, 1947.

Indian Affairs Branch,
Department of Mines and Resources,
OTTAWA, Ontario.

The following is urgently needed for the
Brandon Indian Residential School:-

1. Paint for the hall on the third floor. The walls are in a disgraceful condition - the result of the lack of discipline among the boys prior to Mr. Strapp accepting the position as Principal. This wall is a reminder of the "good old days" and I feel it has a bad effect on the boys. Redecoration would be another step in removing the memory of a time when the "gang spirit" ruled.
2. The dormitory floor space for the girls is crowded. I recommend twelve (12) double deck beds complete with mattresses. At present there are 100 girls in residence.
3. The need for chairs has previously been reported and should be supplied without delay. These chairs are required for use in the auditorium and I understand the folding type is most suitable.
4. The electric irons are in poor condition. They have been repaired many times and should be replaced - six (6) are needed.

these recommendations will receive favourable consideration.



A.G. Hamilton
A.G. Hamilton,
Inspector of Indian Agencies
for Manitoba.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

133-0-5 (W.T. 1)

Ottawa, 21 January 1947.


Mr. A.G. Hamilton, Inspector of Indian Agencies,
538 Dominion Public Bldg., WINNIPEG, Manitoba.

We have your letter of the 16th instant regarding the Brandon Residential School. You did not state the number of gallons of paint required. Please let me have this information and you might also state at what cost you could secure it either at Brandon or in Winnipeg.

It is presumed that the school only requires the ordinary electric iron and you may purchase six of these.

The Departmental Purchasing Agent is being requested to secure the double deck beds and mattresses.

ms
We have been previously requested to supply additional chairs for the auditorium but at the present time they are difficult to secure. In addition the expenditure involved would be considerable. As the end of the present fiscal year is approaching our funds at the present time are limited.


Bernard F. Neary,
Supt. of Welfare & Training.

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY

DEPARTMENT OF MINES AND RESOURCES

133-0-5

21 January 1947.

This space for use of Head Office only

Requisition No.

Order No.

To the Departmental Purchasing Agent, Ottawa,

PLEASE FURNISH THE FOLLOWING SUPPLIES FOR USE OF.....

VOTE 76 ALLOTMENT 12-415 ALLOCATION SYMBOLS.....

SHIP TO Rev. O.B. Strapp, Principal, Indian Residential School,
Brandon, Manitoba.


Purpose for which required Brandon Indian Residential School - No. 576

QUANTITY		UNIT PRICE	TOTAL
12	Double deck beds with mattresses.		


*PO 16524 d/f 4/47
Blue slip mailed 8/2/47
Principal
B.D.*

I hereby certify that I have personal knowledge that all the above articles are required in the Department and for Departmental purposes only. The expenditure required by this requisition is strictly unavoidable and the public interest will suffer if it is not made.

SIGNED—



APPROVED—



Director

- NOTE:—
1. In ordering stationery and printed matter use separate sheets.
 2. Order numbered forms by number or send sample.
 3. Orders for unnumbered forms should be accompanied by samples.
 4. Orders for books should be accompanied by sample pages or folios.
 5. Orders for which purchase orders will issue should give as full details as possible for each item.
 6. All Requisitions should be submitted in duplicate. One copy will be returned as acknowledgment.


Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

*VERY
POOR
COPY*



THE DECORATION OF INTERIOR WALLS

INTERIOR WALLS

Finished entirely as one smooth expanse of delicate tone—a perfect background for the beauty of line in furniture—the painted or enamelled wall has a dignity and serenity that is soothing to the nerves and restful to the eye in quiet contrast to the bolder colors of drapes, ornaments, and other incidentals.

The painted wall is economical both from the viewpoint of durability and the moderate cost of redecoration. Equally important, it is a clean, sanitary finish that can easily be kept spotless with the aid of a damp cloth. This is a strong point for its adoption in any decorative scheme, particularly when there are children in the home.

In C-I-L Wall Finishes, three gradations in sheen are available: Interior Gloss Enamel, Semi-Gloss and Flat Wall Paint. All have their distinctive charm or utility.

The marked resistance of C-I-L Interior Gloss Enamel to moisture and its ease in cleansing make it admirable for use in the kitchen and bathroom. For the living, dining and bedrooms, however, a more restful background is desirable, and it is here that you may exploit, to the fullest extent, the charm of the delicate pastel shades of C-I-L Semi-Gloss and C-I-L Flat Wall Paint with their exquisitely soft, light-diffusing qualities.



"PREPARED PAINT"

Highest quality house paint.

"INTERIOR GLOSS ENAMEL"

Three sheens for interior walls and woodwork.

"SEMI-GLOSS"

"FLAT WALL PAINT"

"CILUX" ENAMEL

Quick-drying. For furniture, cabinets, breakfast-nooks, etc.

"DULUX" Super White ENAMEL

White and stays White.

"FLOW-KOTE" ENAMEL

Full-bodied, high-gloss white enamel.

"FLOOR, PORCH AND DADO" ENAMEL

For interior and exterior use on wood or cement.

"NAVALITE" VARNISH

Pale, flexible, for interior or exterior.

VARNISHES

For all purposes.

MADE BY THE MAKERS OF


"DUCO" & "DULUX"



Indian Residential School

INTERIOR GLOSS ENAMEL

FOR WALLS AND WOODWORK



CANADIAN INDUSTRIES LIMITED
PAINT AND VARNISH DIVISION

Calgary Montreal Toronto Winnipeg Regina Vancouver

910-H 6-30-50. PRODUCED IN CANADA BY E.C.C. 1418

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES


ARCHIVES PUBLIQUES

CANADA


VERY POOR COPY



INTERIOR GLOSS ENAMEL




OLD IVORY 51



SEA FOAM GREEN 52




JERSEY CREAM 55



FRENCH GREY 56



COOLIE BLUE 57




MONASTERY GREY 58

INTERIOR GLOSS ENAMEL


Interior Gloss is a high-grade, gloss enamel for the decoration and protection of interior walls and woodwork.

Specially designed for easy brushing on large areas, the drying time is properly adjusted to allow the edges of freshly-painted sections to blend together smoothly, which prevents the appearance of lap-marks in the finish when dry.

The tough film of Interior Gloss resists abrasion and permits cleaning with a damp cloth or washing with water or mild neutral soap solutions. Thus it is the ideal finish for kitchens and bathrooms in homes or public institutions, or for any other interior wall surfaces that require frequent washing in the interest of cleanliness.



OLD ROSE 54



GOLDEN TAN 53

WHITE 50

DIRECTIONS

STIR THOROUGHLY. Surfaces to be painted must be clean and free from grease. Surfaces that are checked or peeling, should be sanded smooth. NEW PLASTER—Should be neutralized with a zinc sulphate solution and followed by a sizing coat of C-I-L Old English Paint Oil to stop suction. Reduce the first coat of "Interior Gloss" 10% with Pure Turpentine; allow to dry thoroughly and apply a second coat as received.

CAUTION. Water paint should be entirely removed by washing with water before applying any oil-type paint. Cracks and holes should be filled with plaster before applying the sizing coat. Allow ample time for each coat to dry thoroughly.

A WASHABLE GLOSS FINISH FOR INTERIOR WALLS AND WOODWORK


Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY



THE DECORATION OF INTERIOR WALLS

Finished entirely as one smooth expanse of delicate tone—a perfect background for the beauty of line in furniture—the painted or enamelled wall has a dignity and serenity that is soothing to the nerves and restful to the eye in quiet contrast to the bolder colors of drapes, ornaments, and other incidentals.

The painted wall is economical both from the viewpoint of durability and the moderate cost of redecoration. Equally important, it is a clean, sanitary finish that can easily be kept spotless with the aid of a damp cloth. This is a strong point for its adoption in any decorative scheme, particularly when there are children in the home.

In C-I-L Wall Finishes, three gradations in sheen are available: Interior Gloss Enamel, Semi-Gloss and Flat Wall Paint. All have their distinctive charm or utility.

The marked resistance of C-I-L Interior Gloss Enamel to moisture and its ease in cleansing make it admirable for use in the kitchen and bathroom. For the living, dining and bedrooms, however, a more restful background is desirable, and it is here that you may exploit, to the fullest extent, the charm of the delicate pastel shades of C-I-L Semi-Gloss and C-I-L Flat Wall Paint with their exquisitely soft, light-diffusing qualities.



"PREPARED PAINT"

Highest quality house paint.

"INTERIOR GLOSS ENAMEL"

Three sheens
for interior
walls and
woodwork.

"SEMI-GLOSS"

"FLAT WALL PAINT"

"CILUX" ENAMEL

Quick-drying. For furniture, cabinets, breakfast-nooks, etc.

"DULUX" *Super White* ENAMEL

White and stays White.

"FLOW-KOTE" ENAMEL

Full-bodied, high-gloss white enamel.

"FLOOR, PORCH AND DADO" ENAMEL

For interior and exterior use on wood or cement.

"NAVALITE" VARNISH

Pale, flexible, for interior or exterior.

VARNISHES

For all purposes.

MADE BY THE MAKERS OF

"DUCO" & "DULUX"




Indian Residential School

INTERIOR GLOSS

ENAMEL

FOR WALLS AND WOODWORK



CANADIAN INDUSTRIES LIMITED

PAINT AND VARNISH DIVISION

Halifax Montreal Toronto Winnipeg Regina Vancouver

910-14 9-39-20. PRODUCED IN CANADA BY E.C.C. 1419

Indian Affairs. (RG 10, Volume 6257, file 576-5, part 8)

PUBLIC ARCHIVES

ARCHIVES PUBLIQUES

CANADA

VERY
POOR
COPY