

Indian Affairs
School Files

(RG 10, Volume 6351)

| | |
|--------------------|---|
| File 753-5, part 3 | Edmonton - Industrial School - Building Maintenance Accounts. 1929- 1933 |
| File 753-5, part 4 | Edmonton - Industrial School - Building Maintenance Accounts. 1933-1946 |
| File 735-5, part 5 | Edmonton - Industrial School - Application for Inspection of Construction. 1920 - 1925 |
| File 753-5, part 6 | Edmonton - Industrial School - Accounts - Building Maintenance - Supplies. 1947 |
| File 735-5, part 7 | Edmonton - Industrial School - Accounts - Building Maintenance - Supplies. 1947 - 1949 |

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES.
CANADA

FILE NO. 753-5

DEPARTMENT OF MINES AND RESOURCES
INDIAN AFFAIRS BRANCH

EDMONTON RESIDENTIAL SCHOOL
BUILDINGS, ACCOUNTS, ETC.

CROSS REFERENCE

110-0-5

FILE NO. 753-5

| CENTRAL REGISTRY | P.A. or B.F. | DATE | INITIALS | REFERRED TO | FOR REMARKS | INITIALS | DATE |
|---|--------------|----------|----------|-------------|-------------------------------|----------|----------|
| (If purpose for which referred cannot be expressed on one line, add minute to file, and enter here "With Minute") | | | | | | | |
| 26/10/48 | | | | E1 | 28883 | | 26/10/48 |
| 3/11/48 | PA | 1-11 | SD | E4 | V422-40 | | 1/11/48 |
| 18/11/48 | PA | 9/11 | PT | E5 | 27304 | | 9/11/48 |
| | P.A. | 18/11 | SD | E4 | V464-40 | | 17/11/48 |
| | P.A. | 11/11 | SD | E5 | 1275 | | 19/11/48 |
| 25/11/48 | PA | 11/11 | P | E1 | 2348 | CR19 | 24/11/48 |
| 25/11/48 | P.A. | 25/11 | SD | E4 | P.D35862) | CR19 | 25/11/48 |
| 6/12/48 | BF | 30/11 | SD | E1 | 4044 | CR19 | 1/12/48 |
| 9/12/48 | P.A. | 9/12 | SD | E4 | V520-48 | CR19 | 1/12/48 |
| 20/12/48 | BF | 15/11/49 | SD | | | | |
| | P.A. | 17/1/49 | SD | E4 | No 14/11/13/14/15/16/17/18/19 | CR19 | 17/1/49 |
| 17/1/49 | Carne | | BF | E | See B7 | | 15/1/49 |
| | P.A. | 17/1/49 | SD | E4 | V.18-49 | CR19 | 18/1/49 |
| 24/1/49 | P.A. | 24/1/49 | SD | E4 | Letters 11123 & 124 | CR19 | 27/1/49 |
| | P.A. | 16/1/49 | SD | E4 | V.54-49 | | |
| | PA | 2/3 | SD | E | 27453 | CR14 | 2/3/49 |
| | PA | 3/3 | ML | E1 | Low | | |
| 22/3/49 | PA | 22/3 | SD | E1 | 29811 | CR19 | 14/3/49 |
| 24/3/49 | P.A. | 21/3/49 | SD | E4 | V.54-49 | CR19 | 17/3/49 |
| 26/3/49 | P.A. | 26/3/49 | SD | E4 | No 97898-49 | CR19 | 26/3 |
| | PA | 28/3 | SD | E | 1809 | CR19 | 28/3 |
| 14/4/49 | PA | 11/4 | SD | E | 5020 | CR19 | 1/4 |
| 14/4/49 | PA | 11/4 | SD | E | 7259 | CR19 | 11/4 |
| 17/4/49 | PA | 8/4 | SD | E4 | V.151/49 | CR14 | 31/4 |
| 27/4/49 | PA | 10/4 | PT | E | 10694 | CR19 | 27/4 |
| | PA | 12/5/49 | SM | E1 | 13401 | | |
| | P.A. | 7/5/49 | SD | E4 | V.164-49 | CR14 | 3/5 |

SCHOOL SERIES

R. 3755

DO NOT WRITE BELOW THIS LINE

Indian Affairs, School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

FILE NO.

110-0-5 VOL. 6

VOL. 5 CLOSED.

DEPARTMENT OF MINES AND RESOURCES

INDIAN AFFAIRS BRANCH

EDMONTON RESIDENTIAL SCHOOL

BUILDINGS, ACCOUNTS, ETC.

CROSS REFERENCE

| CENTRAL REGISTRY | P.A. OF B.F. | DATE | INITIALS | REFERRED TO | FOR REMARKS | INITIALS | DATE |
|---------------------|--------------------|---------|----------|-------------|---|----------|----------|
| | | | | | (If purpose for which referred cannot be expressed on one line, add minute to file, and enter here "With Minute") | | |
| | PA | 5-3-48 | KB | E4 | 1510 | EM | 3-3-48 |
| | PA | 10-3-48 | E4 | E4 | 2731 | EM | 4-3-48 |
| | PA | 12-3-48 | E4 | E4 | | | |
| | PA | 17-3-48 | KB | E4 | Ref. P.O. | EM | 17-3-48 |
| | PA | 20-3-48 | KB | E4 | 18-3-48 E4 | EM | 18-3-48 |
| | PA | 20/3/48 | AV | E4 | 5372 | EM | 20-3-48 |
| | PA | 13-4-48 | KB | E4 | V-62-48 | EM | 12-4-48 |
| | PA | 11-5-48 | E4 | E4 | 120-48 | EM | 10-5-48 |
| | PA | 12-5-48 | AV | E4 | 14860 | EM | 11-5-48 |
| | PA | 10-6-48 | E4 | E4 | 23844 | EM | 9-6-48 |
| | PA | 10/7/48 | AV | E4 | 1414 | | 7-7-48 |
| | PA | 10/7/48 | AV | E4 | 2170 | | 2-2-48 |
| | PA | 12/4/48 | INT | E4 | See file | | 11/11/48 |
| | PA | | | E1 | 10330 | | 18/8 |
| | PA | | | E3 | memo | | |
| | PA | | | Miss Dean | | | 23/8 |
| | PA | | | E | | | |
| | PA | 13.9 | KB | E4 | 346 | | |
| | PA | 13/9 | AV | E1 | 16385 | EL | 13/8 |
| | PA | 14.9 | KB | E4 | V357-48 | | |
| | PA | 15-9 | AV | E4 | 16732 | | 15/10 |
| | PA | 21.9 | KB | E4 | V360-48 | | 28-9-48 |
| | PA | 9.10 | KB | E4 | V375-48 | | 5/10/48 |
| | PA | 9.10 | KB | E4 | 21738 | | 6/10/48 |
| | PA | 9.10 | AV | E4 | 21838 | | 7/10/48 |

FILE NO. 110-0-5 VOL. 6

VOL. 5 CLOSED.

R 2871

DO NOT WRITE BELOW THIS LINE

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

October 21st, 1946.

Dept. Of Mines and Resources,
Indian Affairs Branch,
Winterburn, Alberta.

Dr to,
HADDON & MAUGHAN Ltd.,
207 - 210 Dressage Building,
Edmonton, Alberta.

349

| Job #514 | To install three toilets: | |
|----------|---|--------|
| 1 | 4" Kadfer Joint | 3.75 |
| 10 lbs. | Lead Wool | 3.00 |
| 2 lbs. | Oakum | .60 |
| 3 | Toilet combinations, Briggs, less seats | 103.50 |
| 6 | T Bolts & washers | 1.20 |
| 3 | 3/8" Tailpieces | .60 |
| 10 lbs. | Putty | 1.00 |
| 2 | 1/2" x 6" Galv. Nipples | .30 |
| 1 | 3" x 1/4" Bend | .72 |
| 1 ft. | 3" S.H. Soil Pipe | .77 |
| 8 lbs. | Lead | .96 |
| 1 lb. | Oakum | .30 |
| 3 | 4" Floor Flanges | 2.28 |
| | Labor | 70.35 |
| | TOTAL..... | 189.33 |

CORRECTED STATEMENT

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

DEPARTMENT OF MINES AND RESOURCES
INDIAN AFFAIRS BRANCH

Form No. 1
R. 2149

TREASURY ONLY

CHEQUE No.

DATE

Pay to Haddon & Maughan,

Address 207 - 210 Kresge Building,
Edmonton, Alberta.

| DATE | SERVICE | AMOUNT |
|------|--|--------|
| 1946 | To installation of three toilets at the Edmonton Indian Residential School as per invoice #349 attached. | 189.33 |
| | Charge Vote 76-09-689 | |



153
3/2/47
Voucher in duplicate collected
for Government to use.

One hundred and eighty nine dollars and thirty three 189.33
cents

I HEREBY CERTIFY that this Voucher is correct, that the material has been supplied, the work performed and that the charges are fair and just, also that the expenditure has been incurred legitimately and that each item of the same is a fair and just charge against the Government of Canada. This expenditure was authorized by Departmental Letter, File No. dated P.O.#15161

E. M. J. Overton
Clerk in Charge Agent
DATE November 16th, 1946.

Voucher No. 342-46

Indian Affairs, School Files.
(RG IC, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

110-0-5 (M.T. 1)

Ottawa, 20 January 1947.

Mr. E.A. Robertson, Clerk in Charge,
WINTERBURN, Alta.

We have your voucher No. 342-46
with amended account from Haddow & Maughan.
The account includes an item of \$70.35 for
labour.

It will be necessary for us to
have detailed information showing the number
of hours the workmen were employed and the
rate per hour.

Bernard F. Neary,
Supt. of Welfare & Training.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

copy

Government of the Province of Alberta
Office of the Fire Commissioner

December 23rd, 1946.

From: J. H. Leyland, Esp.,
Lethbridge, Alta.

To: R. R. Moore, Esq.,
Supt. of Insurance & Fire Comm'r.,
EDMONTON, Alberta.

Fire Inspection Report

Re - Edmonton Indian Residential School,
EDMONTON, Alberta.

In view of the recent tragic fires which have occurred causing loss of life, instructions have been received from R. R. Moore, Superintendent of Insurance & Fire Commissioner, Edmonton, Alta., to inspect all buildings of Public Assembly, and therefore, while in the St. Albert district, a thorough inspection was made of the above Residential School.

The following is a description of the various buildings inspected, their occupancies and recommendations to remedy fire hazards found therein:

ADMINISTRATION BUILDING

This building is three storey and basement - construction brick - interior walls lath and plaster. Built 1924.

Occupancies:

Basement. Wash and bath room, boys and girls playrooms, furnace room, laundry room, kitchen, boys and girls dining room and furnace room.

Recommendations basement:

It is recommended that a stand pipe be connected with the present water pressure pipe in the corridor - North & South wall, with hose and hose bracket - 100 feet of 2½ inch hose, to service Dining room, Kitchen, Laundry and Boiler room. Approved type of fire extinguishers to be installed in all of the above mentioned rooms, furthermore, all drop cords or extensions from ceiling outlets be removed and rooms wired to conform with the present Canadian Electrical Code.

FIRST FLOOR

Occupancies on this floor are as follows:
Offices of the Principal, The Rev. E.J. Staley, and Assistant Principal, J.A.Faunt.
Secretary's office, Staff Dining room, Sewing room, two playrooms each end of corridor.
(East & West) and Church Chapel.

Recommendations 1st floor

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Re: Edmonton Indian Residential School
(continued)

Hose on hose brackets attached to standpipe be replaced - present hose perished. Flexible electric extensions cords from ceiling outlets in sewing room dining room (staff) class rooms and corridor be removed and re-wired to conform with Canadian Electrical Code. Pilot light to be installed over electric iron. Extinguishers S & A type to be thoroughly checked and tagged.

2nd FLOOR

Occupancies of this floor are as follows:
Four childrens dormitories - located
No. 1 S.E. corner - accommodates 15 double beds - 30 children - ages 6 years to 12 years
No. 2 N.E. corner - accommodates 15 double beds - 30 children - ages 12 years to 16 years
The other two dormitories are located at the West end of the building, and are duplicate of the East end. There are also staff bedrooms.

Recommendations - see Fire Exit facilities.

3rd FLOOR

The whole of this floor is presently closed off. It is periodically used as dormitories. At present used as storage for beds and mattresses.

Recommendations - see Fire exit facilities.

FIRE ALARM SYSTEM

Building has the 'break glass type' on own transformer - system services all floors, but not connected with staff residences.
Recommend that system be carried to staff quarters.

FIRE EQUIPMENT

There are two standpipes which service the building - each floor has hose $1\frac{1}{2}$ inch linen, 50 feet, this is attached to hose bracket, with nozzle. Recommend that all hose be condemned and replaced - hose has been in use since 1924.

Each floor has two S & A type fire extinguishers 5 gallon - located each end of corridors - East & West ends. These should all be thoroughly checked and properly tagged.

FIRE EXIT FACILITIES

A very unusual situation exists in connection with these facilities and should be remedied immediately. Fire exit other than main inside

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Re: Edmonton Indian Residential School
(continued)

stairway - South centre of building is by the way of double sash windows, located in each of the childrens dormitories. In order to reach the sill of each window it is necessary for the children to step up some four feet from the ground level and some of the children being so small it would therefore necessitate older children rendering assistance. Such exit facilities are inadequate for an occupancy of this type and would recommend that windows be removed, standard doors installed and to be equipped with approved type of panic bolts. There are two other exits, but these are located in the two staff bedrooms, doors are kept locked and the children deprived of their access.

FIRE ESCAPES

| | | | |
|---------------------|---------|-------|------|
| Two stairway type - | located | North | Wall |
| " pole type | " | " | " |
| " pole type | " | West | Wall |
| " pole type | " | East | Wall |

The two stairway type are so situated that their use would only be for the staff, access to these are gained through the two staff bedrooms. Bedroom and exit doors are kept locked at all times.

for
The pole type of course is for the children and as previously mentioned exit to these are gained through a sash window. From the window sill abutting the wall is a small platform and it is by these means the children are expected to make their escape in the case of fire. At the time of their construction no thought whatever was given to 30 or 40 below zero weather. It is difficult to imagine any person and especially small children, being able to safely make their escape from the building in the event of fire by means of this type of escape. One hundred and thirty children in night attire would, in my opinion, never be able to evacuate the building by means such as are available, especially in winter when the metal would be covered with frost. I would recommend that these pole type of escapes be removed and two steel tubular ones installed at North and East Walls, that inter-connecting doors be installed to connect each dormitory and standard door exits to replace windows and equip each door with approved type of panic bolt.

NIGHT STAFF

Nil. None provided by the Department.

Water Supply

There is only one well which meets the ordinary requirements of the building - that is general use. I should also mention that this supply is used by the residences.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Re: Edmonton Indian Residential School
(continued)

There is no reserve and any extra demands made on the well would run it dry. Water supply would be inadequate to put out any fire should there be a rapid spread. Would recommend that supply be increased.

BOILER ROOM

Cement walls and floor - contains three boilers - two low pressure type of 40 lbs. each and one high pressure of approx. 100 lbs. Coal fed. Room has two exits - North and South walls. Engineer in charge. From midnight until six A.M. each day no person is in charge of the boiler room. Furnaces are banked down for the night and left. The matter of a night watchman has been brought to the attention of the Department of Indian Affairs by the present Principal, but the Department stated that seeing no provisions had been made in the yearly estimates for the payment of one the services of a watchman would have to wait.

The above is one of extreme importance and I would recommend that the services of an night watchman be secured. It is quite evident that if a fire ever started in this building a large loss of life would result.

OUTSIDE BUILDINGS

These consist of the following:
Horse barn, Cow barn, Hog barn, utility building, roothouse and garage.

The hog barn is the only building which has a supply of water and that is through a half inch pipe. No facilities in any of the other buildings in case of fire. Recommend that approved type of fire extinguishers be installed.

STAFF RESIDENCES

No fire extinguishers. Recommend they be installed.

REMARKS:

Inspection shows that buildings have been allowed to deteriorate to a very marked degree, though its cause has not been through the present Principal. Numerous conditions at present prevailing should be remedied. In the matter of fire exits and escapes these should be attended to at once, same applies to all electrical wiring, water supply and fire fighting equipment. In the interests of Fire Prevention some of the conditions should not be tolerated especially where the boiler room is concerned. A second engineer, or night watchman should be added to the present staff.

Indian Affairs. School Files,
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Re: Edmonton Indian Residential School
(continued)

FIRE DRILLS

I omitted to mention that periodic fire drills are held under the supervision of the School Principal. Members of the staff, when available, constitute the volunteer Fire Department.

(sgd.) J. H. Leyland, Insp.

R. R. Moore, Esq.,
Fire Commissioner,
EDMONTON, Alta.

Forwarded for your information.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

OF INDIAN AGENCIES



CANADA
DEPARTMENT
OF

MINES AND RESOURCES

CALGARY, Alberta,
January 7th, 1947.

110-0-5
INDIAN AFFAIRS BRANCH

110-4B-8


Indian Affairs Branch, Dept. of Mines & Resources, OTTAWA, Ont.

Re: Edmonton Indian Residential School
Fire Inspection Report

The Provincial Fire Commissioner submitted the attached report to Dr. Stone, Medical Superintendent, Dept. of Health & Welfare, and he has passed it on to this office. In a covering letter from the fire Commissioner he states that his Department has recently undertaken inspection of public buildings in the Edmonton area, with a view to the elimination of fire hazards, and the recommendations respecting egress and public safety. Certain fire fighting apparatus is now being supplied to this institute, but of course not as complete as this inspection report requires. Your attention is drawn particularly to the report on existing fire exits and the recommendations. You will also please note that the Inspector recommends a night watchman.

The type of fire escapes in this and many other schools is certainly unsatisfactory, and in this I have always felt there was great room for improvement. Failing the ability to supply good fire exits, the next best thing is to supply (temporary of course) a competent night watchmen. In this and other large residential schools a night watchman should be supplied, if at all possible.

The report is submitted for your consideration and comments.


G. H. Gooderham,
Inspector of Indian Agencies,
Alberta Inspectorate.



GHG:RM
enc.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

110-0-5

E.J. Staley

REV. ~~XXXXXXXXXXXX~~
PRINCIPAL

OFFICE PHONE 972-1123
RES. PHONE 972-1124

Indian Residential School

UNITED CHURCH OF CANADA
EDMONTON
ALBERTA

January 14th 1947.

The Secretary,
Indian Affairs Branch,
Department of Mines & Resources,
Ottawa, Canada.



Dear Sir:

In talking with the engineer at the school, I learned that the electric motor at the pumphouse had not been checked for about twelve years and ~~xxx~~ as it has seen a lot of service during that period, he thought that a checkup and a possible rewinding might be warranted.

He also informed me that two or three years ago, when he was changing some valves in the cylinder in the well, he noted considerable wear in the cylinder and it might be possible that replacement of the cylinder would be called for this year, when the cylinder, valves & rods were being checked.

Replacement of the cylinder I would imagine, would be an expensive job, as I understand it is 4" in diameter and about six or seven feet long, but of what make I have been unable to learn.

I thought it best to advise you of these conditions in order that you may be prepared to meet the expense, should it become necessary to incur same.

In connection with the cylinder, I understand that the one in the well has been in use for over eighteen years.

Yours truly,

E. J. Staley
E.J. Staley
Principal.

F.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

Mr. G.H. Gooderham, - Page 2.

22 January 1947.

We cannot see any reason for keeping the doors locked in the two staff bedrooms when the dormitories are occupied. You should inform the principal immediately that the Department expects these doors to be kept unlocked so that if necessary the children can use these exits.

Some years ago we decided to allow an amount for night watchmen to certain Indian residential schools where it was felt a definite fire hazard existed. We never previously considered the Edmonton school in the class just mentioned. However, in view of your recommendation, we are prepared to allow an amount of \$40.00 a month until April 30, 1947 towards the salary of a night watchman at the Edmonton school. It should definitely be understood that this is only a temporary measure.

mp

Bernard F. Neary,
Supt. of Welfare & Training.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

110-0-5 (W.T. 1)

Ottawa, 22 January 1947.

Mr. G.H. Gooderham, Inspector of Indian Agencies,
CALGARY, Alberta.

We are in receipt of your letter of the 7th instant enclosing report submitted by the Provincial Fire Commissioner regarding the Edmonton Residential School.

At the request of the principal, we have arranged within the last month, to have our Purchasing Branch secure 24-1 qt. fire extinguishers, 500 feet of hose, and 12 refills for foamite fire extinguishers at present in the school. The commissioner's report reads as follows regarding the fire exit facilities:-

"A very unusual situation exists in connection with these facilities and should be remedied immediately. Fire exit other than main inside stairway - South centre of building is by the way of double sash windows, located in each of the childrens dormitories. In order to reach the sill of each window it is necessary for the children to step up some four feet from the ground level and some of the children being so small it would therefore necessitate older children rendering assistance. Such exit facilities are inadequate for an occupancy of this type and would recommend that windows be removed, standard doors installed and to be equipped with approved type of panic bolts. There are two other exits, but these are located in the two staff bedrooms, doors are kept locked and the children deprived of their access."

We are not certain if the commissioner's suggestion can be carried out without effecting the building. However, you may make inquiries and let us know. In the meantime it would be advisable to have permanent steps made leading to the windows which are used as an exit to the fire escape.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

...T. 1)

Ottawa, 22 January 1947.

Mr. E.A. Robertson, Clerk in Charge,
WINTERBURN, Alta.

Enclosed for your information
is a copy of a letter received from the
principal of the Edmonton Residential School.

Please let us have your views
regarding the matter mentioned by the principal.

Bernard F. Neary,
Supt. of Welfare & Training.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

E.J. Staley
REV. ~~XXXXXXXXXX~~
PRINCIPAL

OFFICE PHONE
RES. PHONE

Indian Residential School

UNITED CHURCH OF CANADA
EDMONTON
ALBERTA

January 6th 1947

Mr. E.A. Robertson,
Acting Indian Agent,
Winterburn, Alberta.

Dear Mr. Robertson:

I am enclosing herewith the following bills from the Hayward Lumber Coy Ltd. Edmonton, for material supplied to the school:-

| | |
|--|-------|
| Material for benches and for outside doors for rear entrances. | 33.36 |
| Material to repair & replace hoppers | 61.15 |
| Material for making of benches for Manual training and tables for work in room in connection with handicrafts training. | 76.21 |
| Material to work with in Manual Training room. | 41.50 |

The purchase of the material for benches, tables and material to work with was authorised by Mr. Ducet & subsequently confirmed by the Department.

The material for the piggery was needed for repairs to prevent part of the building falling down and the material for the doors was got to rebuild the outside doors at the rear entrances to the school, which were in such poor condition that they would not keep out the snow and it was impossible to begin to keep the building warm.

The replacement of these doors had been under consideration by the Department for over a year, along with some other things, but somehow had not been got around to.

I trust the above explanations will allow you to pass the accounts through in the regular way.

Yours very truly.

E.J. Staley
Principal.

Per.....

F.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

110-0-5 (WT1).

Ottawa, January 29, 1947.

Memorandum:

DEPARTMENTAL PURCHASING AGENT.

The attached account covers the cost of lumber purchased for repair work at the Edmonton Residential School. The material was available locally and authorization was given for the purchase. Please issue Purchase Order so that the account may be paid.

The coding is as follows:

753-76-10-691.


Bernard F. Neary,
Supt. of Welfare & Training.

Encl:

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA



A B C. CODE 5th EDITION

CHARLES NIEDNER'S SONS
MANUFACTURERS
UNDERWRITERS' LINEN FIRE HOSE
FOR INDOOR FIRE PROTECTION

COATICOOK, QUE. January 28th/47

ALL PRICES SUBJECT TO PRESENT IMPORTATION VALUES AND TO CANCELLATION OR REVISION UPON CHANGED CONDITIONS ATTRIBUTABLE TO WAR.
ALL CONTRACTS AND DELIVERIES ARE SUBJECT TO WAR, FIRES, STRIKES, BREAKAGES OF MACHINERY AND OTHER UNFORESEEN CIRCUMSTANCES.

Department of Mines & Resources,
Ottawa, Ont.

Att: Mr. U.M. Vincent,
Departmental Purchasing Agent-

Gentlemen:

Referring to your letter of 20th instant.
As requested, we are enclosing herewith Invoices in quadruplicate in connection with 500 ft 1½" Rendein - 8-50 ft lengths and 1-100 ft. length coupled shipped to Rev. E.J. Staley, Principal, Indian Residential School, Edmonton, Alta., - your file 69438-15-13.

On receipt of Invoices we note you are to forward us confirming order.

Yours very truly,

CHAS. NIEDNER'S SONS

Per. *(Signature)*

A/B

ENCLOSURES-

Invoices in quadruplicate - B/L duly received.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

OFFICE OF THE
INTELLIGENCE



CANADA

DEPARTMENT
OF

MINES AND RESOURCES
INDIAN AFFAIRS BRANCH

Edmonton Agency

110-0-5
Winterburn, Alta,
Dec. 31st, 1946.

PLEASE QUOTE
FILE



Your 110-0-5 (W.R.L)

Indian Affairs Branch, Dept. of Mines & Resources, Ottawa.

Referring to your letter of Dec. 19th, 1946,
in regard to desks required by Edmonton Indian Residential
School.

Mr. Staley advises that they would like to get
twenty No. 1, Model "W" Chair Desks and twenty No. 3, Model
"W" Chair Desks, as put out by the Moyer School Supply Co.

E. A. Robertson

E. A. Robertson,
Clerk in charge.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

DEPARTMENT OF MINES AND RESOURCES

10-0

9 January 19 47

This space for use of Head Office only

Requisition No.

Order No.

To the Departmental Purchasing Agent, Ottawa,

PLEASE FURNISH THE FOLLOWING SUPPLIES FOR USE OF.....

VOTE.....

ALLOTMENT.....

ALLOCATION SYMBOLS.....

SHIP TO Rev. E.J. Staley, Principal, Indian Residential School,
EDMONTON, Alta.

Purpose for which required.....

| QUANTITY | | UNIT PRICE | TOTAL |
|---|----------------------------|------------|-------|
| 20 | Single Chair Desks - Large | | |
| 20 | " " " - Small | | |
| <p>Note: While the desks should be shipped to the address shown above the account should be forwarded to:-</p> <p>E.A. Robertson, Clerk in Charge, WINTERBURN, Alta.</p> | | | |

I hereby certify that I have personal knowledge that all the above articles are required in the Department and for Departmental purposes only. The expenditure required by this requisition is strictly unavoidable and the public interest will suffer if it is not made.

SIGNED—

APPROVED—

for Director

- NOTE:— 1. In ordering stationery and printed matter use separate sheets.
2. Order numbered forms by number or send sample.
3. Orders for unnumbered forms should be accompanied by samples.
4. Orders for books should be accompanied by sample pages or folios.
5. Orders for which purchase orders will issue should give as full details as possible for each item.
6. All Requisitions should be submitted in duplicate. One copy will be returned as acknowledgment.

Indian Affairs. School Files.
(RC 1C, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

E.J. Staley
REV. ~~XXXXXXXXXXXX~~
PRINCIPAL

110-0-5

OFFICE PHONE 972-1123
RES. PHONE 972-1124

Indian Residential School

UNITED CHURCH OF CANADA
EDMONTON
ALBERTA

January 8th, 1947.

The Secretary,
Indian Affairs Branch,
Department of Mines & Resources,
Ottawa, Canada.

Dear Sir:


Will you please arrange for the supplying of the following:-
12 Refills for Foamite Firefoam Fire Extinguishers.
We have none on hand at the school.

Yours very truly.

E.J. Staley
Principal.

Per.....

F.



Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

110-0-5

VILAS FURNITURE COMPANY LIMITED

MANUFACTURERS OF
SCHOOL & HOUSEHOLD FURNITURE
GREY IRON CASTINGS, ETC.

COWANSVILLE, QUE.

Sold to **Department of Mines and Resources,**
OTTAWA, Ont.

Ship to **Rev. E.J. Staley, Principal,**
Shipping Point **Indian Residential School**
EDMONTON, Alta.

Post Office

Ship by

Our Order No. **1047**

Customers Order No. **16036**


Date Sold **Jan. 29/47**

Salesman **Letter**

Terms **30 days net**

F.O.B. **Edmonton**

When Ship

| QUANTITY | ✓ | | PRICE | AMOUNT |
|---|---|---------------------------------------|-------|--------|
| 20 | | <i>W-1</i> # 1 Model W Chair Desks | | |
| 20 | | # 5 " W " " | | |
| Fed. sales tax included | | | | |
|  | | | | |
| 4 copies invoice to E.A. Robertson, Clerk in Charge Winterburn, Alta. | | | | |
| <p>NOTICE</p> <p>This acknowledges your order entered by us and for which we thank you.</p> <p>If there is any error or omission please notify us at once.</p> | | | | |
| FORM No. 13-30M-10-45 | | | | |

Indian Affairs, School Files.
 (RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

110-0-5
ADDRESS REPLY TO
ENGINEERING AND CONSTRUCTION
SERVICE

ES DEPARTMENT
OF
MINES AND RESOURCES
SURVEYS AND ENGINEERING BRANCH



CANADA

QUOTE FILE I.A.1656-12

OTTAWA, January 31, 1947.

Memorandum:

Re: Edmonton Indian Residential School,
Edmonton, Alberta.

We are forwarding, under separate cover, one blueprint copy of all drawings on our file in connection with the above, which include building plans and the drainage and lighting systems as requested in your memorandum of December 20th, 1946, to our Director.

Any further information required in connection with the electrical or drainage systems would have to be obtained by making an inspection of the installation.



T. S. Mills
T. S. Mills,
Chief Engineer.

R.A. Hoey, Esq.,
Director,
Indian Affairs Branch,
Department of Mines and Resources,
Booth Building,
Sparks Street,
OTTAWA.

u.s.c.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

110-0-5 (W.T.1)


Ottawa, February 4th, 1947.

Dear Mr. Staley:-

With reference to the request which you made some weeks ago, we are forwarding under separate cover one blue print copy of all drawings on our file in connection with the Edmonton Residential School. This includes the building plans and the drainage and lighting systems.

Any further information required in connection with the electrical or drainage systems would have to be obtained by making an inspection of the installation.

Yours very truly,


Bernard V. Neary,
Supt. of Welfare & Training.

Rev. E.J. Staley,
Principal,
Indian Residential School,
EDMONTON, Alta.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

207 - 210 Kresge Bldg.,
EDMONTON, Alta., October 21 1946

M Indian Agencies
WINTERBURN, Alberta.

No 349

PHONES:
OFFICE - - - 29 477
AFTER HOURS AND
EMERGENCY - 31 237

HADDOW & MAUGHAN

L I M I T E D

HEATING BY HOT WATER, HOT AIR AND STEAM • PLUMBING • GAS FITTING

JOB #514

To install three toilets:

| | | | |
|----|------|---|--------|
| 1 | | 4" Kaefer Joint | 3.75 |
| 10 | lbs. | Lead Wool | 3.00 |
| 2 | lbs. | Oakum | .60 |
| 3 | | Toilet combinations, Briggs, less seats | 103.50 |
| 3 | | T Bolts & washers | 1.20 |
| 6 | | 3/8" Tailpieces | .60 |
| 3 | | Putty | 1.00 |
| 10 | lbs. | 1/2" x 6" Galv. Nipples | .30 |
| 2 | | 3" x 1/4" Bend | .72 |
| 1 | | 3" S.H. Soil Pipe | .77 |
| 1 | ft. | Lead | .96 |
| 8 | lbs. | Oakum | .30 |
| 1 | lb. | 4" Floor Flanges | 2.28 |
| 3 | | Labor | 70.35 |

TOTAL\$189.33

CORRECTED STATEMENT

Indian Affairs, School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA

OFFICE OF THE
INDIAN AGENT

Edmonton Agency



CANADA
DEPARTMENT
OF
MINES AND RESOURCES
INDIAN AFFAIRS BRANCH

110-0-5
Winterburn, Alta,
Jan. 27th, 1947.

PLEASE QUOTE
FILE _____

Your file 110-0-5 (W.T.1)

Indian Affairs Branch, Dept. of Mines & Resources, Ottawa.

Referring to your letter of Jan. 20th, 1947,
in regard to Voucher No. 342-46, \$70.35, in favor of
Haddow & Naughan, for repair work at Edmonton School.

I am now attaching amended account from
Haddow & Naughan on which they have shown workmen
employed and rate per hour.



E. A. Robertson
E. A. Robertson,
Indian Agent.

Indian Affairs. School Files.
(RG 10, Volume 6351, File 753-5, part 6)

PUBLIC ARCHIVES
ARCHIVES PUBLIQUES
CANADA